SCHEDULE 2

REQUIREMENTS

## Crushing and screening of aggregate

**21.** If crushing and screening of aggregate is undertaken on the application land all crushing and screening plant must be fitted with effective dust suppression measures including dust suppression on all conveyor outfall points.