

SCHEDULE

Part II

Method 7

Defatted continuous atmospheric

Pressing

4. The material discharged from the pre-heater must be passed through a screw press so adjusted that all water and tallow are removed from the protein residue.