

SCHEDULE 1

Rendering requirements

Part I

Requirements to be met where specified risk material is rendered

5. The equipment used to render specified risk material shall include—
 - (a) measuring equipment to check temperature and, if necessary, pressure at critical points;
 - (b) recording devices to record continuously the results of measurements; and
 - (c) an adequate safety system to prevent insufficient heating.