

## SCHEDULE 1

### Rendering requirements

## Part II

### Methods of rendering

#### *Method 4*

#### *Natural fat batch (Batch Pressure)*

### **Equipment**

1. The premises shall be equipped with apparatus to crush specified risk material to the appropriate particle size, at least one cooker to cook the specified risk material, sufficient capacity of hot water and steam production to render specified risk material in accordance with this method, and equipment to separate protein from tallow and store those products.