

SCHEDULE 6

RENDERING REQUIREMENTS

Part II

METHODS OF RENDERING

METHOD 1

NATURAL FAT BATCH

Time and temperature

3. The rendering shall be carried out in a batch system.