

SCHEDULE 6

Rendering requirements

PART II

Methods of Rendering

METHOD 4

CONTINUOUS OR BATCH PRESSURE

Time and temperature

2. After reduction the specified risk material shall be heated to a core temperature of more than 133°C for at least 20 minutes without interruption at a pressure of at least 3 bar.