

SCHEDULE 6

Rendering requirements

PART II

Methods of Rendering

METHOD 7

DEFATTED CONTINUOUS ATMOSPHERIC

Pressing

4. The material discharged from the pre-heater must be passed through a screw press so adjusted that all water and tallow are removed from the protein residue.