

SCHEDULE 2

TESTING OF CERAMIC ARTICLES

PART I

BASIC RULES FOR DETERMINING THE MIGRATION OF LEAD AND CADMIUM

Test liquid (“simulant”)

1. 4% (v/v) acetic acid, in a freshly prepared aqueous solution.