

## FIRST SCHEDULE

### THE COAL AND OTHER MINES (LOCOMOTIVES) REGULATIONS, 1956, HAVING EFFECT AS IF MADE UNDER SECTION ONE HUNDRED AND FORTY-ONE OF THE MINES AND QUARRIES ACT, 1954

## PART VII

### Additional provisions—storage battery locomotives

#### *Charging and changing of batteries*

**32.**—(1) No person shall charge or change any battery of a storage battery locomotive in any mine except at a place appointed for that purpose by the manager.

(2) The manager shall ensure that every place so appointed for charging batteries (in these regulations referred to as a “charging station”) is so arranged in relation to the ventilation that—

- (a) the charging apparatus is on the intake side of the battery racks; and
- (b) the air passes from the battery racks directly into an airway and does not subsequently ventilate a working face.

(3) The manager shall ensure that every charging station—

- (a) is constructed of non-inflammable material;
- (b) is provided with suitable and sufficient apparatus for combating outbreaks of fire;
- (c) is so equipped that the spilling of water or electrolyte is minimised.

(4) Any person spilling any water or electrolyte on any battery in a charging station shall forthwith wipe it up or cause it to be wiped up.

(5) In a mine or part of a mine which is not a safety-lamp mine or a safety-lamp part of a mine, no person shall, in, or within thirty feet of, any charging station, smoke or use any lamp or light other than a locked safety-lamp or an electric lamp adequately protected.