SCHEDULE 2

PART VI DEAD-WEIGHT MACHINES

Vibrating weighing instruments			Accelerating weighing instruments				
				weign	ung instru	ments	Weight required to bring back
Capacity of machine	Weight to be added to test sensitiveness when fully loaded		Error in excess or in deficiency when fully loaded		Error in excess or in deficiency when fully loaded		the beam from position of greatest displacement when fully loaded
Upon passing as fit for the for trade	In relation to the obliteration of stamps	Upon passing as fit n for o use for trade	In relation to the bliteratio of stamps	Upon passing as fit n for o use for trade	In relation to the bbliteratio of stamps	Upon passing as fit n for use for trade	
1 hundredweight	ounce	1½ ounces	1 ounce	2 ounces	1 ounce	2 ounces	2 ounces
3 hundredweight	1 ounce	3 ounces	2 ounces	4 ounces	2 ounces	4 ounces	4 ounces
5 hundredweight	1½ ounces	4½ ounces	3 ounces	6 ounces	3 ounces	6 ounces	6 ounces
7 hundredweight	2 ounces	6 ounces	4 ounces	8 ounces	4 ounces	8 ounces	8 ounces
10 hundredweight	ounces	9 ounces	6 ounces	12 ounces	6 ounces	12 ounces	12 ounces
20 hundredweight	5 ounces	15 ounces	10 ounces	20 ounces	10 ounces	20 ounces	20 ounces
30 hundredweight	$6\frac{1}{2}$ ounces	19½ ounces	13 ounces	26 ounces	13 ounces	26 ounces	26 ounces
40 hundredweight	8 ounces	24 ounces	16 ounces	32 ounces	16 ounces	32 ounces	32 ounces
50 hundredweight	10 ounces	30 ounces	20 ounces	40 ounces	20 ounces	40 ounces	40 ounces