

---

STATUTORY INSTRUMENTS

---

**1989 No. 635**

**The Electricity at Work Regulations 1989**

**PART II**

**GENERAL**

**Means for cutting off the supply and for isolation**

**12.**—(1) Subject to paragraph (3), where necessary to prevent danger, suitable means (including, where appropriate, methods of identifying circuits) shall be available for—

- (a) cutting off the supply of electrical energy to any electrical equipment; and
- (b) the isolation of any electrical equipment.

(2) In paragraph (1), “isolation” means the disconnection and separation of the electrical equipment from every source of electrical energy in such a way that this disconnection and separation is secure.

(3) Paragraph (1) shall not apply to electrical equipment which is itself a source of electrical energy but, in such a case as is necessary, precautions shall be taken to prevent, so far as is reasonably practicable, danger.