



Mines Act (Northern Ireland) 1969

1969 CHAPTER 6

PART III

SAFETY, HEALTH AND WELFARE

SUPPORT

48 Duty to secure safety of roads and working places.

- (1) It shall be the duty of the manager of every mine to take, with respect to every road and working place in the mine, such steps by way of controlling movement of the strata in the mine and supporting the roof and sides of the road or working place as may be necessary for keeping the road or working place secure; but nothing in this subsection shall require the taking of such steps as aforesaid with respect to a road or part of a road which is, or is comprised in, a part of the mine every entrance to which is for the time being provided, in pursuance of^[F1] regulation 8 of the Mines (Safety of Exit) Regulations (Northern Ireland) 1998], with such an enclosure or barrier as is therein mentioned.
- (2) It shall be the duty of the manager of every mine to take such steps as may be necessary for securing that he is at all material times in possession of all information relevant for determining the nature and extent of any steps which it is requisite for him to take in order to discharge efficiently the duty imposed on him by subsection (1).

F1 SR 1998/375

Status:

Point in time view as at 01/01/2006. This version of this provision has been superseded.

Changes to legislation:

There are currently no known outstanding effects for the Mines Act (Northern Ireland) 1969, Section 48.