



# Mines Act (Northern Ireland) 1969

## 1969 CHAPTER 6

### PART III

#### SAFETY, HEALTH AND WELFARE

##### VENTILATION

#### 55 Duty to provide adequate ventilation.

- (1) It shall be the duty of the manager of every mine to take such steps as are necessary for securing that there is constantly produced in all parts of the mine below ground ventilation adequate for the following purposes, namely,—
  - (a) diluting gases that are inflammable or noxious so as to render them harmless and removing them; and
  - (b) providing air containing a sufficiency of oxygen.
- (2) Without prejudice to the general application of subsection (1),—
  - (a) ventilation produced in a part of a mine shall be deemed for the purposes of that subsection not to be adequate for the purpose of diluting carbon dioxide so as to render it harmless unless the amount thereof in the general body of the air in that part of the mine is not more than one and a quarter per cent. by volume or, if a smaller percentage by volume is prescribed, that smaller percentage;
  - (b) ventilation produced in a part of a mine shall be deemed for the purposes of that subsection not to be adequate for the purpose of providing air containing a sufficiency of oxygen unless the amount of oxygen in the general body of the air in that part of the mine is not less than nineteen per cent. by volume;

...

<sup>F1</sup>(3) In the discharge of the duty imposed on him by subsection (1), the manager of a mine shall have regard to the desirability of securing (consistently with the discharge of that duty) the maintenance in the mine of working conditions that are reasonable so far

---

*Status: Point in time view as at 01/01/2006. This version of this provision has been superseded.*

*Changes to legislation: There are currently no known outstanding effects for the Mines Act (Northern Ireland) 1969, Section 55. (See end of Document for details)*

---

as regards the temperature and humidity of the atmosphere and the amount of dust therein.

- (4) Nothing in subsection (1) shall be construed as requiring the production of ventilation—
- (a) in a part of a mine which is stopped off in a prescribed manner or in such other manner as may be approved by<sup>F1</sup> the Executive] by notice served on the manager of the mine or is stowed up;
  - (b) in any waste; or
  - (c) in any such other part of a mine as may be prescribed.
- (5) Where, in any part of a mine required by the foregoing provisions of this section to be ventilated, the ventilation is interrupted or ceases to be adequate for the purposes mentioned in subsection (1), it shall be the duty of the manager of the mine to secure that, until the ventilation is restored, access to that part of the mine is so restricted as to prevent from entering it any person not authorised to do so and no person is permitted to remain in or pass through it except for the purpose of restoring the ventilation or in a case of emergency.

**F1** SR 1980/333

**F2** SR 1999/150

**Status:**

Point in time view as at 01/01/2006. This version of this provision has been superseded.

**Changes to legislation:**

There are currently no known outstanding effects for the Mines Act (Northern Ireland) 1969, Section 55.