



Mines Act (Northern Ireland) 1969

1969 CHAPTER 6

PART III

SAFETY, HEALTH AND WELFARE

BUILDINGS, STRUCTURES, MEANS OF ACCESS, &C.

86 Buildings and structures to be kept safe.

All buildings and structures on the surface of a mine shall be kept in safe condition.

87 Safe means of access and safe means of employment.

- (1) There shall be provided and maintained safe means of access to every place in or on a building or structure on the surface of a mine, being a place at which any person has at any time to work.
- (2) Where a person is to work at any such place as aforesaid from which he will be liable to fall a distance of more than^[F1] 2 metres], then, unless the place is one which affords secure foothold and, where necessary, secure hand-hold, means shall be provided by fencing or otherwise for ensuring his safety.

Status:

Point in time view as at 01/01/2006.

Changes to legislation:

There are currently no known outstanding effects for the Mines Act (Northern Ireland) 1969.