This document is meant purely as a documentation tool and the institutions do not assume any liability for its contents

COMMISSION REGULATION (EC) No 474/2006

of 22 March 2006

establishing the Community list of air carriers which are subject to an operating ban within the Community referred to in Chapter II of Regulation (EC) No 2111/2005 of the European Parliament and of the Council

(Text with EEA relevance)

(OJ L 84, 23.3.2006, p. 14)

Amended by:

<u>B</u>

Official Journal

		No	page	date
<u>M1</u>	Commission Regulation (EC) No 910/2006 of 20 June 2006	L 168	16	21.6.2006
► <u>M2</u>	Commission Regulation (EC) No 1543/2006 of 12 October 2006	L 283	27	14.10.2006
► <u>M3</u>	Commission Regulation (EC) No 235/2007 of 5 March 2007	L 66	3	6.3.2007
► <u>M4</u>	Commission Regulation (EC) No 787/2007 of 4 July 2007	L 175	10	5.7.2007
► <u>M5</u>	Commission Regulation (EC) No 1043/2007 of 11 September 2007	L 239	50	12.9.2007
<u>M6</u>	Commission Regulation (EC) No 1400/2007 of 28 November 2007	L 311	12	29.11.2007
► <u>M7</u>	Commission Regulation (EC) No 331/2008 of 11 April 2008	L 102	3	12.4.2008
<u>M8</u>	Commission Regulation (EC) No 715/2008 of 24 July 2008	L 197	36	25.7.2008
► <u>M9</u>	Commission Regulation (EC) No 1131/2008 of 14 November 2008	L 306	47	15.11.2008
► <u>M10</u>	Commission Regulation (EC) No 298/2009 of 8 April 2009	L 95	16	9.4.2009
► <u>M11</u>	Commission Regulation (EC) No 619/2009 of 13 July 2009	L 182	4	15.7.2009
► <u>M12</u>	Commission Regulation (EC) No 1144/2009 of 26 November 2009	L 312	16	27.11.2009
► <u>M13</u>	Commission Regulation (EU) No 273/2010 of 30 March 2010	L 84	25	31.3.2010
► <u>M14</u>	Commission Regulation (EU) No 590/2010 of 5 July 2010	L 170	9	6.7.2010
► <u>M15</u>	Commission Regulation (EU) No 791/2010 of 6 September 2010	L 237	10	8.9.2010
►M16	Commission Regulation (EU) No 1071/2010 of 22 November 2010	L 306	44	23.11.2010

COMMISSION REGULATION (EC) No 474/2006

of 22 March 2006

establishing the Community list of air carriers which are subject to an operating ban within the Community referred to in Chapter II of Regulation (EC) No 2111/2005 of the European Parliament and of the Council

(Text with EEA relevance)

THE COMMISSION OF THE EUROPEAN COMMUNITIES,

Having regard to the Treaty establishing the European Community,

Having regard to Regulation (EC) No 2111/2005 of the European Parliament and the Council of 14 December 2005 on the establishment of a Community list of air carriers subject to an operating ban within the Community and on informing air transport passengers of the identity of the operating air carrier, and repealing Article 9 of Directive 2004/36/CE (1), and in particular Article 3 thereof,

Whereas:

- (1) Chapter II of Regulation (EC) No 2111/2005 (hereinafter referred to as 'the basic Regulation') lays down procedures for establishing the Community list of air carriers which are subject to an operating ban within the Community as well as procedures allowing the Member States, in certain circumstances, to adopt exceptional measures imposing operating bans within their territory.
- (2) In accordance with Article 3(3) of the basic Regulation, each Member State communicated to the Commission the identity of the air carriers that are subject to an operating ban in its territory, together with the reasons which led to the adoption of such bans and any other relevant information.
- (3) The Commission informed all air carriers concerned either directly or, when this was not practicable, through the authorities responsible for their regulatory oversight, indicating the essential facts and considerations which would form the basis for a decision to impose them an operating ban within the Community.
- (4) In accordance with Article 7 of the basic Regulation, opportunity was given by the Commission to the air carriers concerned to consult the documents provided by Member States, to submit written comments and to make an oral presentation to the Commission within 10 working days and to the Air Safety Committee (2).
- (5) The common criteria for consideration of an operating ban for safety reasons at Community level are set out in the Annex to the basic Regulation.

⁽¹⁾ OJ L 344, 27.12.2005, p. 15.

⁽²⁾ Established by Article 12 of Council Regulation (EEC) No 3922/91 of 16 December 1991 on the harmonization of technical requirements and administrative procedures in the field of civil aviation (OJ L 373, 31.12.1991, p. 4).

Air Bangladesh

- (6) There is verified evidence of serious safety deficiencies on the part of Air Bangladesh with regard to a certain aircraft of its fleet. These deficiencies have been identified during ramp inspections performed by Germany under the SAFA programme (1).
- (7) Air Bangladesh did not respond adequately and timely to an enquiry by the civil aviation authority of Germany regarding the safety aspect of its operation showing a lack of transparency or communication, as demonstrated by its lack of reply to correspondence from this Member State. To date Germany had no opportunity to verify whether the safety deficiencies have been corrected.
- (8) The authorities of Bangladesh with responsibility for regulatory oversight of Air Bangladesh have not exercised an adequate oversight on one specific aircraft used by this carrier in accordance with their obligations under the Chicago Convention.
- (9) Therefore, on the basis of the common criteria, it is assessed that Air Bangladesh should be submitted to a strict operational restriction and included in Annex B.

Air Koryo

- (10) There is verified evidence of serious safety deficiencies on the part of Air Koryo. These deficiencies have been identified by France and Germany, during ramp inspections performed under the SAFA programme (2).
- (11) Persistent failure by Air Koryo to address deficiencies previously communicated by France was identified during other ramp inspections performed under the SAFA programme (3).
- (12) Substantiated and serious incident-related information communicated by France indicates latent systemic safety deficiencies on the part of Air Koryo.
- (13) Air Koryo demonstrated a lack of ability to address these safety deficiencies.
- (14) Air Koryo did not respond adequately and timely to an enquiry by the civil aviation authority of France regarding the safety aspect of its operation showing a lack of transparency or communication, as demonstrated by the absence of reply to a request by that Member State.
- (15) The corrective action plan presented by Air Koryo in response to France's request was not adequate and sufficient to correct the identified serious safety deficiencies.

⁽¹⁾ LBA-D-2005-0003

LBA-D-2005-0004

LBA-D-2005-0004

⁽²⁾ DGAC/F 2000-210

No ref. for another SAFA inspection performed by Germany.

⁽³⁾ DGAC/F-2000-895

▼B

- (16) The authorities of the Democratic People Republic of Korea with responsibility for regulatory oversight of Air Koryo have not exercised an adequate oversight on this carrier in accordance with their obligations under the Chicago Convention.
- (17) Therefore, on the basis of the common criteria, it is assessed that Air Koryo does not meet the relevant safety standards.

Ariana Afghan Airlines

- (18) There is verified evidence of serious safety deficiencies on the part of certain aircraft operated by Ariana Afghan Airlines. These deficiencies have been identified by Germany, during ramp inspections performed under the SAFA programme (1).
- (19) Ariana Afghan Airlines demonstrated a lack of ability to address these safety deficiencies.
- (20) Ariana Afghan Airlines did not respond adequately and timely to an enquiry by the civil aviation authority of Germany regarding the safety aspect of its operation showing a lack of communication, as demonstrated by the absence of adequate response to correspondence from this Member State.
- (21) The competent authorities of Afghanistan, where the aircraft used by Ariana Afghan Airlines is registered, have not exercised a fully adequate oversight of the aircraft used by this carrier in accordance with their obligations under the Chicago Convention.
- (22) Therefore, on the basis of the common criteria, it is assessed that Ariana Afghan does not meet the relevant safety standards for all the aircraft it operates, with the exception of A310 registration number F-GYYY which is registered in France and subject to the oversight of the French authorities.

BGB Air

- (23) There is verified evidence of serious safety deficiencies on the part of BGB Air. These deficiencies have been identified by Italy, during ramp inspections performed under the SAFA programme (2).
- (24) BGB Air demonstrated a lack of ability or willingness to address safety deficiencies as demonstrated by the submission of a self-assessment with ICAO Standards on the basis of the Foreign Operator Check List provided by Italy, which was found not to be in conformity with the subsequent findings of SAFA inspections.
- (25) BGB Air did not respond adequately to an enquiry by the civil aviation authority of Italy, regarding the safety aspect of its operation showing a lack of transparency or communication, as demonstrated by the absence of reply to some correspondence sent by this Member State.

⁽¹⁾ LBA-D-2004-269

LBA-D-2004-341

LBA-D-2004-374

LBA-D-2004-597

⁽²⁾ ENAC-IT-2005-237

- (26) There is no evidence of the implementation of an adequate corrective action plan presented by BGB Air to correct the serious safety deficiencies in response to the request from Italy.
- (27) The authorities of Kazakhstan with responsibility for regulatory oversight of BGB Air did not fully cooperate with the civil aviation authority of Italy when concerns about the safety of the operation of BGB Air certified in that state were raised, as demonstrated by the absence of reply to the correspondence sent by this Member State.
- (28) Therefore, on the basis of the common criteria, it is assessed that BGB Air does not meet the relevant safety standards.

Buraq Air

- (29) There is verified evidence of serious safety deficiencies on the part of Buraq Air concerning its cargo operations. These deficiencies have been identified by Sweden and the Netherlands, during ramp inspections performed under the SAFA programme (1).
- (30) Buraq Air did not respond adequately and timely to an enquiry by the civil aviation authority of Germany regarding the safety aspect of its Cargo operations showing a lack of transparency or communication, as demonstrated by a lack of response to correspondence from this Member State.
- (31) The authorities of Libya with responsibility for regulatory oversight of Buraq Air have not exercised an adequate oversight on the Cargo operations of this carrier in accordance with their obligations under the Chicago Convention.
- (32) Therefore, on the basis of the common criteria, it is assessed that Buraq Air should be subject to strict operational restrictions and included in Annex B.

Air Service Comores

- (33) There is verified evidence of serious safety deficiencies on the part of Air Service Comores. These deficiencies have been identified by a Member State, France, during a ramp inspection performed under the SAFA programme (2).
- (34) There is no evidence of the implementation of an adequate corrective action plan presented by Air Service Comores to correct the identified serious safety deficiencies in response to the request from France.
- (35) The authorities with responsibility for regulatory oversight of Air Service Comores have shown a lack of ability to address safety deficiencies.
- (36) The authorities with responsibility for regulatory oversight of Comores did not cooperate in due time with the civil aviation authority of France when concerns about the safety of the operation of a carrier licensed or certified in that state were raised.

⁽¹⁾ LFV-S-2004-2004-52

CAA-NL-2005-47

⁽²⁾ DGAC/F-2005-1222

(37) Therefore, on the basis of the common criteria, it is assessed that Air Service Comores does not meet the relevant safety standards.

GST Aero Air Company

- (38) There is verified evidence of serious safety deficiencies on the part of GST Aero Air Company. These deficiencies have been identified by Italy, during ramp inspections performed under the SAFA programme (1).
- (39) GST Aero Air Company demonstrated a lack of ability or willingness to address safety deficiencies.
- (40) GST Aero Air Company did not respond adequately and timely to an enquiry by the civil aviation authority of Italy regarding the safety aspect of its operation showing a lack of transparency or communication as demonstrated by the absence of reply to the correspondence sent by this Member State.
- (41) There is no evidence of the implementation of an adequate corrective action plan presented by GST Aero Air Company to correct the serious safety deficiencies in response to Italy's request.
- (42) The authorities of Kazakhstan with responsibility for regulatory oversight of GST Aero Air Company did not fully cooperate with the civil aviation authority of Italy when concerns about the safety of the operation of a carrier licensed or certified in that state were raised, as demonstrated by the limited reply to the correspondence sent by Italy.
- (43) Therefore, on the basis of the common criteria, it is assessed that GST Aero Air Company does not meet the relevant safety standards.

Phoenix Aviation

- (44) The authorities with responsibility for regulatory oversight of Kirghizstan have shown an insufficient ability to implement and enforce the relevant safety standards with regard to Phoenix Aviation. While Phoenix Aviation's Air Operator's Certificate was issued by Kyrgyzstan, there is evidence showing s that the airline has its principal place of business in the United Arab Emirates (UAE), contrary to the requirements of Annex 6 to the Chicago Convention. The US National Transportation Safety Board's Factual Report (2) into an accident involving Kam Air flight 904, which was operated by Phoenix Aviation, states that Phoenix Aviation has its headquarters in the UAE.
- (45) Therefore, on the basis of the common criteria, it is assessed that Phoenix Aviation does not meet the relevant safety standards.

⁽¹⁾ ENAC-IT-2005-170 ENAC-IT-2005-370

⁽²⁾ Factual Aviation Report, USA-National Transportation Safety Board, 2 March 2005, (NTSB ID: DCA05RA033).

Phuket Airlines

- There is verified evidence of serious safety deficiencies on the part of Phuket Airlines. These deficiencies have been identified by Member States, the United Kingdom and the Netherlands, during ramp inspections performed under the programme (1).
- (47)Phuket Airlines demonstrated a lack of ability to address timely and adequately these safety deficiencies.
- The authorities with responsibility for regulatory oversight of (48)Thailand did not fully cooperate with the civil aviation authority of the Netherlands when concerns about the safety of Phuket Airlines certified in that state were raised as demonstrated by the lack of pertinent responses to the correspondence from this Member State.
- (49)Therefore, on the basis of the common criteria, it is assessed that Phuket Airlines does not meet the relevant safety standards.

Reem Air

- There is verified evidence of serious safety deficiencies on the part of Reem Air. These deficiencies have been initially identified by the Netherlands, during ramp inspections performed under the SAFA programme (2).
- (51) Persistent failure by Reem Air to address deficiencies was confirmed by the Netherlands, during subsequent ramp inspections on one specific aircraft performed under the SAFA programme (3).
- (52)Reem Air demonstrated a lack of ability or willingness to address safety deficiencies.
- Reem Air did not respond adequately and timely to an enquiry by the civil aviation authority of the Netherlands regarding the safety aspect of its operation showing a lack of transparency or communication as demonstrated by the absence of reply to the correspondence sent by this Member State.

⁽¹⁾ CAA-UK-2005-40

CAA-UK-2005-41

CAA-UK-2005-42

CAA-UK-2005-46

CAA-UK-2005-47

CAA-UK-2005-48

CAA-NL-2005-49

CAA-NL-2005-51

CAA-NL-2005-54

CAA-NL-2005-55 CAA-NL-2005-56

⁽²⁾ CAA-NL-2005-119

CAA-NL-2005-122

CAA-NL-2005-128

CAA-NL-2005-171

CAA-NL-2005-176

CAA-NL-2005-177 CAA-NL-2005-191

CAA-NL-2005-195

CAA-NL-2005-196

⁽³⁾ CAA-NL-2005-230 CAA-NL-2005-234

CAA-NL-2005-235

▼B

- (54) There is no evidence of the implementation of an adequate corrective action plan presented by Reem Air to correct the identified serious safety deficiencies in response to the request from the Netherlands.
- (55) The authorities of Kirghizstan with responsibility for regulatory oversight of Reem Air have not exercised an adequate oversight on this carrier in accordance with their obligations under the Chicago Convention, as demonstrated by the persistence of serious safety deficiencies. In addition, information provided to the Commission by Reem Air during the hearing granted to this company evidences that, while Reem Air Operator's Certificate was issued by Kyrgyzstan, this airline has its principal place of business in the United Arab Emirates (UAE), contrary to the requirements of Annex 6 to the Chicago Convention.
- (56) Therefore, on the basis of the common criteria, it is assessed that Reem Air does not meet the relevant safety standards.

Silverback Cargo Freighters

- (57) There is verified evidence of serious safety deficiencies on the part of Silverback Cargo Freighters. These deficiencies have been identified by Belgium during a ramp inspection performed under the SAFA programme (1).
- (58) Silverback Cargo Freighters which equally assures the maintenance (A&B checks) of its own aircraft, did not respond adequately to an enquiry by the civil aviation authority of this Member State regarding the safety aspect of its operation showing a lack of transparency or communication as demonstrated by the lack of pertinent response to requests made by this Member State.
- (59) Therefore, on the basis of the common criteria, it is assessed that Silverback Cargo Freighters does not meet the relevant safety standards.

Air carriers from the Democratic Republic of Congo

- (60) In spite of its efforts, the civil aviation authorities of the Democratic Republic of Congo ('DRC') have persistent difficulties to implement and enforce the relevant safety standards, as demonstrated by the ICAO-USOAP Audit Summary Report of the Directorate of Civil Aviation of the Democratic Republic of Congo (Kinshasa, 11-18 June 2001). In particular, no system for the certification of Air Operators is currently in place.
- (61) The authorities of the DRC with responsibility for regulatory oversight have consequently shown a lack of ability to carry out adequate safety oversight.
- (62) An operating ban is imposed on Central Air Express because of substantiated deficiencies related to international safety standards, and its lack of cooperation with a Member State.

- (63) Belgium (¹) and Hewa Bora Airways (HBA) have provided information showing that, in the case of HBA, the deficiencies observed in the past by the Belgian authorities have been significantly corrected with respect to certain aircraft. Belgium has further informed the Commission that it intends to conduct systematic ramp inspections of HBA. In view of this, it is considered that this air carrier should be allowed to continue its current operations.
- (64) Therefore, on the basis of the common criteria, it is assessed that all air carriers certified in the Democratic Republic of Congo (RDC) should be included in Annex A with the exception of Hewa Bora Airways (HBA) which should be included in Annex B.

Air carriers from Equatorial Guinea

- (65) The authorities with responsibility for regulatory oversight of Equatorial Guinea did not fully cooperate with the civil aviation authority of the United Kingdom (UK) when concerns about the safety of the operation of carriers licensed or certified in that state were raised. The UK wrote to the Director General of Civil Aviation in Equatorial Guinea on 27 March 2002 (2) seeking clarification on the following points:
 - a significant increase in the number of aircraft registered in Equatorial Guinea and suggestions that the Aircraft Registration Bureau (ARB) or a similar organisation might be managing the register,
 - the fact that a number of operators holding an Air Operator Certificate (AOC) issued by Equatorial Guinea did not have their principal place of business in Equatorial Guinea.

The letter also advised the Director General of Civil Aviation that the UK would not be in a position to allow further commercial operations to its territory by Equatorial Guinea airlines until the UK authorities were satisfied that these airlines were receiving satisfactory oversight. Equatorial Guinea did not reply to this letter

(66) The authorities with responsibility for regulatory oversight of Equatorial Guinea have shown an insufficient ability to implement and enforce the relevant safety standards, in particular as demonstrated by audits and related corrective action plans established under ICAO's Universal Safety Oversight Audit Programme. Such a USOAP audit of Equatorial Guinea took place in May 2001 whereby the audit report (3) indicated that the Civil Aviation Authority did not, at the time of the audit, have the ability to provide adequate oversight to its airlines and ensure that they operate in accordance with ICAO standards. These audit findings namely included:

⁽¹⁾ SAFA ramp inspection performed by the Authorities of Belgium on March 11, 2006 in Brussels.

⁽²) Correspondence between the UK Department of Transport and DGCA-Equatorial Guinea on the 'Aircraft Register of Equatorial Guinea' (27 March 2002).

⁽³⁾ ICAO-USOAP Summary Report — Audit of the Directorate of Civil Aviation of the Republic of Equatorial Guinea (Malabo, 14-18 May 2001).

- lack of an organisation capable of undertaking safety oversight activities, in particular a lack of specialised staff in the areas of licensing, aircraft operations or airworthiness,
- inability to identify the number of aircraft on the register or the number of valid certificates of airworthiness issued,
- failure to establish a structured system for the certification and supervision of air operators,
- failure to adopt aeronautical operations regulations,
- failure to perform surveillance on authorised operators,
- failure to implement a system for performing the basic duties of an airworthiness inspection agency.

Furthermore the Directorate General of Civil Aviation of Equatorial Guinea has never up to date submitted to ICAO an action plan to address these audit findings (1) and consequently an audit follow up mission has not taken place.

- (67) The authorities with responsibility for regulatory oversight of Equatorial Guinea have shown an insufficient ability to implement and enforce the relevant safety standards in accordance with their obligations under the Chicago Convention. In fact, some holders of Air Operator Certificate (AOC) issued by Equatorial Guinea do not have their principal place of business in Equatorial Guinea, contrary to the requirements of Annex 6 to the Chicago Convention (2).
- (68) The authorities of Equatorial Guinea with responsibility for regulatory oversight of the following air carriers have shown a lack of ability to carry out adequate safety oversight on these carriers: Air Consul SA, Avirex Guinée Equatoriale, COAGE Compagnie Aeree de Guinée Equatorial, Ecuato Guineana de Aviación, Ecuatorial Cargo, GEASA Guinea Ecuatorial Airlines SA, GETRA Guinea Ecuatorial de Transportes Aéreos, Jetline Inc., King Transavia Cargo, Prompt Air GE SA, UTAGE Unión de Transporte Aéreo de Guinea Ecuatorial.
- (69) Therefore, on the basis of the common criteria, it is assessed that all air carriers certified in Equatorial Guinea should be subject to an operating ban and included in Annex A.

Air carriers from Liberia

(70) There is verified evidence of serious safety deficiencies on the part of International Air Services certified in Liberia. These deficiencies have been identified by France, during ramp inspections performed under the SAFA programme (3).

⁽¹⁾ ICAO Council working paper C-WP/12471.

⁽²⁾ Correspondence between the UK Department of Transport and ECAC on the 'Issue of Aircraft Documentation by Non-Approved Companies' (6 August 2003).

⁽³⁾ DGAC/F-2004 Nos 315, 316

- The authorities with responsibility for regulatory oversight of Liberia did not fully cooperate with the civil aviation authority of the United Kingdom (UK) when informed of serious safety deficiencies identified during a ramp inspection of a Liberianregistered aircraft carried out by the UK civil aviation authority on 5 March 1996 (1). Concerns about the safety of the operation of carriers licensed or certified in Liberia were promptly raised when on 12 March 1996 the Liberian DCA was advised by the UK civil aviation authority that all requests for permits for Liberian registered aircraft to operate commercial services to the UK would be refused until the Liberian authorities could demonstrate the existence of an effective regulatory system to ensure the airworthiness of aircraft on the Liberian register. No response was ever received from the Liberian authorities. Likewise, the Liberian authorities did not fully cooperate with the civil aviation authority of France by declining to reply when the latter Member State raised concerns about the safety of the operation of a carrier licensed or certified in Liberia.
- (72) The authorities with responsibility for regulatory oversight of Liberia have shown an insufficient ability to implement and enforce the relevant safety standards. The Government of Liberia itself admitted in 1996 (²) that it was unable to maintain regulatory control over Liberian registered aircraft because of the civil conflict. While the Comprehensive Peace Agreement was signed in 2003 and the UN and the National Transitional Government of Liberia are slowly putting in place measures to improve security, it is unlikely that the Government's ability to regulate its register has improved since 1996. ICAO has not yet carried out a USOAP audit of Liberia because of the security situation.
- (73) The authorities of Liberia with responsibility for regulatory oversight of the following air carriers have shown a lack of ability to carry out adequate safety oversight on these carriers: International Air Services Inc., Satgur Air Transport Corp., Weasua Air Transport Co. Ltd.
- (74) Therefore, on the basis of the common criteria, it is assessed that all air carriers certified in Liberia should be subject to an operating ban and included in Annex A.

Air carriers from Sierra Leone

(75) There is verified evidence of serious safety deficiencies on the part of Air Universal Ltd. These deficiencies have been identified by Sweden during a ramp inspection performed under the SAFA programme (3).

UK-CAA Regulation Group — Aircraft Survey Report, 5 March 1996 (Office code: 223).

⁽²⁾ Correspondence between the Transport Ministry of Liberia and UK DGCA on the 'inability, due to the Liberian Civil conflict, to maintain regulatory control over Liberian registered aircraft', 28 August 1996.

⁽³⁾ LFV-S-04-0037

- The authorities with responsibility for regulatory oversight of Sierra Leone did not fully cooperate with the civil aviation authority of Sweden when concerns about the safety of the operation of Air Universal Ltd. certified in that state were raised, as demonstrated by the lack of response to the correspondence from this Member State.
- The operating authorisation or technical permission of any carrier under the oversight of Sierra Leone has previously been refused or revoked by the United Kingdom.
- While the Air Operator's Certificate of Air Universal Ltd was issued by Sierra Leone, evidence shows that the airline has currently its principal place of business in Jordan, contrary to the requirements of Annex 6 to the Chicago Convention.
- The authorities of Sierra Leone with responsibility for regulatory oversight of Air Universal Ltd have not exercised an adequate oversight on this carrier in accordance with their obligations under the Chicago Convention.
- Therefore, on the basis of the common criteria, it is assessed that Air Universal Ltd. does not meet the relevant safety standards.
- There is verified evidence of serious safety deficiencies on the (81)part of air carriers certified in Sierra Leone. These deficiencies have been identified by three Member States, the UK, Malta and Sweden, during ramp inspections performed under the SAFA programme (1).
- The authorities with responsibility for regulatory oversight of (82)Sierra Leone did not fully cooperate with the civil aviation authorities of Sweden and of Malta when concerns about the safety of the operation of Air Universal Ltd certified in that state were raised as demonstrated by the lack of response to the correspondence from this Member State.
- The authorities with responsibility for regulatory oversight of Sierra Leone have shown an insufficient ability to implement and enforce the relevant safety standards in accordance with their obligations under the Chicago Convention. Sierra Leone lacks an appropriate system in place to oversee its operators or the aircraft, and does not have the technical capability or resources to undertake such a task. Some holders of Air Operator Certificate (AOC) issued by Sierra Leone did not have their principal place of business in Sierra Leone, contrary to the requirements of Annex 6 to the Chicago Convention.

⁽¹⁾ CAA-UK-2003-103

CAA-UK-2003-111

CAA-UK-2003-136

CAA-UK-2003-198 CAA-MA-2003-4

LFV-S-2004-37

- (84) The corrective action plan presented by Sierra Leone is considered inappropriate (or insufficient) to correct the identified serious safety deficiencies. The Civil Aviation Authority of Sierra Leone has contracted a private company, International Aviation Surveyors (IAS), to conduct certain oversight activities on its behalf. However, the arrangements entered into between the two parties in a Memorandum of Understanding (¹) do not provide an adequate oversight system for aircraft on the Sierra Leone register. In particular:
 - The aircraft/airlines covered by the MoU were not based in Sierra Leone and the IAS personnel were based in neither Sierra Leone nor the country in which the airlines were based.
 - IAS did not appear to have any enforcement powers.
 - IAS assumed responsibility for routine inspections of the airlines concerned but the level of inspection activity was not specified.
 - The MoU gave IAS a contractual relationship with the airlines concerned.
 - The MoU did not appear to adequately address the supervision of flight operations.
- (85) The authorities of Sierra Leone with responsibility for regulatory oversight of the following air carriers have shown a lack of ability to carry out adequate safety oversight on these carriers: Aerolift Co. Ltd, Afrik Air Links, Air Leone Ltd, Air Rum Ltd, Air Salone Ltd, Air Universal Ltd, Destiny Air Services Ltd, First Line Air (SL) Ltd, Heavylift Cargo, Paramount Airlines Ltd, Star Air Ltd, Teebah Airways, West Coast Airways Ltd.
- (86) Therefore, on the basis of the common criteria, it is assessed that all air carriers certified in Sierra Leone should be subject to an operating ban and included in Annex A.

Air carriers from Swaziland

- (87) There is verified evidence of serious safety deficiencies on the part of Jet Africa, an air carrier certified in Swaziland. These deficiencies have been identified by the Netherlands during a ramp inspection performed under the SAFA programme (2).
- (88) Jet Africa did not respond adequately and timely to an enquiry by the civil aviation authority of the Netherlands regarding the safety aspect of its operation showing a lack of transparency or communication as demonstrated by the absence of reply to the correspondence sent by this Member State.
- (89) There is no evidence of a corrective action plan presented by Jet Africa to correct the serious safety deficiencies in response to the Netherlands request.

⁽¹) Memorandum of Understanding between DCA Sierra Leone and 'FAST International Aviation Surveyors on the inspection, surveillance and provision of regulatory services to extra-regional air operators' (IAS/SL DCA MOA 201101).

⁽²⁾ CAA/NL-2004-98

- The authorities with responsibility for regulatory oversight of Swaziland have shown an insufficient ability to implement and enforce the relevant safety standards, in particular as demonstrated by a USOAP audit which took place in March 1999. The audit report (1) concluded that at the time of the audit, Swaziland was not capable of satisfactorily undertaking safety oversight related responsibilities in respect of its airlines and aircraft register. It also noted that it was not possible to determine the actual number of aircraft on the register as it was not properly maintained. Neither was it possible for the audit team to determine the actual number of personnel licences issued by Swaziland that were still valid, as records were not being maintained. A USOAP audit follow up mission has not taken place because Swaziland has not provided ICAO with information on the progress it has made in implementing the action plan to address the audit findings.
- (91) The authorities of Swaziland with responsibility for regulatory oversight of the following air carriers have shown a lack of ability to carry out adequate safety oversight on these carriers: Aero Africa (Pty) Ltd, African International Airways (Pty) Ltd, Airlink Swaziland Ltd, Northeast Airlines (Pty) Ltd, Scan Air Charter Ltd, Swazi Express Airways, Jet Africa.
- (92) Therefore, on the basis of the common criteria, it is assessed that all air carriers certified in Swaziland should be subject to an operating ban and included in Annex A.

General considerations concerning the carriers included in the list

- (93) Since it would not compromise safety, all air carriers mentioned above can be permitted to exercise traffic rights by using wetleased aircraft of an air carrier which is not subject to an operating ban, provided that the relevant safety standards are complied with.
- (94) The Community list has to be updated regularly and as soon as it is required, in order to take into account the evolution of safety in relation to the air carriers concerned and on the basis of further evidence of remedial actions undertaken.

Air carriers not included in the list

(95) In light of the evidence provided by Tuninter and the authorities of Tunisia with responsibility for its regulatory oversight and further confirmation by Italy, it is considered that there is substantiated evidence that the safety deficiencies observed during two on-site inspections by the Italian authorities have been corrected by this carrier.

ICAO-USOAP Summary Report — Audit of the Directorate of Civil Aviation of Swaziland, (Mbabane, 9-12 March 1999).

- (96) On the basis of the information provided by Germany, it is considered that there is no longer substantiated evidence of a lack of ability or willingness of the authorities of Tajikistan with responsibility for regulatory oversight of air carriers certified in this State.
- (97) On the basis of the information provided to Belgium showing that the deficiencies which led to a national ban on I.C.T.T.P.W. and South Airlines have been fully remedied, it is considered that there is no substantiated evidence of persisting serious safety deficiencies on the part of these air carriers.
- (98) On the basis of the information provided by Germany showing that the specific aircraft which led to the imposition of a operational restriction on Atlant Soyuz is no more part of its fleet, it is considered that there is no substantiated evidence of persisting serious safety deficiencies on the part of this air carrier.
- (99) On the basis of the information available at this stage, it is considered that there is no substantiated evidence of non-corrected serious safety deficiencies on the part of Air Mauritanie. Nevertheless, the ability of the authorities of Mauritania with responsibility for regulatory oversight of this air carrier needs to be further assessed. To this end, an evaluation of the authorities of Mauritania with responsibility for regulatory oversight of this air carrier and the undertakings under its responsibility should be conducted within 2 months by the Commission with the assistance of the authorities of any interested Member States.
- (100) The measures provided for in this Regulation are in accordance with the opinion of the Air Safety Committee,

HAS ADOPTED THIS REGULATION:

Article 1

Subject matter

This Regulation establishes the Community list of air carriers which are subject to an operating ban within the Community referred to in Chapter II of the basic Regulation.

Article 2

Operating bans

- 1. The air carriers listed in Annex A are subject to a ban within the Community for all their operations.
- 2. The air carriers listed in Annex B are subject to operational restrictions within the Community. The operational restrictions consist of a prohibition on the use of the specific aircraft or specific aircraft types mentioned in Annex B.

Article 3

Enforcement

Member States shall inform the Commission of any measures taken under Articles 3(1) of the basic Regulation to enforce, within their territory, the operating bans included in the Community list in respect of the air carriers that are the subject of those bans.

Article 4

Entry into force

This Regulation shall enter into force on the first day following that of its publication in the *Official Journal of the European Union*.

This Regulation shall be binding in its entirety and directly applicable in all Member States.

 ${\it ANNEX~A}$ LIST OF AIR CARRIERS OF WHICH ALL OPERATIONS ARE SUBJECT TO A BAN WITHIN THE EU $(^1)$

Name of the legal entity of the air carrier as indicated on its AOC (and its trading name, if different)		ICAO airline designation number	State of the Operator	
BLUE WING AIRLINES	SRBWA-01/2002	BWI	Suriname	
MERIDIAN AIRWAYS LTD	AOC 023	MAG	Republic of Ghana	
SIEM REAP AIRWAYS INTER- NATIONAL	AOC/013/00	SRH	Kingdom of Cambodia	
SILVERBACK CARGO FREIGHTERS	Unknown	VRB	Republic of Rwanda	
All air carriers certified by the authorities with responsibility for regulatory oversight of Afghanistan, including			Islamic Republic of Afghanistan	
ARIANA AFGHAN AIRLINES	AOC 009	AFG	Islamic Republic of Afghanistan	
KAM AIR	AOC 001	KMF	Islamic Republic of Afghanistan	
PAMIR AIRLINES	Unknown	PIR	Islamic Republic of Afghanistan	
SAFI AIRWAYS	AOC 181	SFW	Islamic Republic of Afghanistan	
All air carriers certified by the authorities with responsibility for regulatory oversight of Angola, with the exception of TAAG Angola Airlines put in Annex B, including			Republic of Angola	
AEROJET	015	Unknown	Republic of Angola	
AIR26	004	DCD	Republic of Angola	
AIR GEMINI	002	GLL	Republic of Angola	
AIR GICANGO	009	Unknown	Republic of Angola	
AIR JET	003	MBC	Republic of Angola	
AIR NAVE	017	Unknown	Republic of Angola	
ALADA	005	RAD	Republic of Angola	
ANGOLA AIR SERVICES	006	Unknown	Republic of Angola	
DIEXIM	007	Unknown	Republic of Angola	
GIRA GLOBO	008	GGL	Republic of Angola	
HELIANG	010	Unknown	Republic of Angola	
HELIMALONGO	011	Unknown	Republic of Angola	
MAVEWA	016	Unknown	Republic of Angola	
РНА	019	Unknown	Republic of Angola	
RUI & CONCEICAO	012	Unknown	Republic of Angola	

⁽¹⁾ Air carriers listed in Annex A could be permitted to exercise traffic rights by using wet-leased aircraft of an air carrier which is not subject to an operating ban, provided that the relevant safety standards are complied with.

Air Operator Certificate (AOC) Number or Operating Licence Number	ICAO airline designation number	State of the Operator
018	Unknown	Republic of Angola
014	SOR	Republic of Angola
		Republic of Benin
PEA No 014/ MDCTTTATP-PR/ ANAC/DEA/SCS	AEB	Republic of Benin
Unknown	AFF	Republic of Benin
PEA No 014/ANAC/ MDCTTTATP-PR/ DEA/SCS	N/A	Republic of Benin
PEA No 012/MDCTTP- PR/ANAC/DEA/SCS.	BGL	Republic of Benin
PEA No 013/ MDCTTTATP-PR/ ANAC/DEA/SCS.	LTL	Republic of Benin
PEA No 015/ MDCTTTATP-PR/ ANAC/DEA/SCS.	СОВ	Republic of Benin
PEA No 11/ANAC/ MDCTTP-PR/DEA/SCS	BNR	Republic of Benin
PEA No 016/ MDCTTTATP-PR/ ANAC/DEA/SCS	TNB	Republic of Benin
		Republic of Congo
RAC06-002	RSR	Republic of Congo
RAC 06-003	EKA	Republic of Congo
RAC 06-004	Unknown	Republic of Congo
RAC 06-001	Unknown	Republic of Congo
		Democratic Republic of Congo (RDC)
409/CAB/MIN/TVC/ 051/09	Unknown	Democratic Republic of Congo (RDC)
409/CAB/MIN/TVC/ 036/08	Unknown	Democratic Republic of Congo (RDC)
409/CAB/MIN/TVC/ 031/08	Unknown	Democratic Republic of Congo (RDC)
409/CAB/MIN/TVC/ 029/08	Unknown	Democratic Republic of Congo (RDC)
409/CAB/MIN/TVC/ 028/08	BUL	Democratic Republic of Congo (RDC)
409/CAB/MIN/TC/ 0090/2006	BRV	Democratic Republic of Congo (RDC)
	(AOC) Number or Operating Licence Number 018 014 PEA No 014/ MDCTTTATP-PR/ ANAC/DEA/SCS Unknown PEA No 014/ANAC/ MDCTTTATP-PR/ DEA/SCS PEA No 012/MDCTTP- PR/ANAC/DEA/SCS. PEA No 013/ MDCTTTATP-PR/ ANAC/DEA/SCS. PEA No 015/ MDCTTTATP-PR/ ANAC/DEA/SCS. PEA No 016/ MDCTTTATP-PR/ ANAC/DEA/SCS 409/CAB/MIN/TVC/ 031/08 409/CAB/MIN/TVC/ 031/08 409/CAB/MIN/TVC/ 029/08 409/CAB/MIN/TVC/ 029/08 409/CAB/MIN/TVC/ 029/08 409/CAB/MIN/TVC/ 029/08 409/CAB/MIN/TVC/ 029/08	CAOC Number or Operating Licence Number

Name of the legal entity of the air carrier as indicated on its AOC (and its trading name, if different)	Air Operator Certificate (AOC) Number or Operating Licence Number	ICAO airline designation number	State of the Operator
BUSINESS AVIATION	409/CAB/MIN/TVC/ 048/09	Unknown	Democratic Republic of Congo (RDC)
BUSY BEE CONGO	409/CAB/MIN/TVC/ 052/09	Unknown	Democratic Republic of Congo (RDC)
CETRACA AVIATION SERVICE	409/CAB/MIN/TVC/ 026/08	CER	Democratic Republic of Congo (RDC)
CHC STELLAVIA	409/CAB/MIN/TC/ 0050/2006	Unknown	Democratic Republic of Congo (RDC)
CONGO EXPRESS	409/CAB/MIN/TVC/ 083/2009	EXY	Democratic Republic of Congo (RDC)
COMPAGNIE AFRICAINE D'AVIATION (CAA)	409/CAB/MIN/TVC/ 035/08	Unknown	Democratic Republic of Congo (RDC)
DOREN AIR CONGO	409/CAB/MIN/TVC/ 0032/08	Unknown	Democratic Republic of Congo (RDC)
ENTREPRISE WORLD AIRWAYS (EWA)	409/CAB/MIN/TVC/ 003/08	EWS	Democratic Republic of Congo (RDC)
FILAIR	409/CAB/MIN/TVC/ 037/08	Unknown	Democratic Republic of Congo (RDC)
GALAXY KAVATSI	409/CAB/MIN/TVC/ 027/08	Unknown	Democratic Republic of Congo (RDC)
GILEMBE AIR SOUTENANCE (GISAIR)	409/CAB/MIN/TVC/ 053/09	Unknown	Democratic Republic of Congo (RDC)
GOMA EXPRESS	409/CAB/MIN/TC/ 0051/2006	Unknown	Democratic Republic of Congo (RDC)
GOMAIR	409/CAB/MIN/TVC/ 045/09	Unknown	Democratic Republic of Congo (RDC)
HEWA BORA AIRWAYS (HBA)	409/CAB/MIN/TVC/ 038/08	ALX	Democratic Republic of Congo (RDC)
INTERNATIONAL TRANS AIR BUSINESS (ITAB)	409/CAB/MIN/TVC/ 033/08	Unknown	Democratic Republic of Congo (RDC)
KIN AVIA	409/CAB/MIN/TVC/ 042/09	Unknown	Democratic Republic of Congo (RDC)
LIGNES AÉRIENNES CONGO- LAISES (LAC)	Ministerial signature (ordonnance No. 78/ 205)	LCG	Democratic Republic of Congo (RDC)
MALU AVIATION	409/CAB/MIN/TVC/ 04008	Unknown	Democratic Republic of Congo (RDC)
MANGO AVIATION	409/CAB/MIN/TVC/ 034/08	Unknown	Democratic Republic of Congo (RDC)
SAFE AIR COMPANY	409/CAB/MIN/TVC/ 025/08	Unknown	Democratic Republic of Congo (RDC)
SERVICES AIR	409/CAB/MIN/TVC/ 030/08	Unknown	Democratic Republic of Congo (RDC)
SWALA AVIATION	409/CAB/MIN/TVC/ 050/09	Unknown	Democratic Republic of Congo (RDC)
TMK AIR COMMUTER	409/CAB/MIN/TVC/ 044/09	Unknown	Democratic Republic of Congo (RDC)
TRACEP CONGO AVIATION	409/CAB/MIN/TVC/ 046/09	Unknown	Democratic Republic of Congo (RDC)
TRANS AIR CARGO SERVICES	409/CAB/MIN/TVC/ 024/08	Unknown	Democratic Republic of Congo (RDC)

Name of the legal entity of the air carrier as indicated on its AOC (and its trading name, if different)	Air Operator Certificate (AOC) Number or Operating Licence Number	ICAO airline designation number	State of the Operator
WIMBI DIRA AIRWAYS	409/CAB/MIN/TVC/ 039/08	WDA	Democratic Republic of Congo (RDC)
ZAABU INTERNATIONAL	409/CAB/MIN/TVC/ 049/09	Unknown	Democratic Republic of Congo (RDC)
All air carriers certified by the authorities with responsibility for regulatory oversight of Djibouti, including			Djibouti
DAALLO AIRLINES	Unknown	DAO	Djibouti
All air carriers certified by the authorities with responsibility for regulatory oversight of Equatorial Guinea, including			Equatorial Guinea
CRONOS AIRLINES	Unknown	Unknown	Equatorial Guinea
CEIBA INTERCONTINENTAL	Unknown	CEL	Equatorial Guinea
EGAMS	Unknown	EGM	Equatorial Guinea
EUROGUINEANA DE AVIACION Y TRANSPORTES	2006/001/MTTCT/ DGAC/SOPS	EUG	Equatorial Guinea
GENERAL WORK AVIACION	002/ANAC	n/a	Equatorial Guinea
GETRA - GUINEA ECUATORIAL DE TRANSPORTES AEREOS	739	GET	Equatorial Guinea
GUINEA AIRWAYS	738	n/a	Equatorial Guinea
STAR EQUATORIAL AIRLINES	Unknown	Unknown	Equatorial Guinea
UTAGE – UNION DE TRANSPORT AEREO DE GUINEA ECUATORIAL	737	UTG	Equatorial Guinea
All air carriers certified by the authorities with responsibility for regulatory oversight of Indonesia, with the exception of Garuda Indonesia, Airfast Indonesia, Mandala Airlines, Ekspres Transportasi Antarbenua, Indonesia Air Asia and Metro Batavia, including			Republic of Indonesia
AIR PACIFIC UTAMA	135-020	Unknown	Republic of Indonesia
ALFA TRANS DIRGANTATA	135-012	Unknown	Republic of Indonesia
ASCO NUSA AIR	135-022	Unknown	Republic of Indonesia
ASI PUDJIASTUTI	135-028	Unknown	Republic of Indonesia
AVIASTAR MANDIRI	135-029	Unknown	Republic of Indonesia
CARDIG AIR	121-013	Unknown	Republic of Indonesia
DABI AIR NUSANTARA	135-030	Unknown	Republic of Indonesia
DERAYA AIR TAXI	135-013	DRY	Republic of Indonesia
DERAZONA AIR SERVICE	135-010	DRZ	Republic of Indonesia
DIRGANTARA AIR SERVICE	135-014	DIR	Republic of Indonesia
EASTINDO	135-038	Unknown	Republic of Indonesia
GATARI AIR SERVICE	135-018	GHS	Republic of Indonesia
INDONESIA AIR TRANSPORT	135-034	IDA	Republic of Indonesia
INTAN ANGKASA AIR SERVICE	135-019	Unknown	Republic of Indonesia

Name of the legal entity of the air carrier as indicated on its AOC (and its trading name, if different)	Air Operator Certificate (AOC) Number or Operating Licence Number	ICAO airline designation number	State of the Operator
JOHNLIN AIR TRANSPORT	135-043	Unknown	Republic of Indonesia
KAL STAR	121-037	KLS	Republic of Indonesia
KARTIKA AIRLINES	121-003	KAE	Republic of Indonesia
KURA-KURA AVIATION	135-016	KUR	Republic of Indonesia
LION MENTARI AIRLINES	121-010	LNI	Republic of Indonesia
MANUNGGAL AIR SERVICE	121-020	Unknown	Republic of Indonesia
MEGANTARA	121-025	MKE	Republic of Indonesia
MERPATI NUSANTARA AIRLINES	121-002	MNA	Republic of Indonesia
MIMIKA AIR	135-007	Unknown	Republic of Indonesia
NATIONAL UTILITY HELICOPTER	135-011	Unknown	Republic of Indonesia
NUSANTARA AIR CHARTER	121-022	Unknown	Republic of Indonesia
NUSANTARA BUANA AIR	135-041	Unknown	Republic of Indonesia
NYAMAN AIR	135-042	Unknown	Republic of Indonesia
PELITA AIR SERVICE	121-008	PAS	Republic of Indonesia
PENERBANGAN ANGKASA SEMESTA	135-026	Unknown	Republic of Indonesia
PURA WISATA BARUNA	135-025	Unknown	Republic of Indonesia
REPUBLIC EXPRESS AIRLINES	121-040	RPH	Republic of Indonesia
RIAU AIRLINES	121-016	RIU	Republic of Indonesia
SAMPOERNA AIR NUSANTARA	135-036	SAE	Republic of Indonesia
SAYAP GARUDA INDAH	135-004	Unknown	Republic of Indonesia
SKY AVIATION	135-044	Unknown	Republic of Indonesia
SMAC	135-015	SMC	Republic of Indonesia
SRIWIJAYA AIR	121-035	SJY	Republic of Indonesia
SURVEI UDARA PENAS	135-006	Unknown	Republic of Indonesia
TRANSWISATA PRIMA AVIATION	135-021	Unknown	Republic of Indonesia
TRAVEL EXPRESS AVIATION SERVICE	121-038	XAR	Republic of Indonesia
TRAVIRA UTAMA	135-009	Unknown	Republic of Indonesia
TRI MG INTRA ASIA AIRLINES	121-018	TMG	Republic of Indonesia
TRIGANA AIR SERVICE	121-006	TGN	Republic of Indonesia
UNINDO	135-040	Unknown	Republic of Indonesia
WING ABADI AIRLINES	121-012	WON	Republic of Indonesia
All air carriers certified by the authorities with responsibility for regulatory oversight of Kazakhstan, with the exception of Air Astana, including			Republic of Kazakhstan
AERO AIR COMPANY	Unknown	Unknown	Republic of Kazakhstan
AIR ALMATY	AK-0331-07	LMY	Republic of Kazakhstan
AIR COMPANY KOKSHETAU	AK-0357-08	KRT	Republic of Kazakhstan
AIR DIVISION OF EKA	Unknown	Unknown	Republic of Kazakhstan

<u>™16</u>

Name of the local entity of the air corrier of	Air Operator Cartificate		
Name of the legal entity of the air carrier as indicated on its AOC (and its trading name, if different)	Air Operator Certificate (AOC) Number or Operating Licence Number	ICAO airline designation number	State of the Operator
AIR FLAMINGO	Unknown	Unknown	Republic of Kazakhstan
AIR TRUST AIRCOMPANY	Unknown	Unknown	Republic of Kazakhstan
AK SUNKAR AIRCOMPANY	Unknown	AKS	Republic of Kazakhstan
ALMATY AVIATION	Unknown	LMT	Republic of Kazakhstan
ARKHABAY	Unknown	KEK	Republic of Kazakhstan
ASIA CONTINENTAL AIRLINES	AK-0345-08	CID	Republic of Kazakhstan
ASIA CONTINENTAL AVIALINES	AK-0371-08	RRK	Republic of Kazakhstan
ASIA WINGS	AK-0390-09	AWA	Republic of Kazakhstan
ATMA AIRLINES	AK-0372-08	AMA	Republic of Kazakhstan
ATYRAU AYE JOLY	AK-0321-07	JOL	Republic of Kazakhstan
AVIA-JAYNAR	Unknown	SAP	Republic of Kazakhstan
BEYBARS AIRCOMPANY	Unknown	BBS	Republic of Kazakhstan
BERKUT AIR/BEK AIR	AK-0311-07	BKT/BEK	Republic of Kazakhstan
BURUNDAYAVIA AIRLINES	AK-0374-08	BRY	Republic of Kazakhstan
COMLUX	AK-0352-08	KAZ	Republic of Kazakhstan
DETA AIR	AK-0344-08	DET	Republic of Kazakhstan
EAST WING	AK-0332-07	EWZ	Republic of Kazakhstan
EASTERN EXPRESS	AK-0358-08	LIS	Republic of Kazakhstan
EURO-ASIA AIR	AK-0384-09	EAK	Republic of Kazakhstan
EURO-ASIA AIR INTERNATIONAL	Unknown	KZE	Republic of Kazakhstan
FLY JET KZ	AK-0391-09	FJK	Republic of Kazakhstan
INVESTAVIA	AK-0342-08	TLG	Republic of Kazakhstan
IRTYSH AIR	AK-0381-09	MZA	Republic of Kazakhstan
JET AIRLINES	AK-0349-09	SOZ	Republic of Kazakhstan
JET ONE	AK-0367-08	JKZ	Republic of Kazakhstan
KAZAIR JET	AK-0387-09	KEJ	Republic of Kazakhstan
KAZAIRTRANS AIRLINE	AK-0347-08	KUY	Republic of Kazakhstan
KAZAIRWEST	Unknown	KAW	Republic of Kazakhstan
KAZAVIA	Unknown	KKA	Republic of Kazakhstan
KAZAVIASPAS	Unknown	KZS	Republic of Kazakhstan
KOKSHETAU	AK-0357-08	KRT	Republic of Kazakhstan
MEGA AIRLINES	AK-0356-08	MGK	Republic of Kazakhstan
MIRAS	AK-0315-07	MIF	Republic of Kazakhstan
ORLAN 2000 AIRCOMPANY	Unknown	KOV	Republic of Kazakhstan
PANKH CENTER KAZAKHSTAN	Unknown	Unknown	Republic of Kazakhstan
PRIME AVIATION	Unknown	PKZ	Republic of Kazakhstan
SAMAL AIR	Unknown	SAV	Republic of Kazakhstan
SAYAKHAT AIRLINES	AK-0359-08	SAH	Republic of Kazakhstan
SEMEYAVIA	Unknown	SMK	Republic of Kazakhstan

Name of the legal entity of the air carrier as indicated on its AOC (and its trading name, if different)	Air Operator Certificate (AOC) Number or Operating Licence Number	ICAO airline designation number	State of the Operator
SCAT	AK-0350-08	VSV	Republic of Kazakhstan
SKYBUS	AK-0364-08	BYK	Republic of Kazakhstan
SKYJET	AK-0307-09	SEK	Republic of Kazakhstan
UST-KAMENOGORSK	AK-0385-09	UCK	Republic of Kazakhstan
ZHETYSU AIRCOMPANY	Unknown	JTU	Republic of Kazakhstan
ZHERSU AVIA	Unknown	RZU	Republic of Kazakhstan
ZHEZKAZGANAIR	Unknown	KZH	Republic of Kazakhstan
All air carriers certified by the authorities with responsibility for regulatory oversight of the Kyrgyz Republic, including			Kyrgyz Republic
AIR MANAS	17	MBB	Kyrgyz Republic
ASIAN AIR	36	AAZ	Kyrgyz Republic
AVIA TRAFFIC COMPANY	23	AVJ	Kyrgyz Republic
AEROSTAN (EX BISTAIR-FEZ BISHKEK)	08	BSC	Kyrgyz Republic
CAAS	13	СВК	Kyrgyz Republic
CLICK AIRWAYS	11	CGK	Kyrgyz Republic
DAMES	20	DAM	Kyrgyz Republic
EASTOK AVIA	15	EEA	Kyrgyz Republic
GOLDEN RULE AIRLINES	22	GRS	Kyrgyz Republic
ITEK AIR	04	IKA	Kyrgyz Republic
KYRGYZ TRANS AVIA	31	KTC	Kyrgyz Republic
KYRGYZSTAN	03	LYN	Kyrgyz Republic
KYRGYZSTAN AIRLINE	Unknown	KGA	Kyrgyz Republic
MAX AVIA	33	MAI	Kyrgyz Republic
S GROUP AVIATION	6	SGL	Kyrgyz Republic
SKY GATE INTERNATIONAL AVIATION	14	SGD	Kyrgyz Republic
SKY WAY AIR	21	SAB	Kyrgyz Republic
TENIR AIRLINES	26	TEB	Kyrgyz Republic
TRAST AERO	05	TSJ	Kyrgyz Republic
VALOR AIR	07	VAC	Kyrgyz Republic
All air carriers certified by the authorities with responsibility for regulatory oversight of Liberia.			Liberia
All air carriers certified by the authorities with responsibility for regulatory oversight of the Republic of Gabon, with the exception of Gabon Airlines, Afrijet and SN2AG put in Annex B, including			Republic of Gabon
AFRIC AVIATION		Unknown	Republic of Gabon

	ICAO airline designation number	State of the Operator
004/MTAC/ANAC-G/ DSA	RVS	Republic of Gabon
007/MTAC/ANAC-G/ DSA	LGE	Republic of Gabon
008/MTAC/ANAC-G/ DSA	NRG	Republic of Gabon
005/MTAC/ANAC-G/ DSA	SCY	Republic of Gabon
009/MTAC/ANAC-G/ DSA	SKG	Republic of Gabon
006/MTAC/ANAC-G/ DSA	Unknown	Republic of Gabon
		Republic of Mauritania
	MTW	Republic of Mauritania
		Republic of the Philippines
2010030	Unknown	Republic of the Philippines
2009006	GAP	Republic of the Philippines
200911	Unknown	Republic of the Philippines
2010027	Unknown	Republic of the Philippines
4AN9800036	Unknown	Republic of the Philippines
4AN2007005	Unknown	Republic of the Philippines
200910	Unknown	Republic of the Philippines
4AN9900003	Unknown	Republic of the Philippines
Unknown	Unknown	Republic of the Philippines
4AN2008006	Unknown	Republic of the Philippines
4AN9800025	Unknown	Republic of the Philippines
2009002	CEB	Republic of the Philippines
2009018	Unknown	Republic of the Philippines
4AN2000001	Unknown	Republic of the Philippines
Unknown	Unknown	Republic of the Philippines
4AN9900008	Unknown	Republic of the Philippines
2009013	Unknown	Republic of the Philippines
2009017	Unknown	Republic of the Philippines
2009014	Unknown	Republic of the Philippines
	(AOC) Number or Operating Licence Number 004/MTAC/ANAC-G/ DSA 007/MTAC/ANAC-G/ DSA 008/MTAC/ANAC-G/ DSA 009/MTAC/ANAC-G/ DSA 009/MTAC/ANAC-G/ DSA 006/MTAC/ANAC-G/ DSA 2010030 2009006 200911 2010027 4AN9800036 4AN2007005 200910 4AN9900003 Unknown 4AN2008006 4AN9800025 2009018 4AN2000001 Unknown 4AN9900008 2009017	(AOC) Number or Operating Licence Number NAVO almine designation number

Name of the legal entity of the air carrier as indicated on its AOC (and its trading name, if different)	Air Operator Certificate (AOC) Number or Operating Licence Number	ICAO airline designation number	State of the Operator
INAEC AVIATION CORP.	4AN2002004	Unknown	Republic of the Phil ippines
ISLAND AVIATION	2009009	SOY	Republic of the Phil ippines
ISLAND TRANSVOYAGER	2010022	Unknown	Republic of the Phil ippines
LION AIR, INCORPORATED	2009019	Unknown	Republic of the Phil ippines
MACRO ASIA AIR TAXI SERVICES	2010029	Unknown	Republic of the Phil ippines
MINDANAO RAINBOW AGRI- CULTURAL DEVELOPMENT SERVICES	2009016	Unknown	Republic of the Phil ippines
MISIBIS AVIATION & DEVEL- OPMENT CORP	2010020	Unknown	Republic of the Phil ippines
OMNI AVIATION CORP.	2010033	Unknown	Republic of the Phil ippines
PACIFIC EAST ASIA CARGO AIRLINES, INC.	4AS9800006	PEC	Republic of the Philippines
PACIFIC AIRWAYS CORPORATION	4AN9700007	Unknown	Republic of the Philippines
PACIFIC ALLIANCE CORPORATION	4AN2006001	Unknown	Republic of the Philippines
PHILIPPINE AIRLINES	2009001	PAL	Republic of the Phil ippines
PHILIPPINE AGRICULTURAL AVIATION CORP.	4AN9800015	Unknown	Republic of the Phil ippines
ROYAL AIR CHARTER SERVICES INC.	2010024	Unknown	Republic of the Philippines
ROYAL STAR AVIATION, INC.	2010021	Unknown	Republic of the Philippines
SOUTH EAST ASIA INC.	2009004	Unknown	Republic of the Philippines
SOUTHSTAR AVIATION COMPANY, INC.	4AN9800037	Unknown	Republic of the Philippines
SPIRIT OF MANILA AIRLINES CORPORATION	2009008	MNP	Republic of the Philippines
SUBIC INTERNATIONAL AIR CHARTER	4AN9900010	Unknown	Republic of the Philippines
SUBIC SEAPLANE, INC.	4AN2000002	Unknown	Republic of the Phil- ippines
TOPFLITE AIRWAYS, INC.	4AN9900012	Unknown	Republic of the Philippines
TRANSGLOBAL AIRWAYS CORPORATION	2009007	TCU	Republic of the Phil- ippines
WORLD AVIATION, CORP.	Unknown	Unknown	Republic of the Phil- ippines
WCC AVIATION COMPANY	2009015	Unknown	Republic of the Philippines
YOKOTA AVIATION, INC.	Unknown	Unknown	Republic of the Philippines
ZENITH AIR, INC.	2009012	Unknown	Republic of the Philippines
ZEST AIRWAYS INCORPORATED	2009003	RIT	Republic of the Philippines
All air carriers certified by the authorities with responsibility for regulatory oversight of Sao Tome and Principe, including			Sao Tome and Princip
AFRICA CONNECTION	10/AOC/2008	Unknown	Sao Tome and Principe
	01/AOC/2007	BGI	Sao Tome and Principe

Name of the legal entity of the air carrier as	Air Operator Certificate	ICAO airline designation	
indicated on its AOC (and its trading name, if different)	(AOC) Number or Operating Licence Number	number	State of the Operator
EXECUTIVE JET SERVICES	03/AOC/2006	EJZ	Sao Tome and Principe
GLOBAL AVIATION OPERATION	04/AOC/2006	Unknown	Sao Tome and Principe
GOLIAF AIR	05/AOC/2001	GLE	Sao Tome and Principe
ISLAND OIL EXPLORATION	01/AOC/2008	Unknown	Sao Tome and Principe
STP AIRWAYS	03/AOC/2006	STP	Sao Tome and Principe
TRANSAFRIK INTERNATIONAL LTD	02/AOC/2002	TFK	Sao Tome and Principe
TRANSCARG	01/AOC/2009	Unknown	Sao Tome and Principe
TRANSLIZ AVIATION (TMS)	02/AOC/2007	TMS	Sao Tome and Principe
All air carriers certified by the authorities with responsibility for regulatory oversight of Sierra Leone, including			Sierra Leone
AIR RUM, LTD	Unknown	RUM	Sierra Leone
DESTINY AIR SERVICES, LTD	Unknown	DTY	Sierra Leone
HEAVYLIFT CARGO	Unknown	Unknown	Sierra Leone
ORANGE AIR SIERRA LEONE LTD	Unknown	ORJ	Sierra Leone
PARAMOUNT AIRLINES, LTD	Unknown	PRR	Sierra Leone
SEVEN FOUR EIGHT AIR SERVICES LTD	Unknown	SVT	Sierra Leone
TEEBAH AIRWAYS	Unknown	Unknown	Sierra Leone
All air carriers certified by the authorities with responsibility for regulatory oversight of Sudan, including			Republic of Sudan
SUDAN AIRWAYS	Unknown	SUD	Republic of the Sudan
SUN AIR COMPANY	051	SNR	Republic of the Sudan
MARSLAND COMPANY	040	MSL	Republic of the Sudan
ATTICO AIRLINES	023	ETC	Republic of the Sudan
FOURTY EIGHT AVIATION	054	WHB	Republic of the Sudan
SUDANESE STATES AVIATION COMPANY	010	SNV	Republic of the Sudan
ALMAJARA AVIATION	Unknown	MJA	Republic of the Sudan
BADER AIRLINES	035	BDR	Republic of the Sudan
ALFA AIRLINES	054	AAJ	Republic of the Sudan
AZZA TRANSPORT COMPANY	012	AZZ	Republic of the Sudan
GREEN FLAG AVIATION	017	Unkown	Republic of the Sudan
ALMAJAL AVIATION SERVICE	015	MGG	Republic of the Sudan
NOVA AIRLINES	001	NOV	Republic of the Sudan
TARCO AIRLINES	056	Unknown	Republic of the Sudan
All air carriers certified by the authorities with responsibility for regulatory oversight of Swaziland, including			Swaziland

Name of the legal entity of the air carrier as indicated on its AOC (and its trading name, if different)		ICAO airline designation number	State of the Operator
SWAZILAND AIRLINK	Unknown	SZL	Swaziland
All air carriers certified by the authorities with responsibility for regulatory oversight of Zambia, including			Zambia
ZAMBEZI AIRLINES	Z/AOC/001/2009	ZMA	Zambia

ANNEX B

LIST OF AIR CARRIERS OF WHICH OPERATIONS ARE SUBJECT TO OPERATIONAL RESTRICTIONS WITHIN THE EU $(^{\rm l})$

Name of the legal entity of the air carrier as indicated on its AOC (and its trading name, if different)	Air Operator Certificate (AOC) Number	ICAO airline designation number	State of the Operator	Aircraft type restricted	Registration mark(s) and, when available, construction serial number(s)	State of registry
AIR KORYO	GAC-AOC/ KOR-01	KOR	DPRK	All fleet with the exception of: 2 aircraft of type Tu- 204	All fleet with the exception of: P-632, P-633	DPRK
AFRIJET (¹)	002/MTAC/ ANAC-G/ DSA		Republic of Gabon	All fleet with the exception of: 2 aircraft of type Falcon 50; 2 aircraft of type Falcon 900	All fleet with the exception of: TR-LGV; TR-AFJ; TR-AFR	Republic of Gabon
AIR ASTANA (²)	AK-0388-09	KZR	Kazakhsta- n	All fleet with the exception of: 2 aircraft of type B767; 4 aircraft of type B757; 10 aircraft of type A319/320/321; 5 aircraft of type Fokker 50	All fleet with the exception of: P4-KCA, P4-KCB; P4-EAS, P4-FAS, P4-GAS, P4-NAS, P4-OAS, P4-PAS, P4-VAS, P4-VAS, P4-VAS, P4-VAS, P4-VAS, P4-IAS, P4-IAS, P4-IAS, P4-IAS, P4-IAS, P4-IAS, P4-IAS, P4-IAS	Aruba (Kingdom of the Netherlands)
AIRLIFT INTER- NATIONAL (GH) LTD	AOC 017	ALE	Republic of Ghana		All fleet with the exception of: 9G-TOP and 9G-RAC	
AIR SERVICE COMORES	06-819/TA-15/ DGACM	KMD	Comoros	All fleet with the exception of: LET 410 UVP	All fleet with the exception of: D6-CAM (851336)	Comoros
GABON AIRLINES (³)	001/MTAC/ ANAC	GBK	Republic of Gabon	All fleet with the exception of: 1 aircraft of type Boeing B-767-200	All fleet with the exception of: TR-LHP	Republic of Gabon

⁽¹⁾ Air carriers listed in Annex B could be permitted to exercise traffic rights by using wet-leased aircraft of an air carrier which is not subject to an operating ban, provided that the relevant safety standards are complied with.

Name of the legal entity of the air carrier as indicated on its AOC (and its trading name, if different)	Air Operator Certificate (AOC) Number	ICAO airline designation number	State of the Operator	Aircraft type restricted	Registration mark(s) and, when available, construction serial number(s)	State of registry
IRAN AIR (⁴)	FS100	IRA	Islamic Republic of Iran	All fleet with the exception of: 14 aircraft of type A300, 8 aircraft of type A310, 1 aircraft B737	All fleet with the exception of: EP-IBA EP-IBB EP-IBC EP-IBD EP-IBG EP-IBH EP-IBI EP-IBJ EP-IBN EP-IBN EP-IBN EP-IBS EP-IBS EP-IBT EP-IBV EP-IBZ EP-ICE EP-ICF EP-IBK EP-IBL EP-IBP EP-IBQ EP-AGA	Islamic Republic of Iran
NOUVELLE AIR AFFAIRES GABON (SN2AG)	003/MTAC/ ANAC-G/ DSA	NVS	Republic of Gabon	All fleet with the exception of: 1 aircraft of type Challenger CL601; 1 aircraft of type HS-125-800	All fleet with the exception of: TR-AAG, ZS-AFG	Republic of Gabon; Republic of South Africa
TAAG ANGOLA AIRLINES	001	DTA	Republic of Angola	All fleet with the exception of: 3 aircraft of type Boeing B-777 and 4 aircraft of type Boeing B-737-700	All fleet with the exception of: D2-TED, D2-TEE, D2-TEF, D2-TBF, D2, TBG, D2-TBH, D2-TBJ	Republic of Angola
UKRAINIAN MEDITER- RANEAN	164	UKM	Ukraine	All fleet with the exception of: one aircraft of type MD-83	All fleet with the exception of: UR-CFF	Ukraine

⁽¹⁾ Afrijet is only allowed to use the specific aircraft mentioned for its current operations within the European Union.

⁽²⁾ Air Astana is only allowed to use the specific aircraft mentioned for its current operations within the European Union.

 ⁽³⁾ Gabon Airlines is only allowed to use the specific aircraft mentioned for its current operations within the European Community.
 (4) Iran Air is allowed to operate to the European Union using the specific aircraft under the conditions set out in recital (69) Regulation (EU) No 590/2010, OJ L 170, 6.7.2010, p. 15.