



Mines and Quarries Act 1954

1954 CHAPTER 70

PART III

SAFETY, HEALTH AND WELFARE (MINES)

*Provisions for securing safe operation of Winding
and Rope Haulage Apparatus and Conveyors*

44 Charge of conveyors at working faces

No conveyor shall be operated along a working face in a mine except by, or under the constant supervision of, a competent male person who has attained the age of eighteen years.