

FIRST SCHEDULE

THE MISCELLANEOUS MINES (GENERAL) REGULATIONS, 1956, HAVING EFFECT AS IF MADE UNDER SECTION ONE HUNDRED AND FORTY-ONE OF THE MINES AND QUARRIES ACT, 1954

PART VI

Duties of persons operating winding apparatus

21.—(1) A person operating any winding apparatus with which a shaft is provided shall not leave the controlling gear whilst the apparatus is in motion or when he has any cause to believe that anyone is in or on the cage or kibble.

(2) Every person operating any such winding apparatus shall at least once during his shift examine the external parts of any engine which he operates to see if they are in proper working order.

(3) After any cessation of winding exceeding two hours the person operating any such winding apparatus shall immediately before lowering or raising any person run the cage or kibble at least once between the top of the shaft and the lowest entrance to the shaft for the time being in use in order to ascertain whether winding can be safely resumed. If any defect likely to affect the proper working of the winding apparatus is thus discovered he shall not begin winding until the defect has been remedied.

22. No person operating any winding apparatus shall allow any engine to be operated under his supervision (on an occasion to which subsection (1) of section forty-two of the Act does not apply) by any person other than one authorised in writing by the manager so to do.