
STATUTORY INSTRUMENTS

1956 No. 1943

The Stratified Ironstone, Shale and Fireclay
Mines (Explosives) Regulations 1956

PART V

Shot firing—all mines

Drilling and cleaning shot holes

- 20.**—(1) No person shall begin to charge any shot hole unless it is thoroughly cleaned out.
- (2) No person shall use compressed air to clean out any shot hole unless he ensures that the giving off of any dust is minimised.