
STATUTORY INSTRUMENTS

1996 No. 1656

The Work in Compressed Air Regulations 1996

Badge, label or other device

19.—(1) Every compressed air contractor shall ensure that any person who works in compressed air at a pressure of 0.7 bar or above is supplied with a suitable and suitably worded badge, label or other similar device for the guidance of others should that employee be taken ill after leaving work and that the badge, label or device, as the case may be, contains such particulars as may be approved by the Executive.

(2) Every person to whom a badge, label or other device has been supplied in accordance with paragraph (1) shall wear that badge, label or device for 24 hours after leaving work in compressed air.