

## SCHEDULE 2

### DANGEROUS OCCURRENCES

#### PART 3

#### DANGEROUS OCCURRENCES REPORTABLE IN RELATION TO A MINE

##### **Failures of plant or equipment**

**36.** The bringing to rest of any conveyance operated using the friction of a rope on a winding sheave by the apparatus provided—

(a) in the headframe of the shaft; or

(b) in the part of the shaft below the lowest landing for the time being in use,

for the purpose of bringing the conveyance to rest in the event of it being overwound.