

SCHEDULE 1

INFORMATION TO BE MARKED ON REGULATED NON-AUTOMATIC WEIGHING INSTRUMENTS

8. When applicable the following:
- (a) for instruments consisting of separate but associated units, the identification mark on each unit;
 - (b) scale interval if different from e, in the form “d = ...”;
 - (c) maximum additive tare effect, in the form “T = +.....”;
 - (d) maximum subtractive tare effect if it is different from Max, in the form “T = -...”;
 - (e) tare interval if it is different from d, in the form “d_T = ...”;
 - (f) maximum safe load if it is different from “Max...”, in the form “Lim...”;
 - (g) the special temperature limits, in the form “...°C/...°C”; and
 - (h) ratio between load receptor and load.