

Directive 2006/21/EC of the European Parliament and of the Council of 15 March 2006 on the management of waste from extractive industries and amending Directive 2004/35/EC

Article 4

General requirements

1 Member States shall take the necessary measures to ensure that extractive waste is managed without endangering human health and without using processes or methods which could harm the environment, and in particular without risk to water, air, soil and fauna and flora, without causing a nuisance through noise or odours and without adversely affecting the landscape or places of special interest. Member States shall also take the necessary measures to prohibit the abandonment, dumping or uncontrolled depositing of extractive waste.

2 Member States shall ensure that the operator takes all measures necessary to prevent or reduce as far as possible any adverse effects on the environment and human health brought about as a result of the management of extractive waste. This includes the management of any waste facility, also after its closure, and the prevention of major accidents involving that facility and the limiting of their consequences for the environment and human health.

3 The measures referred to in paragraph 2 shall be based, *inter alia*, on the best available techniques, without prescribing the use of any technique or specific technology, but taking into account the technical characteristics of the waste facility, its geographical location and the local environmental conditions.