

Commission Directive 2012/32/EU of 25 October 2012 amending Council Directive 96/98/EC on marine equipment (Text with EEA relevance) (repealed)

COMMISSION DIRECTIVE 2012/32/EU

of 25 October 2012

amending Council Directive 96/98/EC on marine equipment

(Text with EEA relevance) (repealed)

THE EUROPEAN COMMISSION,

Having regard to the Treaty on the Functioning of the European Union,

Having regard to Council Directive 96/98/EC of 20 December 1996 on marine equipment⁽¹⁾, and in particular Article 17 thereof,

Whereas:

- (1) For the purposes of Directive 96/98/EC, the international conventions and testing standards should apply in their up-to-date versions.
- (2) A number of amendments to the international conventions and applicable testing standards have entered into force since the adoption of the last amending act to Directive 96/98/EC. Those amendments should be incorporated into Directive 96/98/EC.
- (3) In the same period the International Maritime Organisation and the European standardisation organisations have also adopted standards, including detailed testing standards, for a number of items of equipment which are listed in Annex A.2 to Directive 96/98/EC or which, albeit not listed, are considered relevant for the purpose of that Directive. Therefore such items of equipment should be included in Annex A.1 or transferred from Annex A.2 to Annex A.1, as appropriate.
- (4) Directive 96/98/EC should therefore be amended accordingly.
- (5) It is reasonable to allow equipment newly subject to harmonised requirements under this Directive and manufactured before the expiry of the time limit for the implementation of this Directive to be placed on the market and on board a Community ship during a transitional period.
- (6) The measures provided for in this Directive are in accordance with the opinion of the Committee on Safe Seas and the Prevention of Pollution from Ships (COSS),

HAS ADOPTED THIS DIRECTIVE:

Article I

Annex A to Directive 96/98/EC is replaced by the text in the Annex to this Directive.

Article 2

Equipment listed in column 1 of Annex A.1 as ‘new item’ or as having been transferred from Annex A.2 which was manufactured before 30 November 2013 in conformity with procedures for type-approval already in force before that date within the territory of a Member State may continue to be placed on the market and on board a Community ship until 30 November 2015.

Article 3

1 Member States shall adopt and publish, by 30 November 2013 at the latest, the laws, regulations and administrative provisions necessary to comply with this Directive. They shall forthwith communicate to the Commission the text of those provisions.

They shall apply those provisions from 30 November 2013.

When Member States adopt those provisions, they shall contain a reference to this Directive or be accompanied by such a reference on the occasion of their official publication. Member States shall determine how such reference is to be made.

2 Member States shall communicate to the Commission the text of the main provisions of national law which they adopt in the field covered by this Directive.

Article 4

This Directive shall enter into force on the twentieth day following that of its publication in the *Official Journal of the European Union*.

Article 5

This Directive is addressed to the Member States.

Done at Brussels, 25 October 2012.

For the Commission

The President

José Manuel BARROSO

ANNEX

ANNEX General note for Annex A: SOLAS Regulations refer to SOLAS consolidated version A 2009.

General note for Annex A: Within certain item designations, column 5 shows some possible product variants under the same item designation. Product variants are independently provisioned and separated by a dotted line from each other. For certification purpose only the relevant product variant shall be chosen, as appropriate (Example: A.1/3.3).

List of acronyms used:

- A.1, Amendment 1 concerning standard documents other than IMO.
- A.2, Amendment 2 concerning standard documents other than IMO.
- AC, Amending Corrigendum concerning standard documents other than IMO.
- CAT, Category for radar equipment as defined in Section 1.3 of IEC 62388 (2007).
- Circ., Circular.
- Colreg, International Regulations for Preventing Collisions at Sea.
- Comsar, IMO's Sub-Committee on Radiocommunications and Search and Rescue.
- EN, European Standard.
- ETSI, European Telecommunication Standardisation Institute.
- FSS, International Code for Fire Safety Systems.
- FTP, International Code for Application of Fire Test Procedures.
- HSC, High-speed Craft Code.
- IBC, International Bulk Chemical Code.
- ICAO, International Civil Aviation Organisation.
- IEC, International Electro-technical Commission.
- IGC, International Code for the Construction and Equipment of Ships Carrying Liquefied Gases in Bulk.
- IMO, International Maritime Organisation.
- ISO, International Standardisation Organisation.
- ITU, International Telecommunication Union.
- LSA, Life-saving appliance.
- Marpol, International Convention for the Prevention of Pollution from Ships.
- MEPC, Marine Environment Protection Committee.
- MSC, Maritime Safety Committee.
- NO_x, Nitrogen oxides.
- SOLAS, International Convention for the Safety of Life at Sea.
- SO_x, Sulphur oxides.
- Reg., Regulation.
- Res., Resolution.

ANNEX A.1

EQUIPMENT FOR WHICH DETAILED TESTING STANDARDS ALREADY EXIST IN INTERNATIONAL INSTRUMENTS

Notes applicable to the whole of Annex A.1

- (a) General: in addition to the testing standards specifically mentioned, a number of provisions, which must be checked during type-examination (type approval) as referred to in the modules for conformity assessment in Annex B, are to be found in the applicable requirements of the international conventions and the relevant resolutions and circulars of the IMO.
- (b) Column 1: Article 2 of Commission Directive 2010/68/EU⁽²⁾ may apply (6th amendment of MED Annex A).
- (c) Column 1: Article 2 of Commission Directive 2011/75/EU⁽³⁾ may apply (7th amendment of MED Annex A).
- (d) Column 2: When the term “systems components” is used it may be that a single component, a group of components or a whole system needs to be tested to ensure that the international requirements are fulfilled.
- (e) Column 5: Where IMO Resolutions are cited, only the testing standards contained in relevant parts of the Annexes to the Resolutions are applicable and exclude the provisions of the Resolutions themselves.
- (f) Column 5: International conventions and testing standards apply in their up-to-date version. For the purpose of identifying correctly the relevant standards, test reports, certificates of conformity and declarations of conformity shall identify the specific testing standard applied and its version.
- (g) Column 5: Where two sets of identifying standards are separated by “or”, each set fulfills all the testing requirements to meet IMO performance standards; thus testing to one of these sets is sufficient to demonstrate compliance with the requirements of the relevant international instruments. Conversely, when other separators (comma) are used all the listed references apply.
- (h) Column 6: Where module H appears, module H plus design-examination certificate is to be understood.
- (i) The requirements laid down in this Annex shall be without prejudice to carriage requirements in the international conventions.

1. Life-saving appliances

Column 4: IMO MSC/Circular 980 shall apply except when superseded by the specific instruments referred to in Column 4.

No	Item designation	Regulation SOLAS 74, as amended, where “type approval” is required	Regulations of SOLAS 74, as amended, and the relevant resolutions and circulars of the IMO, as applicable	Testing standards	Modules for conformity assessment
a	Member States may apply Circular MSC.1/Circ.1393 of the IMO.				

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

1	2	3	4	5	6
A.1/1.1	Lifebuoys	— Reg. III/4, — Reg. X/3.	— Reg. III/7, — Reg. III/34, — IMO Res. — MSC.36(63)- (1994) HSC Code) 8, — IMO Res. — MSC.48(66)- (LSA Code) I, II, IMO Res. — MSC.97(73)- (2000) HSC Code) 8.	—	IMO Res. MSC.81(70).
A.1/1.2	Position-indicating lights for life-saving appliances: (a) for survival craft and rescue boats, (b) for lifebuoys, (c) for lifejackets.	— Reg. III/4, — Reg. X/3.	— Reg. III/7, — Reg. III/22, — Reg. III/26, — Reg. III/32, — Reg. III/34, — IMO Res. — MSC.36(63)- (1994) HSC Code) 8, — IMO Res. — MSC.48(66)- (LSA Code) II, IV, IMO Res.	—	IMO Res. MSC.81(70).

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

Status: This is the original version (as it was originally adopted).

				MSC.97(73)- (2000 HSC Code) 8.		
A.1/1.3	Lifebuoys self- activating smoke signals	— —	Reg. III/4, Reg. X/3.	Reg. III/7, — Reg. III/34, — IMO Res. MSC.36(63)- (1994 HSC Code) 8, IMO Res. MSC.48(66)- (LSA Code) I, II, IMO Res. MSC.97(73)- (2000 HSC Code) 8.	— IMO Res. MSC.81(70).	B + D B + E B + F
A.1/1.4	Lifejackets	— —	Reg. III/4, Reg. X/3.	Reg. III/7, — Reg. III/22, — Reg. III/34, — IMO Res. MSC.36(63)- (1994 HSC Code) 8, IMO Res. MSC.48(66)- (LSA Code) I, II, IMO Res.	— IMO Res. MSC.81(70).	B + D B + E B + F

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

					MSC.97(73)- (2000 HSC Code) 8, IMO MSC/ Circ.922, IMO MSC.1/ Circ.1304.	
A.1/1.5	Immersion suits and anti-exposure suits not classified as lifejackets: — insulated or not insulated.	— Reg. III/4, — Reg. X/3.	— Reg. III/7, — Reg. III/22, — Reg. III/32, — Reg. III/34, — IMO Res. MSC.36(63)- (1994 HSC Code) 8, IMO Res. MSC.48(66)- (LSA Code) I, II, IMO Res. MSC.97(73)- (2000 HSC Code) 8, IMO MSC/ Circ.1046.	— IMO Res. MSC.81(70).	B + D B + E B + F	
A.1/1.6	Immersion suits and anti-exposure suits classified as lifejackets: — insulated or	— Reg. III/4, — Reg. X/3.	— Reg. III/7, — Reg. III/22, — Reg. III/32, — Reg. III/34,	— IMO Res. MSC.81(70).	B + D B + E B + F	

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

Status: This is the original version (as it was originally adopted).

		non-insulated.	—	IMO Res. MSC.36(63)-(1994 HSC Code) 8,		
			—	IMO Res. MSC.48(66)-(LSA Code) I, II,		
			—	IMO Res. MSC.97(73)-(2000 HSC Code) 8,		
			—	IMO MSC/Circ.1046.		
A.1/1.7	Thermal protective aids	Reg. III/4, Reg. X/3	—	Reg. III/22, Reg. III/32, Reg. III/34, IMO Res. MSC.36(63)-(1994 HSC Code) 8,	IMO Res. MSC.81(70).	B + D B + E B + F
			—	IMO Res. MSC.48(66)-(LSA Code) I, II,		
			—	IMO Res. MSC.97(73)-(2000 HSC Code) 8,		

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

				—	IMO MSC/ Circ.1046.		
A.1/1.8	Rocket parachute flares (pyrotechnics)	—	Reg. III/4, —	—	Reg. III/6, —	—	IMO Res. MSC.81(70). B + D B + E B + F
A.1/1.9	Hand flares (pyrotechnics)	—	Reg. III/4, —	—	Reg. III/34, —	—	IMO Res. MSC.81(70). B + D B + E B + F

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

Status: This is the original version (as it was originally adopted).

				Code) 8.		
A.1/1.10	Buoyant smoke signals (pyrotechnics)	—	Reg. III/4, Reg. X/3.	Reg. III/34, IMO Res. MSC 48(66)- (LSA Code) I, III.	IMO Res. MSC 81(70).	B + D B + E B + F
A.1/1.11	Line-throwing appliances	—	Reg. III/4, Reg. X/3.	Reg. III/18, Reg. III/34, IMO Res. MSC 36(63)- (1994 HSC Code) 8, IMO Res. MSC 48(66)- (LSA Code) I, VII, IMO Res. MSC 97(73)- (2000 HSC Code) 8.	IMO Res. MSC 81(70).	B + D B + E B + F
A.1/1.12	Inflatable liferafts	—	Reg. III/4, Reg. X/3.	Reg. III/13, Reg. III/21, Reg. III/26, Reg. III/31, Reg. III/34, IMO Res. MSC 36(63)- (1994	IMO Res. MSC 81(70).	B + D B + E B + F

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

				HSC Code) 8, IMO Res. MSC.48(66)- (LSA Code) I, IV, IMO Res. MSC.97(73)- (2000 HSC Code) 8, IMO MSC/ Circ.811.		
A.1/1.13	Rigid liferafts	—	Reg. III/4, —	Reg. III/21, Reg. X/3.	—	IMO B + D B + E MSC.81(70), IMO MSC/ Circ.1006.

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

Status: This is the original version (as it was originally adopted).

				—	IMO MSC/ Circ.811.		
A.1/1.14	Automatically self-righting liferafts	—	Reg. III/4, X/3.	—	Reg. III/26, Reg. III/34, — IMO Res. MSC.36(63)- (1994 HSC Code) 8, — IMO Res. MSC 48(66)- (LSA Code) I, IV, IMO Res. MSC.97(73)- (2000 HSC Code) 8, — IMO MSC/ Circ.809, IMO MSC/ Circ.811.	IMO Res. MSC.81(70).	B + D B + E B + F
A.1/1.15	Canopied reversible liferafts	—	Reg. III/4, X/3.	—	Reg. III/26, Reg. III/34, — IMO Res. MSC.36(63)- (1994 HSC Code) 8, — IMO Res. MSC.48(66)- (LSA	IMO Res. MSC.81(70).	B + D B + E B + F

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

					Code) I, IV, IMO Res. MSC.97(73)- (2000 HSC Code) 8, IMO MSC/ Circ.809, IMO MSC/ Circ.811.		
A.1/1.16	Float-free arrangements for liferafts (hydrostatic release units)	—	Reg. III/4, —	Reg. III/13, —	Reg. III/13, —	IMO Res. B + D B + E B + F MSC.81(70).	
A.1/1.17	Lifeboats: (a) davit-launched lifeboats:	—	Reg. III/4, Reg. X/3.	—	Reg. III/21, Reg. III/31,	IMO Res. B + D B + F MSC.81(70),	

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

Status: This is the original version (as it was originally adopted).

		—	partially enclosed,	—	Reg. III/34,	—	IMO MSC/
		—	totally enclosed.	—	IMO Res.		Circ.1006.
(b)	free-fall lifeboats:	—			MSC.36(63)-(1994 HSC Code) 8,		
		—	totally enclosed.	—	IMO Res. MSC.48(66)-(LSA Code) I, IV, IMO Res. MSC.97(73)-(2000 HSC Code) 8.		
A.1/1.18	Rigid rescue boats	—	Reg. III/4, Reg. X/3.	—	Reg. III/21, Reg. III/31,—	IMO Res. MSC/	B + D B + F &I(70), Circ.1006.
		—		—	IMO Res. MSC.36(63)-(1994 HSC Code) 8,		
		—		—	IMO Res. MSC.48(66)-(LSA Code) I, V, IMO Res. MSC.97(73)-(2000 HSC Code) 8.		

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

A.1/1.19	Inflated rescue boats	—	Reg. III/4, Reg. X/3.	—	Reg. III/21, Reg. III/31, Reg. III/34, IMO Res. MSC HSC Code) 8, IMO Res. MSC Code) I, V, IMO Res. MSC HSC Code) 8.	—	IMO Res. MSC 81(70), ISO 15372 (2000).	B + D B + F
A.1/1.20	Fast rescue boats: (a) inflated, (b) rigid, (c) rigid-inflated.	—	Reg. III/4.	—	Reg. III/26, Reg. III/34, IMO Res. MSC Code) I, V, IMO MSC Circ. 1016, IMO MSC Circ. 1094.	—	IMO Res. MSC 81(70), IMO MSC Circ. 1006, ISO 15372 (2000).	B + D B + F
A.1/1.21	Launching appliances using falls (davits)	—	Reg. III/4, Reg. X/3.	—	Reg. III/23, Reg. III/33, Reg. III/34, IMO Res.	—	IMO Res. MSC 81(70).	B + D B + E B + F

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

Status: This is the original version (as it was originally adopted).

				MSC.36(63)- (1994 HSC Code) 8, IMO Res. MSC.48(66)- (LSA Code) I, VI, IMO Res. MSC.97(73)- (2000 HSC Code) 8.	
A.1/1.22	Float free launching appliances for survival craft			Moved to A.2/1.3	
A.1/1.23	Launching appliances for free-fall lifeboats	—	Reg. III/4, —	Reg. III/16, —	IMO B + D B + E Res. B + F MSC.81(70). — Reg. III/33, — Reg. III/34, — IMO Res. MSC.36(63)- (1994 HSC Code) 8, IMO Res. MSC.48(66)- (LSA Code) I, VI, IMO Res. MSC.97(73)- (2000 HSC

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

					Code) 8.		
A.1/1.24	Liferaft launching appliances (davits)	—	Reg. III/4, —	— Reg. X/3. —	Reg. III/12, Reg. III/16, Reg. III/34, IMO Res. MSC.36(63)- (1994 HSC Code) 8, IMO Res. MSC.48(66)- (LSA Code) I, VI, IMO Res. MSC.97(73)- (2000 HSC Code) 8.	IMO Res. MSC.81(70).	B + D B + E B + F G
A.1/1.25	Fast rescue boat launching appliances (davits)	—	Reg. III/4.	—	Reg. III/26, Reg. III/34, IMO Res. MSC.48(66)- (LSA Code) I, VI.	IMO Res. MSC.81(70).	B + D B + E B + F G
A.1/1.26	Release mechanism for: (a) lifeboats and rescue boats (launched by a fall)	—	Reg. III/4, —	— Reg. X/3. —	Reg. III/16, Reg. III/34, IMO Res. MSC.36(63)- (1994 HSC	IMO Res. MSC.81(70).	B + D B + E B + F G

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

Status: This is the original version (as it was originally adopted).

	(b) or falls), liferafts (launched by a fall or falls).	—	Code) 8, IMO Res. MSC.48(66)- (LSA Code) I, IV, VI ^a , IMO Res. MSC.97(73)- (2000 HSC Code) 8.			
A.1/1.27	Marine evacuation systems	— Reg. III/4, — Reg. X/3.	Reg. III/15, — Reg. III/26, — Reg. III/34, — IMO Res. MSC.36(63)- (1994 HSC Code) 8, — IMO Res. MSC.48(66)- (LSA Code) I, VI, IMO Res. MSC.97(73)- (2000 HSC Code) 8.	—	IMO Res. MSC.81(70).	B + D B + F G
A.1/1.28	Means of rescue	— Reg. III/4.	Reg. III/26, — Reg. III/34, — IMO Res.	—	IMO Res. MSC.81(70), IMO Res. MSC/Circ.810.	B + D B + F

^a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

				MSC.48(66)- (LSA Code) I, VI.		
A.1/1.29	Embarkation ladders	— Reg. III/4, — Reg. III/11, — Reg. X/3.	— III/11, — Reg. III/34,— — IMO Res.	Reg. IMO Res. MSC.36(63)- (1994 HSC Code), IMO Res. MSC.48(66)- (LSA Code), IMO Res. MSC.97(73)- (2000 HSC Code), IMO MSC.1/ Circ.1285.	IMO Res. MSC.81(70), ISO 5489 (2008).	B + D B + F B + F
A.1/1.30	Retro-reflective materials	— Reg. III/4, — Reg. X/3.	— III/34,— IMO Res.	Reg. IMO Res. MSC.36(63)- (1994 HSC Code) 8, IMO Res. MSC.48(66)- (LSA Code) I, IMO Res. MSC.97(73)- (2000 HSC	IMO Res. A.658(16).	B + D B + E B + F

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

Status: This is the original version (as it was originally adopted).

				Code) 8.		
A.1/1.31	Survival craft two-way VHF radio telephone apparatus	Moved to A.1/5.17 and A.1/5.18				
A.1/1.32	9 GHz SAR transponder (SART)	Moved to A.1/4.18				
A.1/1.33	Radar reflector for lifeboats and rescue boats (passive)	— Reg. III/4, — Reg. X/3.	— Reg. III/34, — IMO Res. MSC.36(63)- (1994 HSC Code) 8, IMO Res. MSC.48(66)- (LSA or Code) I, IV, V, IMO Res. MSC.97(73)- (2000 HSC Code) 8, IMO Res. or MSC.164(78).	— EN ISO 8729(B98), EN 60945 (2002) including IEC 60945 Corrigendum 1 (2008). EN ISO 8729(1998), IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008). ISO 8729-1 (2010), EN 60945 (2002) including IEC 60945 Corrigendum 1 (2008). or	B + D B + E B + E EN	

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

					—	ISO 8729-1 (2010), IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008).
A.1/1.34	Compass for lifeboats and rescue boats	Moved to A.1/4.23				
A.1/1.35	Portable fire-extinguishing equipment for lifeboats and rescue boats	Moved to A.1/3.38				
A.1/1.36	Lifeboat/ rescue boat propulsion engine	— Reg. III/4, — Reg. X/3.	— Reg. III/34, — IMO Res.	— MSC 48(66)- (LSA Code) IV, V.	IMO Res. MSC	B + D B + E B + F 81(70).
A.1/1.37	Rescue boat propulsion engine — outboard motor	— Reg. III/4, — Reg. X/3.	— Reg. III/34, — IMO Res.	— MSC 48(66)- (LSA Code) V.	IMO Res. MSC	B + D B + E B + F 81(70).
A.1/1.38	Searchlights for use in lifeboats and rescue boats	— Reg. III/4, — Reg. X/3.	— Reg. III/34, — IMO Res.	— MSC 36(63)- (1994 HSC Code) 8, IMO Res.	IMO Res. MSC	B + D B + E B + F 81(70).

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

Status: This is the original version (as it was originally adopted).

				(LSA Code) I, IV, V, IMO Res. MSC 97(73)- (2000 HSC Code) 8.		
A.1/1.39	Open reversible liferafts	— Reg. III/4, — Reg. X/3.	— MSC 36(63)- (1994 HSC Code) 8, Annex 10, 10, IMO Res. MSC 48(66)- (LSA Code) I, IMO Res. MSC 97(73)- (2000 HSC Code) 8, Annex 11.	IMO Res. MSC 36(63)- (1994 HSC Code) 8, Annex 10, IMO Res. MSC 97(73)- (2000 HSC Code) I, IMO Res. MSC 97(73)- (2000 HSC Code) 8, Annex 11.	IMO Res. MSC 36(63)- (1994 HSC Code) 8, Annex 10, IMO Res. MSC 97(73)- (2000 HSC Code) I, IMO Res. MSC 97(73)- (2000 HSC Code) 8, Annex 11.	B + D B + F B + D B + F
A.1/1.40	Mechanical pilot hoist	Moved to A.1/4.48				
A.1/1.41	Winches for survival craft and rescue boats (a) davit- launched lifeboats, (b) free- fall lifeboats, (c) liferafts,	— Reg. III/4, — Reg. X/3.	— III/16, — Reg. III/17, — Reg. III/23, — Reg. III/24, — Reg. III/34, — IMO Res.	Reg. III/16, — Reg. III/17, — Reg. III/23, — Reg. III/24, — Reg. III/34, — IMO Res.	IMO Res. MSC 81(70).	B + D B + E B + F

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

(d)	rescue boats,		MSC	36(63)- (1994			
(e)	fast rescue boats.	—	HSC	Code)	8,	IMO	
			Code)	8,	IMO	Res.	MSC
			Code)	8,	IMO	Res.	48(66)-
			Code)	8,	IMO	Res.	(LSA
			Code)	8,	IMO	Res.	Code)
			Code)	8,	IMO	Res.	I,
			Code)	8,	IMO	Res.	VI,
			Code)	8,	IMO	Res.	IMO
			Code)	8,	IMO	Res.	Res.
			Code)	8,	MSC	97(73)-	MSC
			Code)	8,	MSC	(2000	36(63)-
			Code)	8,	MSC	HSC	(1994
			Code)	8,	MSC	Code)	HSC
			Code)	8,	MSC	Code)	Code)
			Code)	8,	IMO	Res.	8,
			Code)	8,	IMO	Res.	IMO
			Code)	8,	IMO	Res.	Res.
			Code)	8,	IMO	Res.	MSC
			Code)	8,	IMO	Res.	48(66)-
			Code)	8,	IMO	Res.	(LSA
			Code)	8,	IMO	Res.	Code)
			Code)	8,	IMO	Res.	I,
			Code)	8,	IMO	Res.	V,
			Code)	8,	IMO	Res.	IMO
			Code)	8,	IMO	Res.	Res.
			Code)	8,	MSC	97(73)-	MSC
			Code)	8,	MSC	(2000	36(63)-
			Code)	8,	MSC	HSC	(1994
			Code)	8,	MSC	Code)	HSC
			Code)	8,	IMO	Code)	Code)
			Code)	8,	IMO	Code)	8,
A.1/1.42	Pilot ladder	Moved to A.1/4.49					
A.1/1.43 Refer to note (b) of this Annex A.1	Rigid/inflated rescue boats	—	Reg. III/4,	Reg. III/21,	IMO	B + D	
		—	Reg. X/3.	Reg. III/31,	Res.	B + F	
				Reg. III/31,	MSC	§1(70),	
				Reg. III/34,	IMO		
				Reg. III/34,	MSC		
				Reg. IMO	Circ.	1006,	
				Reg. IMO	ISO	15372	
				Reg. IMO	MSC	(2000).	
				Reg. IMO	36(63)-		
				Reg. IMO	(1994		
				Reg. IMO	HSC		
				Reg. IMO	Code)		
				Reg. IMO	8,		
				Reg. IMO	IMO		
				Reg. IMO	Res.		
				Reg. IMO	Res.		
				Reg. IMO	MSC		
				Reg. IMO	48(66)-		
				Reg. IMO	(LSA		
				Reg. IMO	Code)		
				Reg. IMO	I, V,		
				Reg. IMO	IMO		
				Reg. IMO	Res.		
				Reg. IMO	Res.		
				Reg. IMO	MSC		
				Reg. IMO	97(73)-		
				Reg. IMO	(2000		
				Reg. IMO	HSC		
				Reg. IMO	Code)		
				Reg. IMO	8.		

a Member States may apply Circular MSC.1/Circ.1393 of the IMO.

2. Marine pollution prevention

Status: This is the original version (as it was originally adopted).

No	Item designation	Regulation Marpol 73/78, as amended, where “type approval” is required	Regulations of Marpol 73/78, as amended, and the relevant resolutions and circulars of the IMO, as applicable	Testing standards	Modules for conformity assessment
1	2	3	4	5	6
A.1/2.1	Oil-filtering equipment (for an oil content of the effluent not exceeding 15 p.p.m.)	— Annex I, Reg. 14.	Annex I, Reg. 14, IMO MEPC.1/ Circ.643.	IMO Res. MEPC.108(49), IMO MEPC.1/ Circ.643.	B + D B + E B + F
A.1/2.2	Oil/water interface detectors	— Annex I, Reg. 32.	Annex I, Reg. 32.	IMO Res. MEPC.5(XIII).	B + D B + E B + F
A.1/2.3	Oil-content meters	— Annex I, Reg. 14.	Annex I, Reg. 14, IMO MEPC.1/ Circ.643.	IMO Res. MEPC.108(49), IMO MEPC.1/ Circ.643.	B + D B + E B + F
A.1/2.4	Process units intended for attachment to existing oily water separating equipment (for an oil content of the effluent not exceeding 15 p.p.m.)	Deliberately left blank			
A.1/2.5	Oil discharge monitoring and control system for oil tankers	— Annex I, Reg. 31.	Annex I, Reg. 31.	IMO Res. MEPC.108(49).	B + D B + E B + F

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

A.1/2.6	Sewage systems	—	Annex IV, Reg. 9.	Annex IV, Reg. 9.	IMO Res. MEPC.159(55).	B + D B + E B + F
A.1/2.7	Shipboard incinerators	—	Annex VI, Reg. 16.	Annex VI, Reg. 16.	IMO Res. MEPC.76(40).	B + D B + E B + F
A.1/2.8	On board NO _x analysers using the direct measurement and monitoring method of NO _x Technical Code 2008	—	IMO Res. MEPC.176(58) (Revised Marpol Annex VI, Reg. 13);	IMO — Marpol Annex VI, Reg. 13);	IMO Res. MEPC.177(58) HEC (NO _x Technical Code 2008) IMO or MEPC.4/ Circ.638.	B + D B + E G Technical Code 2008) EN 60945 (2002) including MEPC.177(58) Corrigendum (NO _x Technical Code 2008) 1 (2008). IMO Res. MEPC.177(58) — (NO _x Technical Code 2008) IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008).
A.1/2.9	Equipment using other technological methods to limit SO _x emissions	Moved to A.2/2.4				

Status: This is the original version (as it was originally adopted).

A.1/2.10 Refer to note (c) of this Annex A.1	On board exhaust gas cleaning systems	—	IMO Res. MEPC.176(58) (Revised Marpol Annex VI, Reg. 4), IMO Res. MEPC.184(59).	IMO Res. MEPC.176(58) (Revised Marpol Annex VI, Reg. 4).	IMO Res. MEPC.184(59).	B + D B + E B + F G
---	--	---	--	--	------------------------------	------------------------------

3. Fire protection equipment

No	Item designation	Regulation SOLAS 74, as amended, where “type approval” is required	Regulations of SOLAS 74, as amended, and the relevant resolutions and circulars of the IMO, as applicable	Testing standards	Modules for conformity assessment
1	2	3	4	5	6
A.1/3.1	Primary decks covering	— Reg. II-2/4, — Reg. II-2/6, — Reg. X/3.	Reg. II-2/4, Reg. II-2/6, IMO Res. MSC.36(63)-7, IMO Res. MSC.97(73)-7.	IMO Res. MSC.207(88)-(2010 FTP Code), IMO MSC/ Circ.1102.	B + D B + E B + F
A.1/3.2	Portable fire extinguishers	— Reg. II-2/10, — Reg. X/3,	Reg. II-2/4, Reg. II-2/10,	EN 3-7 (2004) including	B + D B + E B + F

marines.

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

		IMO	—	Reg.	Protective	A.1
		Res.	II-2/18,	II-2/18, Reg.	clothing for	B + D
		MSC 98(73)-	—	IMO	fire-fighting:	B + E
		(FSS	X/3,	Res. —	EN	B + F
		Code)	IMO	MSC 36(63)-	469	
		4.	Res.	(1994	(2005)	
		MSC 98(73)-	—	HSC	including	
		(FSS	X/3,	Code)	A1	
		Code)	IMO	7,	(2006)	
		3.	—	IMO	and	
				Res.	AC	
				MSC 97(73)-	(2006).	
				(2000	Protective	
				HSC	clothing	
				Code)	for fire-	
				7,	fighting —	
				Reflective		
A.1/3.3	Fire-fighter's outfit: protective clothing (close proximity clothing)	—	Reg.	—	Reg.	Protective
		—	II-2/10,	II-2/10, Reg.	clothing for	B + D
		—	Reg.	IMO	fire-fighting:	B + E
		—	X/3,	Res. —	EN	B + F
		—	IMO	MSC 36(63)-	469	
		—	Res.	(1994	(2005)	
		—	MSC 98(73)-	HSC	including	
			(FSS	Code)	A1	
			Code)	7,	(2006)	
			3.	IMO	and	

Status: This is the original version (as it was originally adopted).

			—	IMO Res. MSC (FSS Code) 3.	clothing for specialised fire-fighting: EN 1486 (2007). Protective clothing for fire-fighting — Protective clothing with a reflective outer surface: ISO 15538 (2001).	
A.1/3.4	Fire-fighter's outfit: boots	— Reg. II-2/10, — Reg. X/3, — IMO Res. MSC (FSS Code) 3.	— Reg. II-2/10, — IMO Res. MSC (FSS Code) 7, — IMO Res. MSC (FSS Code) 3.	— Reg. II-2/10, — IMO Res. MSC (FSS Code) 7, — IMO Res. MSC (FSS Code) 3.	EN 15090 (2006), HSC Code) 7, HSC Code) 7, HSC Code) 7,	B + D B + E B + F
A.1/3.5	Fire-fighter's outfit: gloves	— Reg. II-2/10, — Reg. X/3, — IMO Res. MSC (FSS Code) 3.	— Reg. II-2/10, — IMO Res. MSC (FSS Code) 7, — IMO Res. MSC (FSS Code) 3.	— Reg. II-2/10, — IMO Res. MSC (FSS Code) 7, — IMO Res. MSC (FSS Code) 3.	EN 659 (2003) including A1 (2008) and AC (2009).	B + D B + E B + F

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

				HSC Code) 7, IMO Res. MSC.98(73)- (FSS Code) 3.		
A.1/3.6	Fire-fighter's outfit: helmet	—	Reg. II-2/10, Reg. X/3, IMO	Reg. II-2/10, IMO Res. MSC.98(73)- (FSS Code) 3.	EN 443 (2008). HSC 7, IMO Res. MSC.97(73)- (2000 HSC Code) 7, IMO Res. MSC.98(73)- (FSS Code) 3.	B + D B + E B + F
A.1/3.7	Self-contained compressed-air-operated breathing apparatus <i>Note: For use in accidents involving dangerous goods a positive pressure type mask is required.</i>	—	Reg. II-2/10, Reg. X/3, IMO	Reg. II-2/10, IMO Res. MSC.98(73)- (FSS Code) 3.	EN 136 (1998) including AC (2003), EN 137 (2006). And where the apparatus use in (2000 accidents HSC with cargo: Code)— ISO 7, IMO Res. MSC.98(73)- (FSS	B + D B + E B + F

Status: This is the original version (as it was originally adopted).

				Code) 3. And where the apparatus is for use in accidents with cargo: — IMO Res. MSC 4(48)- (IBC Code) 14, — IMO Res. MSC 5(48)- (IGC Code) 14.		
A.1/3.8	Compressed air line breathing apparatus	— Reg. X/3. — IMO Res. MSC 36(63)- (1994 (1994 HSC Code) 7. <i>Note: This equipment is only for high- speed craft built under provisions of the 1994 HSC Code.</i>	—	IMO Res. MSC 36(63)- (1994 HSC Code) 7.	— EN 14593-1 (2005) B + F EN 14593-2 (2005) including AC (2005), — EN 14594 (2005) including AC (2005).	B + D B + E B + F
A.1/3.9	Sprinkler systems components for accommodation spaces, service spaces and control stations equivalent to that referred to in SOLAS 74 Reg. II-2/12 (limited to nozzles	— Reg. II-2/7, — Reg. II-2/10, — Reg. X/3, — IMO Res. MSC 98(73)- (FSS Code) 8.	— Reg. II-2/7, — Reg. II-2/9, — Reg. II-2/10, — IMO Res. MSC 36(63)- (1994 HSC Code) 7, — IMO Res. MSC 44(65),	—	IMO Res. A.800(19).	B + D B + E B + F

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

	and their performance). (Nozzles for fixed sprinkler systems, for high-speed craft (HSC) are included under this item)	—	IMO Res. MSC 97(73)-(2000 HSC Code) 7, — IMO Res. MSC 98(73)-(FSS Code) 8, — IMO MSC/ Circ.912.		
A.1/3.10	Nozzles for fixed pressure water spraying fire extinguishing systems for machinery spaces and cargo pump-rooms	— Reg. II-2/10, — Reg. X/3, — IMO Res. MSC 98(73)-(FSS Code) 7.	— Reg. II-2/10, — IMO Res. MSC 36(63)-(1994 HSC Code) 7, — IMO Res. MSC 97(73)-(2000 HSC Code) 7, — IMO Res. MSC 98(73)-(FSS Code) 7, — IMO MSC 1/ Circ.1313.	IMO MSC/ Circ.1165, Appendix A.	B + D B + E B + F
A.1/3.11	“A” and “B” class divisions fire integrity (a) “A” class divisions, (b) “B” class divisions.	“A” class: — Reg. II-2/3.2 “B” class: — Reg. II-2/3.4.	Reg. II-2/9, and, — Reg. II-2/3.2, — IMO MSC/ Circ. 1005 (for light	IMO Res. MSC 307(88)-(2010 FTP Code).	B + D B + E B + F

Status: This is the original version (as it was originally adopted).

				weight constructions). “B” class: — Reg. II-2/3.4.		
A.1/3.12	Devices to prevent the passage of flame into the cargo tanks in tankers	— Reg. II-2/4, — Reg. II-2/16.	Reg. II-2/4, Reg. II-2/16.	EN 12874 equipment (2001) other than ISO valves: 15364 (2007), IMO MSC/ Circ.677.	B + D B + E B + F	For valves: B + F
A.1/3.13	Non-combustible materials	— Reg. II-2/3, — Reg. X/3.	Reg. II-2/3, Reg. II-2/5, Reg. II-2/9, IMO Res. MSC.36(63)- (1994 HSC Code) 7, IMO Res. MSC.97(73)- (2000 HSC Code) 7.	IMO Res. MSC.307(88)- (2010 FTP Code).	B + D B + E B + F	
A.1/3.14	Materials other than steel for pipes penetrating “A” or “B” class division	Item included in A.1/3.26 and A.1/3.27				
A.1/3.15	Materials other than steel for pipes conveying oil or fuel oil (a) pipes and fittings,	— Reg. II-2/4, — Reg. X/3.	Reg. II-2/4, IMO Res. MSC.36(63)- (1994 Valves: HSC Code)	Pipes and fittings: IMO Res. A.753(18).	B + D B + E B + F	

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

	(b) valves, (c) flexible pipe (d) assemblies, metallic pipe components with resilient and elastomeric seals.	—	7, 10, IMO Res. MSC/ 7, 10, IMO MSC/ Circ.1120.	— Flexible pipe assemblies: (2000 — EN HSC ISO Code) 15540 (2001) — EN ISO 15541 (2001). Metallic pipe components with resilient and elastomeric seals: — ISO 19921 (2005), — ISO 19922 (2005).	ISO 10497 (2010).
A.1/3.16	Fire doors	—	Reg. II-2/9.	Reg. II-2/9.	— IMO Res. MSC/ B7(88)- (2010 FTP Code). IMO MSC.1/ Circ.1319.
A.1/3.17	Fire door control systems components.	— —	Reg. II-2/9, Reg. X/3.	Reg. II-2/9, IMO Res. MSC/ 97(73)- (2000 HSC Code) 7.	— IMO Res. MSC/ 307(88)- (2010 FTP Code).
A.1/3.18	Surface materials and floor coverings with low flame-spread characteristics	— — — — —	Reg. II-2/3, Reg. II-2/5, Reg. II-2/6, Reg. II-2/9,	Reg. II-2/3, Reg. II-2/5, Reg. II-2/6, Reg. II-2/9,	— IMO Res. MSC/ 307(88)- (2010 FTP Code).

Status: This is the original version (as it was originally adopted).

	(a) decorative veneers, (b) paint systems, (c) floor coverings, (d) pipe insulation covers, (e) adhesives used in the construction of “A”, “B” and “C” class divisions, (f) combustible ducts,	Reg. X/3.	—	IMO Res. MSC.36(63)-(1994) HSC Code) 7, IMO Res. MSC.97(73)-(2000) HSC Code) 7, IMO MSC/ Circ.1120.		
A.1/3.19	Draperys, curtains and other suspended textile materials and films	— Reg. II-2/3, — Reg. II-2/9, — Reg. X/3.	— Reg. II-2/3, — Reg. II-2/9, — IMO Res. MSC.36(63)-(1994) HSC Code) 7, IMO Res. MSC.97(73)-(2000) HSC Code) 7.	— Reg. II-2/3, — Reg. II-2/9, — IMO Res. MSC.36(63)-(1994) HSC Code) 7, IMO Res. MSC.97(73)-(2000) HSC Code) 7.	IMO Res. MSC.36(63)-(1994) HSC Code) 7, IMO Res. MSC.97(73)-(2000) HSC Code) 7.	B + D B + E MSC.36(63)-(2010) FTP Code), IMO MSC/ Circ.1102.
A.1/3.20	Upholstered furniture	— Reg. II-2/3, — Reg. II-2/5, — Reg. II-2/9, — Reg. X/3.	— Reg. II-2/3, — Reg. II-2/5, — Reg. II-2/9, — IMO Res. MSC.36(63)-(1994) HSC	— Reg. II-2/3, — Reg. II-2/5, — Reg. II-2/9, — IMO Res. MSC.36(63)-(1994) HSC	IMO Res. MSC.36(63)-(1994) HSC	B + D B + E MSC.36(63)-(2010) FTP Code), IMO Res. MSC/ Circ.1102.

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

				Code) 7, IMO Res. MSC.97(73)- (2000 HSC Code) 7.		
A.1/3.21	Bedding components	—	Reg. II-2/3, —	Reg. II-2/3, Reg. II-2/9, Reg. X/3.	IMO Res. MSC.307(88)- (2010 FTP Code), IMO MSC/ Circ.1102.	B + D B + E
A.1/3.22	Fire dampers	—	Reg. II-2/9.	Reg. II-2/9.	IMO Res. MSC.307(88)- (2010 FTP Code).	B + D B + E B + F
A.1/3.23	Non-combustible duct penetrations through “A” class divisions	Moved to A.1/3.26				
A.1/3.24	Electric cable transits through “A” class divisions	Moved to A.1/3.26(a)				
A.1/3.25	“A” and “B” class fire-proof	—	Reg. II-2/9.	Reg. II-2/9,	IMO Res. MSC.307(88)- (2010	B + D B + E B + F

Status: This is the original version (as it was originally adopted).

	windows and side scuttles	—	IMO MSC/Circ.1120.	FTP Code).
A.1/3.26	Penetrations through “A” class divisions (a) electric cable transits, (b) pipe, duct, trunk, etc. penetrations.	— Reg. II-2/9.—	Reg. II-2/9,— IMO MSC.1/Circ.1276.	IMO Res. MSC.307(88)-(2010 FTP Code).
A.1/3.27	Penetrations through “B” class divisions (a) electric cable transits, (b) pipe, duct, trunk, etc. penetrations.	— Reg. II-2/9.—	Reg. II-2/9.—	IMO Res. MSC.307(88)-(2010 FTP Code).
A.1/3.28	Sprinkler systems (limited to sprinkler heads). (Nozzles for fixed sprinkler systems, for high-speed craft (HSC) are included under this item)	— Reg. II-2/7,— — Reg. II-2/10,— — Reg. X/3.	Reg. II-2/7,— Reg. II-2/10, IMO — MSC.36(63)-(1994 HSC Code) 7, IMO Res. MSC.44(65), IMO Res. MSC.97(73)-(2000 HSC Code) 7, IMO Res. MSC.98(73)-(FSS	ISO 6182-1 (2004) B + F EN 12259-1 (1999) including A1 (2001), A2 (2004) and A3 (2006).

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

				Code) 8, IMO MSC/ Circ.912.		
A.1/3.29	Fire hoses	—	Reg. II-2/10, — Reg. X/3.	Reg. II-2/10, — IMO Res. — MSC.36(63)- (1994 HSC Code) — IMO Res. — MSC.97(73)- (2000 HSC Code) — 7.	EN 14540 (2004) including A.1 (2007).	B + D B + E B + F
A.1/3.30	Portable oxygen analysis and gas detection equipment	—	Reg. II-2/4, — Reg. VI/3.	Reg. II-2/4, — Reg. VI/3, — IMO Res. — MSC.98(73)- (FSS Code) — 15.	EN 60945 B + E (2002) including IEC 60945 Corrigendum 1 (2008) or IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 60092-504 (2001) including IEC 60092-504 Corrigendum 1 (2011), IEC 60533 (1999),	B + D B + E B + Fxxx

Status: This is the original version (as it was originally adopted).

			and as applicable to:
		(a)	Category 1: (safe area):
			— EN 50104 (2010),
			— EN 60079-29-1 (2007).
		(b)	Category 2: (explosive gas atmospheres):
			— EN 50104 (2010),
			— EN 60079-29-1 (2007),
			— EN 60079-0 (2009),
			— EN 60079-1 (2007) including IEC 60079-1 Corrigendum 1 (2008),
			— EN 60079-10-1 (2009),
			— EN 60079-11 (2007),
			— EN 60079-15 (2010),
			— EN 60079-26 (2007).
A.1/3.31	Nozzles for fixed sprinkler systems, for	Item deleted as it is covered by A.1/3.9 and A.1/3.28	

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

	high-speed craft (HSC)						
A.1/3.32	Fire restricting materials (except furniture) for high-speed craft	—	Reg. X/3.	—	IMO Res. MSC 36(63)- (1994 HSC Code) 7, IMO Res. MSC 97(73)- (2000 HSC Code) 7.	—	IMO Res. MSC 307(88)- (2010 FTP Code). B + D B + E B + F
A.1/3.33	Fire restricting materials for furniture for high-speed craft	—	Reg. X/3.	—	IMO Res. MSC 36(63)- (1994 HSC Code) 7, IMO Res. MSC 97(73)- (2000 HSC Code) 7, IMO MSC/ Circ.1102.	—	IMO Res. MSC 307(88)- (2010 FTP Code). B + D B + E B + F
A.1/3.34	Fire resisting divisions for high-speed craft	—	Reg. X/3.	—	IMO Res. MSC 36(63)- (1994 HSC Code) 7, IMO Res. MSC 97(73)- (2000 HSC Code) 7.	—	IMO Res. MSC 307(88)- (2010 FTP Code). B + D B + E B + F
A.1/3.35	Fire doors on high-speed craft	—	Reg. X/3.	—	IMO Res. MSC 36(63)- (1994	—	IMO Res. MSC 307(88)- B + D B + E B + F

Status: This is the original version (as it was originally adopted).

				HSC Code) 7, IMO Res. MSC.97(73)- (2000 HSC Code) 7.	(2010 FTP Code).	
A.1/3.36	Fire dampers on high-speed craft	—	Reg. X/3.	IMO Res. MSC.36(63)- (1994 HSC Code) 7, IMO Res. MSC.97(73)- (2000 HSC Code) 7, IMO MSC/ Circ.1102.	IMO Res. MSC.307(88)- (2010 FTP Code).	B + D B + E B + F
A.1/3.37	Penetrations through fire resisting divisions on high-speed craft (a) electric cable transits, (b) pipe, duct, trunk etc. penetrations.	—	Reg. X/3.	IMO Res. MSC.36(63)- (1994 HSC Code) 7, IMO Res. MSC.97(73)- (2000 HSC Code) 7.	IMO Res. MSC.307(88)- (2010 FTP Code).	B + D B + E B + F
A.1/3.38	Portable fire- extinguishing equipment for lifeboats and rescue boats	—	Reg. III/4,	Reg. III/34, 3-7	EN	B + D B + E
		—	Reg. X/3,	IMO Res.	(2004)	B + F including
		—	IMO Res. MSC.98(73)- (FSS Code) 4.	A.951(23), IMO Res. MSC.36(63)- (1994 HSC	A1 (2007), EN 3-8 (2006) including	

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

				Code) 8, IMO — Res. MSC.48(66)- (LSA Code) I, IV, V, IMO Res. MSC.97(73)- (2000 HSC Code),' IMO Res. MSC.98(73)- (FSS Code) 4, IMO MSC.1/ Circ.1313.	AC (2007), EN 3-9 (2006) including AC (2007), EN 3-10 (2009).	
A.1/3.39	Nozzles for equivalent water-mist fire extinguishing systems for machinery spaces and cargo pump rooms	— —	Reg. II-2/10, Reg. X/3.	Reg. II-2/10, IMO Res. MSC.36(63)- (1994 HSC Code) 7, IMO Res. MSC.97(73)- (2000 HSC Code) 7, IMO Res. MSC.98(73)- (FSS Code) 7, IMO MSC.1/ Circ.1313.	IMO MSC/ Circ.1165.	B + D B + E B + F

Status: This is the original version (as it was originally adopted).

A.1/3.40	Low-location lighting systems (components only)	—	Reg. II-2/13, IMO — Res. MSC (FSS Code) 11.	— II-2/13, IMO Res. or A.752(18), IMO Res. MSC (FSS Code) 11.	— II-2/13, IMO Res. or A.752(18), IMO Res. MSC (FSS Code) 11.	IMO Res. A.752(18)F ISO 15370 (2010).	B + D B + E
A.1/3.41	Emergency escape breathing devices (EEBD)	—	Reg. II-2/13. —	Reg. II-2/13, IMO Res. MSC (FSS Code) 3, IMO MSC Circ.849.	— Reg. II-2/13, IMO Res. MSC (FSS Code) 3, IMO MSC Circ.849.	ISO 23269 (2008) and alternatively: For self- contained open- circuit compressed air breathing apparatus with full mask or mouthed piece assembly for escape: EN 402(2003). For self- contained open- circuit compressed air breathing apparatus with a hood for escape: EN 1146(2005).	B + D B + E B + F

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

					For self-contained: closed-circuit compressed air breathing apparatus: EN 13794(2002).	
A.1/3.42	Inert gas systems components	—	Reg. II-2/4.	— Reg. II-2/4, — IMO Res. A.567(14), — IMO Res. MSC.98(73)-(FSS Code) 15, — IMO MSC/ Circ.353, — IMO MSC/ Circ.387, — IMO MSC/ Circ.485, — IMO MSC/ Circ.450 Rev.1, — IMO MSC/ Circ.731, — IMO MSC/ Circ.1120.	IMO MSC/ Circ.353, G.	B + D B + E B + F
A.1/3.43	Nozzles for deep fat cooking equipment fire extinguishing systems (automatic or manual type).	—	Reg. II-2/1,	Reg. II-2/1, — Reg. II-2/10, — Reg. X/3.	ISO 15371 (2009).	B + D B + E B + F

Status: This is the original version (as it was originally adopted).

				Code) 7.			
A.1/3.44	Fire-fighters outfit — lifeline	— Reg. II-2/10, — Reg. X/3, — IMO Res. MSC(73)- (FSS Code) 3.	— Reg. II-2/10, — IMO Res. MSC(1994) HSC — (1994) Code) 7, — IMO Res. MSC(97(73)- (2000) HSC Code) 7, — IMO Res. MSC(98(73)- (FSS Code) 3.	— Reg. II-2/10, — IMO Res. MSC(36(63)- (1994) HSC — (1994) Code) 7, — IMO Res. MSC(307(88)- (2010) FTP Code).	IMO Res. MSC(98(73)- (FSS Code) 3.	B + D B + E (FSS Code) 3, IMO Res. MSC(307(88)- (2010) FTP Code).	
A.1/3.45	Equivalent fixed gas fire extinguishing systems components (extinguishing medium, head valves and nozzles) for machinery spaces and cargo pump rooms	— Reg. II-2/10, — Reg. X/3, — IMO Res. MSC(98(73)- (FSS Code) 5.	— Reg. II-2/10, — IMO Res. MSC(36(63)- (1994) HSC — (1994) Code) 7, — IMO Res. MSC(97(73)- (2000) HSC Code) 7, — IMO Res. MSC(98(73)- (FSS Code) 5, — IMO Res. MSC(848, — IMO Res. MSC(1313,	IMO Res. MSC(848, — IMO Res. MSC(1313,	B + D B + E Circ. 848, F MSC(1/1317.		

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

				—	IMO MSC.1/ Circ.1316, IMO MSC.1/ Circ.1317.	
A.1/3.46	Equivalent fixed gas fire extinguishing systems for machinery spaces (aerosol systems)	—	Reg. II-2/10, Reg. X/3, IMO Res. MSC.98(73)- 5.	Reg. II-2/10, IMO Res. MSC.97(73)- 7, IMO Res. MSC.98(73)- 5, IMO MSC.1/ Circ.1270, IMO MSC.1/ Circ.1313.	IMO MSC.1/ Circ.1270 including Corrigendum 1.	B + D B + E B + F
A.1/3.47	Concentrate for fixed high expansion foam fire extinguishing systems for machinery spaces and cargo pump rooms. <i>Note:</i> The fixed high expansion foam fire extinguishing system (including those systems	—	Reg. II-2/10.	Reg. II-2/10, IMO Res. MSC.98(73)- 6.	IMO MSC.1/ Circ.670.	B + D B + E B + F

	which use inside air from their working spaces for their intended performance), for machinery spaces and cargo pump rooms must still be tested with the approved concentrate to the satisfaction of the administration.						
A.1/3.48	Fixed water-based local application fire-fighting systems components for use in category "A" machinery spaces (nozzles and performance tests).	— —	Reg. II-2/10, Reg. X/3.	— IMO Res. — IMO Res. —	Reg. II-2/10, IMO Res. MSC.36(63)- (1994 HSC Code) 7, IMO Res. MSC.97(73)- (2000 HSC Code) 7.	IMO MSC Circ.1387.	B + D B + E B + F
A.1/3.49	Nozzles for fixed water-based fire-fighting systems for ro-ro spaces and special category spaces equivalent to that referred to in resolution A.123(V)	— — —	Reg. II-2/19, Reg. II-2/20, Reg. X/3.	— Reg. II-2/20, IMO Res. — IMO Res. —	Reg. II-2/19, Reg. II-2/20, A.123(V), IMO Res. MSC.36(63)- (1994 HSC Code) 7, IMO Res. MSC.97(73)-	IMO MSC Circ.1272.	B + D B + E B + F

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

				(2000 HSC Code) 7.		
A.1/3.50	Protective clothing resistant to chemical attack		Moved to A.2/3.9			
A.1/3.51	Fixed fire detection and fire alarm systems components for control stations, service spaces, accommodation spaces, cabin balconies, machinery spaces and unattended machinery spaces	— Reg. II-2/7, — Reg. X/3, — IMO Res. MSC.98(73)-(FSS Code) 9.	Reg. II-2/7, indicating IMO equipment. Res. Electrical MSC.36(63)ations (1994 in ships: HSC — EN 54-2 7, (1997) IMO including Res. AC(1999) MSC.97(73)-(2000) and A1(2006). HSC Power supply Code) equipment: 7, — EN IMO 54-4 Res. (1997) MSC.98(73)-(FSS Code) 9, including AC(1999), A1(2002) and IMO A2(2006). MSC. Heat Circ. 142 detectors — IMO Point MSC. Detectors: Circ. 1343. EN 54-5 (2000) including A1(2002). Smoke detectors — Point detectors using scattered light, transmitted light or ionisation:		Control and indicating equipment. Electrical in ships: EN 54-2 (1997) including AC(1999) and A1(2006). Power supply equipment: EN 54-4 (1997) including AC(1999), A1(2002) and A2(2006). Heat detectors — Point detectors using scattered light, transmitted light or ionisation:	B + D B + E B + F

Status: This is the original version (as it was originally adopted).

			— EN 54-7 (2000) including A1(2002) and A2(2006). Flame detectors — Point detectors: — EN 54-10 (2002) including A1(2005). Manual call points: — EN 54-11 (2001) including A1(2005). Short circuit isolators: — EN 54-17 (2007) including AC(2007). Input/output devices: — EN 54-18 (2005) including AC(2007). Cables: — EN 60332-1-1 (2004). And, as applicable, electrical and electronic installations in ships: — IEC 60092-504 (2001) including IEC 60092-504
--	--	--	---

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

					Corrigendum 1 (2011), IEC 60533 (1999).	
A.1/3.52	Non-portable and transportable fire extinguishers	— Reg. II-2/10, — Reg. X/3.	— II-2/4, Reg. II-2/10 or Reg. X/3, IMO Res. MSC HSC Code) 7, IMO Res. MSC HSC Code) 7.	— Reg. II-2/7, — IMO X/3, Res. MSC HSC Code) 98(73)- 9.	EN 1866- (2007) B + E (2007) B + F ISO 11601 (2008). 36(63)- (1994) HSC Code) 7, IMO Res. MSC HSC Code) 7.	B + D
A.1/3.53	Fire alarm devices — Sounders	— Reg. II-2/7, — Reg. X/3, — IMO Res. MSC (FSS Code) 9.	— II-2/7,— IMO Res. MSC HSC Code) 7, IMO Res. MSC HSC Code) 7, IMO Res. MSC (FSS Code) 9, IMO MSC 1/ Circ.1313.	Sounders: EN 54-3 (2001) 36(63)- (1994) HSC and A1(2002) A2(2006), IEC 60092-504 (2001) 97(73)- (2000) HSC Code) 7, IMO Res. MSC HSC Code) 7, IMO Res. MSC (FSS Code) 9, IMO MSC 1/ Circ.1313.	B + D B + E B + F (2001) including A1(2002) and A2(2006), IEC 60092-504 (2001) including IEC 60092-504 Corrigendum 1 (2011), IEC 60533 (1999).	

Status: This is the original version (as it was originally adopted).

A.1/3.54	Fixed oxygen analysis and gas detection equipment	—	Reg. II-2/4, Reg. VI/3.	—	Reg. II-2/4, Reg. VI/3, IMO Res. MSC.98(73)-(FSS Code) 15.	—	EN 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 (2008) or IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 60092-504 (2001) including IEC 60092-504 Corrigendum 1 (2011), IEC 60533 (1999), and as applicable to: (a) Category 4: (safe area): — EN 50104 (2010). (b) Category 3: (explosive gas atmospheres): — EN 50104 (2010), — EN 60079-0 (2009),	B + D
----------	---	---	----------------------------	---	--	---	---	-------

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

					—	EN 60079-29-1 (2007).
A.1/3.55	Dual-purpose type nozzles (spray/jet type)	— Reg. II-2/10, — Reg. X/3.	Reg. II-2/10, IMO Res. MSC.36(63) combination (1994 branch pipes HSC PN 16: Code) — EN 7, IMO Res. MSC.97(73)-(2000) — HSC Code) 7.	Hand-held branch pipes for fire service use — Smooth bore jet and/or one fixed spray jet angle branch pipes PN 16: — EN 15182-1 (2007) including A1(2009), — EN 15182-2 (2007) including A1(2009). Hand-held branch pipes for fire service use — Smooth bore jet and/or one fixed spray jet angle branch pipes PN 16: — EN 15182-1 (2007) including A1(2009), — EN 15182-3 (2007) including A1(2009).	—	B + D B + E B + F
A.1/3.56	Fire hoses (reel type)	— Reg. II-2/10, — Reg. X/3.	Reg. II-2/10, IMO Res. MSC.36(63)-(1994 HSC Code) 7, IMO Res. MSC.97(73)-	EN 671-1 (2001) including AC (2002).	—	B + D B + E B + F

Status: This is the original version (as it was originally adopted).

				(2000 HSC Code) 7.		
A.1/3.57	Medium expansion foam fire extinguishing systems components — Fixed deck foam for tankers	— Reg. II-2/10.	—	Reg. II-2/10.8.1, IMO Res. MSC.98(73)-(FSS Code) 14, IMO MSC.1/ Circ.1239, IMO MSC.1/ Circ.1276.	IMO MSC/ Circ.798.	B + D B + E B + F
A.1/3.58	Fixed low expansion foam fire extinguishing systems components for machinery spaces and tanker deck protection.	— Reg. II-2/10.	—	Reg. II-2/10. IMO Res. MSC.98(73)-(FSS Code) 6, 14, IMO MSC.1/ Circ.1239, IMO MSC.1/ Circ.1276, IMO MSC.1/ Circ.1313.	IMO MSC/ Circ.1312.	B + D B + E B + F
A.1/3.59	Expansion foam for fixed fire extinguishing systems for chemical tankers	— Reg. II-2/1, — IMO Res. MSC.4(48)-(IBC Code),	—	IMO Res. MSC.4(48)-(IBC Code), IMO MSC/ Circ.553.	IMO MSC/ Circ.1312.	B + D B + E B + F
A.1/3.60	Nozzles for fixed pressure water-spraying fire-extinguishing systems	— Reg. II-2/10.	—	Reg. II-2/10. IMO Res. MSC.98(73)-(FSS	IMO MSC/ Circ.1268.	B + D B + E B + F

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

	for cabin balconies		—	Code) 7, IMO MSC.1/ Circ.1313.		
A.1/3.61	Inside air high expansion foam systems for the protection of machinery spaces and cargo pump rooms <i>Note:</i> Inside air high expansion foam systems for the protection of machinery spaces and cargo pump rooms shall be tested with the approved concentrate to the satisfaction of the administration.	—	Reg. II-2/10.	Reg. II-2/10.	IMO MSC Circ.1271.	B + D B + E B + F
A.1/3.62 Refer to note (c) of this Annex A.1	Dry chemical powder extinguishing systems	—	Reg. II-2/1.	Reg. II-2/1, International Code for the Construction and Equipment of Ships Carrying Liquefied Gases in Bulk; Chapter 11.	IMO MSC Circ.1315.	B + D B + E B + F

Status: This is the original version (as it was originally adopted).

A.1/3.63 Ex. A.2/3.15	Sample extraction smoke detection systems components	— Reg. II-2/7, — Reg. II-2/19, — Reg. II-2/20.	— Reg. II-2/7, — Reg. II-2/19, — Reg. II-2/20,	IMO Res. MSC 98(73) - (FSS Code) 10, IMO and for: Res. Control and MSC 98/17/EC (FSS equipment. Code) Electrical 10. installations in ships:	— EN 54-2 (1997) including AC(1999) and A1(2006). Power supply equipment: — EN 54-4 (1997) including AC(1999), A1(2002) and A2(2006). Aspiring smoke detectors: — EN 54-20 (2006) including AC(2008). And, as applicable, electrical and electronic installations in ships: — IEC 60092-504 (2001) including IEC 60092-504 Corrigendum 1 (2011),	B + D B + E
--------------------------	--	--	--	--	--	-------------

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

					— IEC 60533 (1999). And, as applicable for explosive atmospheres: — EN 60079-0 (2009).	
A.1/3.64 Ex. A.2/3.25	“C” class divisions	— Reg. II-2/3.	— Reg. II-2/3.	— IMO Res. MSC.307(88)-(2010) FTP Code).		B + D B + E B + F
A.1/3.65 (New item)	Fixed hydrocarbon gas detection system	— Reg. II-2/4.	— Reg. II-2/4, IMO Res. MSC.98(73)-(FSS Code) — 16, IMO MSC.1/ Circ.1370.	— 98(73)- (2007), IEC 60092-504 (2001) including IEC 60092-504 Corrigendum 1 (2011), IEC 60533 (1999), EN/ IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008).	IMO Res. MSC.1370,F Circ.1370, EN IEC 60092-504 (2001) including IEC 60092-504 Corrigendum 1 (2011), IEC 60533 (1999), EN/ IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008).	B + D B + E B + F
A.1/3.66 (New item)	Evacuation guidance systems used as an alternative to low-location	— Reg. II-2/13.	— Reg. II-2/13, IMO MSC.1/ Circ.1168.	— IMO Res. MSC.1168.		B + D B + E B + F

lighting systems				
------------------	--	--	--	--

4. Navigation equipment

Notes applicable to Section 4: Navigation equipment.

Column 5:

IEC 61162 series refer to the following reference standards for Maritime navigation and radiocommunication equipment and systems — Digital interfaces:

- (a) IEC 61162-1 ed4.0 (2010-11) — Part 1: Single talker and multiple listeners
- (b) IEC 61162-2 ed1.0 (1998-09) — Part 2: Single talker and multiple listeners, high-speed transmission
- (c) IEC 61162-3 ed1.1 Consol. with am1 (2010-11) — Part 3: Serial data instrument network
 - IEC 61162-3 ed1.0 (2008-05) — Part 3: Serial data instrument network
 - IEC 61162-3-am1 ed1.0 (2010-06) Amendment 1 — Part 3: Serial data instrument network
- (d) IEC 61162-400 ed1.0 (2001-11) — Part 400: Multiple talkers and multiple listeners — Ship systems interconnection — Introduction and general principles
 - IEC 61162-401 ed1.0 (2001-11) — Part 401: Multiple talkers and multiple listeners — Ship systems interconnection — Application profile
 - IEC 61162-402 ed1.0 (2005-09) — Part 402: Multiple talkers and multiple listeners — Ship systems interconnection — Documentation and test requirements
 - IEC 61162-410 ed1.0 (2001-11) — Part 410: Multiple talkers and multiple listeners — Ship systems interconnection — Transport profile requirements and basic transport profile
 - IEC 61162-420 ed1.0 (2001-11) — Part 420: Multiple talkers and multiple listeners — Ship systems interconnection — Companion standard requirements and basic companion standards
 - IEC 61162-450 ed1.0 (2011-06) — Part 450: Multiple talkers and multiple listeners — Ethernet interconnection

EN 61162 series refer to the following reference standards for Maritime navigation and radiocommunication equipment and systems — Digital interfaces:

- (a) EN 61162-1 (2011) — Part 1: Single talker and multiple listeners
- (b) EN 61162-2 (1998) — Part 2: Single talker and multiple listeners, high-speed transmission
- (c) EN 61162-3 (2008) — Part 3: Serial data instrument network
 - EN 61162-3-am1 (2010) Amendment 1 — Part 3: Serial data instrument network
- (d) EN 61162-400 (2002) — Part 400: Multiple talkers and multiple listeners — Ship systems interconnection — Introduction and general principles

- EN 61162-401 (2002) — Part 401: Multiple talkers and multiple listeners — Ship systems interconnection — Application profile
- EN 61162-402 (2005) — Part 402: Multiple talkers and multiple listeners — Ship systems interconnection — Documentation and test requirements
- EN 61162-410 (2002) — Part 410: Multiple talkers and multiple listeners — Ship systems interconnection — Transport profile requirements and basic transport profile
- EN 61162-420 (2002) — Part 420: Multiple talkers and multiple listeners — Ship systems interconnection — Companion standard requirements and basic companion standards
- EN 61162-450 (2011) — Part 450: Multiple talkers and multiple listeners — Ethernet interconnection

No	Item designation	Regulation SOLAS 74, as amended, where “type approval” is required	Regulations of SOLAS 74, as amended, and the relevant resolutions and circulars of the IMO, as applicable	Testing standards	Modules for conformity assessment
1	2	3	4	5	6
A.1/4.1	Magnetic compass (a) Class A for ships, (b) Class B for lifeboats and rescue boats.	— Reg. V/18	— Reg. V/19, — IMO Res. A.382(X), — IMO Res. A.694(17).	ISO 1069 (1973) B + F ISO 25862 (2009), EN 60945 (2002) including IEC 60945 Corrigendum 1 (2008). or — ISO 1069 (1973), — ISO 25862 (2009), IEC 60945	B + D B + E G

Status: This is the original version (as it was originally adopted).

					(2002) including IEC 60945 Corrigendum 1 (2008).
A.1/4.2	Transmitting heading device THD (magnetic method)	— Reg. V/18, — Reg. V/19, — Reg. X/3, — IMO Res. MSC.36(63)- (1994 (1994 HSC HSC Code) Code) 13, 13, — IMO Res. MSC.97(73)- (2000 (2000 HSC HSC Code) Code) 13, 13. — IMO Res. MSC.191(79). — IMO Res. MSC.191(79). — IMO Res. MSC.191(79). — IEC 60945 — ISO 22090-2 — EN 61162 series; — EN 62288 (2008). — IEC 60945 — ISO 22090-2 (2004), including Corrigendum 2005, — EN 62288 (2008). — IEC 60945 — ISO 22090-2 (2004), including Corrigendum 2005, — IEC 62288 Ed.1.0(2008).	EN 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 (2008), — EN 61162 — ISO 22090-2 (2004), including Corrigendum 2005, — EN 62288 (2008). — IEC 60945 — ISO 22090-2 (2004), including Corrigendum 2005, — IEC 62288 Ed.1.0(2008).	B + D	

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

A.1/4.3	Gyro compass	—	Reg. V/18	—	Reg. V/19, IMO Res. A.424(XI), IMO Res. A.694(17), IMO Res. MSC.191(79).	—	EN ISO 8728 (1998)G EN 60945 (2002) including IEC 60945 Corrigendum 1 (2008), EN 61162 series, EN 62288 (2008). or ISO 8728 (1997), IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, IEC 62288 Ed.1.0(2008).	B + D B + E B + F G
A.1/4.4	Radar equipment	Moved to A.1/4.34, A.1/4.35 and A.1/4.36						
A.1/4.5	Automatic radar plotting aid (ARPA)	Moved to A.1/4.34						
A.1/4.6	Echo-sounding equipment	—	Reg. V/18	—	Reg. V/19, IMO Res. A.224(VII), IMO Res. MSC.36(63)-(1994)	—	EN ISO 9875 (2001)G including ISO Technical Corrigendum A.694(17),	B + D B + E B + F G

Status: This is the original version (as it was originally adopted).

		HSC — Code) 13, IMO Res. MSC 97(73)- (2000 HSC — Code) 13.	IMO Res. MSC 36(63)- (1994 HSC Code) 13, IMO Res. MSC 74(69)	1: 2006, EN (2002) including IEC 60945 Corrigendum 1 (2008), EN 61162 series, EN 62288 (2008). ISO 9875 (2000) MSC 191(79). including ISO Technical Corrigendum 1: 2006, IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, IEC 62288 Ed.1.0(2008).	
A.1/4.7	Speed and distance measuring equipment (SDME)	— Reg. V/18, — Reg. X/3, — IMO Res. MSC (1994 HSC —	Reg. V/19, — IMO Res. A.694(17), IMO Res. MSC 36(63)- (1994 HSC —	— 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 (2008), EN 61162 series, IEC 62288 Ed.1.0(2008).	EN B + D 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 (2008), B + D 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 (2008), EN 61162 series, IEC 62288 Ed.1.0(2008).

marines.

Document Generated: 2023-08-19

Sto

Status: This is the original version (as it was originally adopted).

Status: This is the original version (as it was originally adopted).

				Code)	(2002)	
			—	13,	including	
				IMO	IEC	
				Res.	60945	
				MSC.191(79).	Corrigendum	
					1	
					(2008),	
					IEC	
					61162	
					series,	
					ISO	
					20672	
					(2007),	
					IEC	
					62288	
					Ed.1.0(2008).	
A.1/4.10	Direction finder	Deliberately left blank				
A.1/4.11	Loran-C equipment	—	Reg. V/18,	Reg. V/19,	EN 60945	B + D
		—	Reg. —	IMO	B + E	
			X/3,	Res.	(2002) B + F	
			—	IMO	including	
				A.694(17),	IEC	
				Res. —	60945	
			MSC.36(63)-	Res.	Corrigendum	
			(1994	A.818(19),	1	
			HSC —	IMO	(2008),	
			Code)	Res. —	EN	
			13,	MSC.36(63)-	61075	
			IMO	(1994	(1993),	
			Res.	HSC —	EN	
			MSC.97(73)-	Code)	61162	
			(2000	13,	series,	
			HSC —	IMO —	EN	
			Code)	Res.	62288	
			13.	MSC.97(73)-	(2008).	
			(2000 or	HSC —	IEC	
				Code)	60945	
				13,	(2002)	
				IMO	including	
				Res.	IEC	
			MSC.191(79).	60945	Corrigendum	
					1	
					(2008),	
					IEC	
					61075	
					(1991),	
					IEC	
					61162	
					series,	

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

						IEC 62288 Ed.1.0(2008).
A.1/4.12	Chayka equipment	— Reg. V/18, — Reg. X/3, — IMO MSC.36(63)-(1994) HSC Code) 13, — IMO Res. MSC.97(73)-(2000) HSC Code) 13, — IMO Res. or MSC.97(73)-(2000) HSC Code) 13, — IMO Res. MSC.191(79). 1	— Reg. V/19, — IMO Res. A.694(17), — IMO Res. — IMO Res. MSC.36(63)-(1994) HSC Code) 13, — IMO Res. MSC.97(73)-(2000) HSC Code) 13, — IMO Res. MSC.191(79). 1	— Reg. V/19, — IMO Res. A.694(17), — IMO Res. — IMO Res. MSC.36(63)-(1994) HSC Code) 13, — IMO Res. MSC.97(73)-(2000) HSC Code) 13, — IMO Res. MSC.191(79). 1	— EN 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 EN 61075 (1993), EN 61162 series, EN 62288 (2008). IEC 60945 (2002) including IEC 60945 Corrigendum 1 EN 61075 (1991), EN 61162 series, IEC 62288	EN 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 EN 61075 (1993), EN 61162 series, IEC 62288 (2008). IEC 60945 (2002) including IEC 60945 Corrigendum 1 EN 61075 (1991), EN 61162 series, IEC 62288 (2008). Ed.1.0(2008).
A.1/4.13	Decca navigator equipment	Deliberately left blank				
A.1/4.14	GPS equipment	— Reg. V/18, — Reg. X/3, — IMO MSC.36(63)-(1994)	— Reg. V/19, — IMO Res. A.694(17), — IMO Res. MSC.36(63)-	— Reg. V/19, — IMO Res. A.694(17), — IMO Res. MSC.36(63)-	— EN 60945B + E (2002)B + F including IEC 60945 Corrigendum	

Status: This is the original version (as it was originally adopted).

		HSC Code) 13, IMO Res. MSC (2000 HSC Code) 13.	(1994 HSC Code),— IMO Res. 97(73)- (2000 HSC Code) —	1 (2008), EN (2003), EN 61108-1 61162 series, EN 62288 Res. MSC. b12(73), IMO — Res. MSC.191(79).	1 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61108-1 (2003), IEC 61162 series, IEC 62288 Ed.1.0(2008).
A.1/4.15	GLONASS equipment	— Reg. V/18, — Reg. X/3, — IMO Res. MSC (1994 HSC Code) 13, IMO Res. MSC (2000 HSC Code) 13.	— — IMO Res. A.694(17), IMO Res. 36(63)- (1994 HSC Code) 13, IMO Res. 97(73)- (2000 HSC Code) 13.	Reg. V/19, — IMO Res. — Res. 36(63)- (1994 HSC Code) — IMO Res. 97(73)- (2000 HSC Code) — 13, IMO Res. 97(73)- (2000 HSC Code) — 13,	EN 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 (2008), EN 61108-2 (1998), EN 61162 series, EN 62288 (2008). or IEC 60945 MSC.113(73), (2002)

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

			—	IMO Res. MSC.191(79).	including IEC 60945 Corrigendum 1 (2008), IEC 61108-2 (1998), IEC 61162 series, IEC 62288 Ed.1.0(2008).
A.1/4.16	Heading control system (HCS)	—	Reg. V/18.	— IMO Res. A.342(IX), — IMO Res. A.694(17), — IMO Res. MSC.64(67) Annex 3, — IMO Res. MSC.191(79).	ISO 11674B + E (2006)B + F EN G 60945 (2002) including IEC 60945 Corrigendum 1 (2008), EN 61162 series, EN 62288 (2008). or — ISO 11674 (2006), — IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, IEC 62288 Ed.1.0(2008).

Status: This is the original version (as it was originally adopted).

A.1/4.17	Mechanical pilot hoist	Moved to A.1/1.40					
A.1/4.18	9 GHz SAR transponder (SART)	—	Reg.	—	Reg.	—	EN B + D
		III/4,		III/6,		60945	B + E
		—	Reg.	—	Reg.	(2002)	B + F
		IV/14,		IV/7,		including	
		—	Reg.	—	IMO	IEC	
		V/18,		Res.		60945	
		—	Reg.	A.530(13),		Corrigendum	
		X/3,	—	IMO		1	
		—	IMO	Res.		(2008),	
			Res.	A.802(49),	EN		
		MSC.36(63)-		IMO		61097-1	
		(1994)		Res.		(2007).	
		HSC		A.694(17),			
		Code)	—	IMO	—	IEC	
		13,		Res.		60945	
		—	IMO	MSC.36(63)-	(2002)	including	
			Res.	(1994)			
		MSC.97(73)-		HSC	IEC		
		(2000)		Code)	60945		
		HSC		8,	Corrigendum		
		Code)		14,	1		
		13.	—	IMO	(2008),		
				Res.	IEC		
				MSC.97(73)-	61097-1		
				(2000)	(2007).		
		HSC		Code)			
		Code)		8,			
				14,			
				ITU-			
				R			
				M.628-3(11/93).			
A.1/4.19	Radar equipment for high-speed craft	Moved to A.1/4.37					
A.1/4.20	Rudder angle indicator	—	Reg.	—	Reg.	—	EN B + D
		V/18,		V/19,		60945	B + E
		—	Reg.	—	IMO	(2002)	B + F
		X/3,		Res.		including	
		—	IMO	A.694(17),	IEC		
			Res.	IMO	60945		
		MSC.36(63)-		Res.	Corrigendum		
		(1994)		MSC.36(63)-	1		
		HSC		(1994)	(2008),		
		Code)		HSC	EN		
		13,		Code)	61162		
		IMO		13,	series,		
				Res.			

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

		MSC	97(73)- (2000 HSC Code) 13.	IMO	— Res. MSC (2000 — HSC Code) 13, or IMO Res. MSC	ISO 20673 (2007), EN 62288 (2008). IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, ISO 20673 (2007), IEC 62288 Ed.1.0(2008).
A.1/4.21	Propeller revolution indicator	—	Reg. V/18, — Reg. X/3, — IMO Res. MSC	Reg. V/19, — IMO Res. A.694(17), IMO Res. 36(63)- (1994 HSC Code) 13, IMO Res. MSC	— IMO Res. 36(63)- (1994 HSC Code) 13, IMO Res. 97(73)- (2000 HSC Code) 13.	EN B + D 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 (2008), EN 61162 series, ISO 22554 (2007), EN 62288 (2008). IEC 60945 MSC

Status: This is the original version (as it was originally adopted).

						1 (2008), IEC 61162 series, ISO 22554 (2007), IEC 62288 Ed.1.0(2008).
A.1/4.22	Pitch indicator	—	Reg. V/18, — Reg. X/3, — IMO Res. MSC.36(63)- (1994 HSC Code) 13, IMO Res. MSC.97(73)- (2000 HSC Code) 13.	— V/19, — IMO Res. A.694(17), IMO Res. MSC.36(63)- (1994 HSC Code) 13, IMO Res. MSC.97(73)- (2000 HSC Code) 13. — IMO Res. MSC.191(79).	— EN 60945 B + E (2002) B + F including IEC 60945 Corrigendum 1 (2008), EN 61162 series, ISO 22555 (2007), EN 62288 (2008). — IEC 60945 including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, ISO 22555 (2007), IEC 62288 Ed.1.0(2008).	B + D B + E G
A.1/4.23	Compass for lifeboats and rescue boats	—	Reg. III/4, — Reg. X/3,	— III/34, — IMO Res.	— ISO 25862 (2009)	B + D B + E B + F G

		—	IMO Res. MSC	36(63)- (1994 HSC Code) — 13, IMO Res. MSC	48(66)- (LSA Code) IV, V, IMO Res. MSC	36(63)- (1994 HSC Code) 8, 13, IMO Res. MSC	97(73)- (2000 HSC Code) 8, 13.	
A.1/4.24	Automatic radar plotting aid (ARPA) for high-speed craft				Moved to A.1/4.37			
A.1/4.25	Automatic tracking aid (ATA)				Moved to A.1/4.35			
A.1/4.26	Automatic tracking aid (ATA) for high-speed craft				Moved to A.1/4.38			
A.1/4.27	Electronic plotting aid (EPA)				Moved to A.1/4.36			
A.1/4.28	Integrated bridge system				Moved to A.2/4.30			
A.1/4.29	Voyage data recorder (VDR)	—	Reg. V/18,	—	Reg. V/20,	—	EN 60945B + E	B + D
		—	Reg. V/20,	—	IMO Res.	—	(2002) including	B + F
		—	Reg. X/3,	A.694 (17),		—	IEC 60945	
		—	IMO Res.	IMO Res.		—	Corrigendum 1	
			MSC	36(63)- (1994 HSC	A.861 (20),		(2008),	

		Code) — 13, IMO Res. MSC 97(73)- (2000 HSC Code) — 13.	IMO Res. MSC 36(63)- (1994 HSC Code) 13, IMO Res. MSC 97(73)- (2000 HSC Code) 13, IMO Res. MSC 191(79)	— series, EN 61162 EN 61996-1 (2008), EN 62288 (2008). IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, IEC 61996-1 (2007-11), IEC 62288 Ed.1.0(2008).	EN 61162	
A.1/4.30	Electronic chart display and information system (ECDIS) with backup, and raster chart display system (RCDS)	— Reg. V/18, — Reg. X/3, — IMO Res. — MSC 36(63)- (1994 HSC Code) 13, IMO Res. — MSC 97(73)- (2000 HSC Code) 13. —	Reg. V/19, IMO Res. A.694(17), IMO Res. MSC 36(63)- (1994 HSC Code) 13, 13 IMO Res. MSC 97(73)- (2000 HSC Code) 13. 13, or IMO Res. MSC 191(79),	— including IEC 60945 Corrigendum 1 (2008), EN 61162 series, EN 61174 (2008), EN 62288 (2008). IEC 60945 (2002) including IEC	EN 60945 B + D B + E B + F including B + F EN 61162 B + E EN 61996-1 (2007-11), IEC 62288 Ed.1.0(2008).	B + D B + E B + F including B + F EN 61162 B + E EN 61996-1 (2007-11), IEC 62288 Ed.1.0(2008).

				—	IMO Res. MSC.232(82), SN.1/ Circ.266.	60945 Corrigendum 1 (2008), IEC 61162 series, IEC 61174 (2008), IEC 62288 Ed.1.0(2008).
A.1/4.31	Gyro compass for high-speed craft	—	Reg. X/3, IMO Res. MSC.36(63)- (1994) HSC Code) 13,	—	IMO A.694(17), IMO Res. A.821(19), IMO Res. MSC.36(63)- (1994) IMO Res. MSC.97(73)- (2000) HSC Code) 13.	— ISO 16328B + E (2001) B + F EN G 60945 (2002) including IEC 60945 Corrigendum 1 (2008), EN 61162 series, EN 62288 (2008). Code) or 13, — ISO IMO 16328 Res. (2001), MSC.191(79). IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008),

Status: This is the original version (as it was originally adopted).

					—	IEC 61162 series, IEC 62288 Ed.1.0(2008).
A.1/4.32	Universal automatic identification system equipment (AIS)	— Reg. V/18, — Reg. X/3, — IMO Res. MSC.36(63)-(1994) HSC Code) 13, — IMO Res. MSC.97(73)-(2000) HSC Code) — 13. — MSC.97(73)-(2000) HSC Code) 13, — IMO Res. MSC.191(79), ITU-R M.1371-4(2010) Note: ITU-R M.1371-4(2010) shall only be applicable in accordance with requirements of IMO Res.MSC.74(69).	Reg. V/19, — IMO Res. A.694(17), — IMO Res. (2008), EN	—	EN 60945B + E (2002) B + F including IEC 60945 Corrigendum 1 EN 61162 series, IEC 62288 (2008). EN 61993-2 (2001), EN 62288 (2008). IEC 60945 (2002) including IEC 60945 Corrigendum 1 EN 61993-2 (2001), EN 62288 Ed.1.0(2008).	B + D
A.1/4.33	Track control system (working at ship's speed from minimum manoeuvring	— Reg. V/18	Reg. V/19, — IMO Res. A.694(17),	—	EN 60945B + E (2002) B + F including IEC 60945 Corrigendum	B + D

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

	speed up to 30 knots)		—	IMO Res. MSC.74(69), IMO Res. MSC.191(79).	1 (2008), EN 61162 series, EN 62065 (2002), EN 62288 (2008). or — IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, IEC 62065 (2002), IEC 62288 Ed.1.0(2008).	
A.1/4.34	Radar equipment CAT 1	—	Reg. V/18	— IMO Res. A.278(VIII), IMO Res. A.694(17), IMO Res. A.823(19), IMO Res. MSC.191(79), IMO Res. MSC.192(79), ITU- R M.1177-3(06/03	EN 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 (2008), EN 61162 series, EN 62288 (2008), EN 62388 (2008). IEC 60945 (2002)	

Status: This is the original version (as it was originally adopted).

						including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, IEC 62288 Ed.1.0(2008). IEC 62388 Ed.1.0(2007).
A.1/4.35	Radar equipment CAT 2	—	Reg. V/18	—	EN 60945B + E (2002) B + F including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, IEC 62288 Ed.1.0(2008). IEC 62388 Ed.1.0(2007). or IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, IEC 62288 Ed.1.0(2008). IEC 62388 Ed.1.0(2007).	

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

A.1/4.36	Radar equipment CAT 3	—	Reg. V/18	—	Reg. V/19, IMO Res. A.278(VIII), IMO Res. A.694(17), IMO Res. MSC.191(79), IMO Res. MSC.192(79), ITU-R M.1177-3(06/03)	—	EN 60945B + E (2002) B + F including IEC 60945 Corrigendum 1 EN 61162 series, EN 62288 (2008), EN 62388 (2008). or IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, IEC 62288 Ed.1.0(2008). IEC 62388 Ed.1.0(2007).	B + D
A.1/4.37	Radar equipment for high-speed craft applications (CAT 1H and CAT 2H)	—	Reg. X/3,	—	IMO Res. A.278(VIII), IMO Res. IEC 60945B + E (2002) B + F including IEC 60945 Corrigendum 1 EN 61162 series, EN 62288 (2008),	—	EN 60945B + E (2002) B + F including IEC 60945 Corrigendum 1 EN 61162 series, EN 62288 (2008),	B + D

Status: This is the original version (as it was originally adopted).

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

					—	IEC 61162 series, IEC 62288 Ed.1.0(2008), IEC 62388 Ed.1.0(2007).
A.1/4.39	Radar reflector — passive type	—	Reg. V/18, —	Reg. V/19, IMO	ISO 8729-1 (2010) B + F	B + D
		—	Reg. X/3, —	Res. —	EN G	
		—	IMO	MSC.36(63)- Res. MSC.36(63)- (1994)	60945 (2002)	
				HSC	including IEC	
				13,	60945	
				Code) —	IMO	Corrigendum
				13,	Res. 1	
		—	IMO	MSC.97(73)- Res. MSC.97(73)- (2000)	97(73)- (2008).	
				HSC	ISO 8729-1	
				13,	(2010),	
				Code) —	IMO	IEC
				13.	Res. 60945	
				MSC.164(78).	164(78). (2002)	
					including IEC 60945	
					Corrigendum	
					1	
					(2008).	
A.1/4.40	Heading control system for high-speed craft	—	Reg. X/3, IMO	IMO — A.694(17),	ISO 16329-1 (2003) B + F	B + D
		—	Res. —	IMO —	EN G	
		—	MSC.36(63)- (1994)	Res. 60945		
				A.822(19),	(2002)	
				HSC —	including	
				Code) Res.	IEC	
				13,	60945	
		—	IMO	MSC.36(63)- (1994)	Corrigendum	
				Res. HSC 1		
				MSC.97(73)- (2000)	(2008),	
				13,	EN	
				HSC —	61162	
				Code) Res.	series,	
				13.	MSC.97(73)- (2000)	EN 62288
				HSC	(2008).	

Status: This is the original version (as it was originally adopted).

				Code) or 13, — IMO Res. MSC.191(79).	ISO 16329 (2003), IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, IEC 62288 Ed.1.0(2008).
A.1/4.41	Transmitting heading device THD (GNSS method)	— Reg. V/18, — Reg. X/3, — IMO Res. MSC.36(63)- (1994 HSC Code) 13, IMO Res. MSC.97(73)- (2000 HSC Code) 13.	— V/19, — IMO Res. A.694(17), IMO Res. MSC.36(63)- (1994 HSC Code) 13, IMO Res. MSC.97(73)- (2000 HSC Code) 13.	— IMO Res. MSC.97(73)- (2000 HSC Code) 13, IMO Res. MSC.116(73), IMO Res. or MSC.191(79).	B + D 22090B + E B + F including ISO Corrigendum 1 (2005), EN 60945 (2002) including IEC 60945 Corrigendum 1 (2008), EN 61162 series, EN 62288 (2008). ISO 22090-3 (2004) including ISO Corrigendum 1 (2005),

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

						—	IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, IEC 62288 Ed.1.0(2008).
A.1/4.42	Searchlight for high- speed craft	—	Reg. X/3, IMO Res. MSC (1994 HSC Code) 13, IMO Res. MSC (2000 HSC Code) 13.	—	IMO A.694(17), IMO Res. MSC (1994 HSC Code) 13, IMO Res. MSC (2000 HSC Code) 13.	—	ISO 17884B + E (2004)B + F EN G 60945 (2002) including IEC 60945 Corrigendum 1 (2008). ISO 17884 (2004), IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008).
A.1/4.43	Night vision equipment for high-speed craft	—	Reg. X/3, IMO Res. MSC (1994 HSC Code) 13, IMO Res. MSC (2000 HSC Code) 13.	—	IMO A.694(17), IMO Res. MSC (1994 HSC Code) 13, IMO Res. MSC (2000 HSC Code) 13.	—	ISO 16273B + E (2003)B + F EN G 60945 (2002) including IEC 60945 Corrigendum 1 (2008).

Status: This is the original version (as it was originally adopted).

		(2000 — HSC Code) 13.	IMO Res. MSC 97(73)- (2000 HSC Code) 13.	or ISO 16273 (2003), IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008).	
A.1/4.44	Differential beacon receiver for DGPS and DGLONASS equipment	— Reg. V/18, — Reg. X/3, — IMO Res. MSC 36(63)- (1994 HSC Code) 13, — IMO Res. MSC 97(73)- (2000 HSC Code) 13.	Reg. V/19, IMO Res. A.694 (17), IMO Res. 36(63)- (1994 HSC Code) 13, IMO Res. 97(73)- (2000 HSC Code) 13.	— EN 60945 B + E (2002) B + F including IEC 60945 Corrigendum 1 (2008), IEC 61108-4 (2004), EN 61162 series. IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61108-4 (2004), IEC 61162 series.	B + D
A.1/4.45	Chart facilities for shipborne radar	Item deleted, as it is covered by A.1/4.38			
A.1/4.46	Transmitting heading device THD	— Reg. V/18,	Reg. V/19,	ISO 22090 B + E (2002) B + F	B + D

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

	(gyroscopic method)	—	Reg. X/3,	—	IMO Res.	including Corr. 1	Eng
		—	IMO	A.694	—	(2005),	
		—	Res.	(17), —	—	EN	
		MSC.36(63)-	IMO	—	60945		
		(1994)	Res.	—	(2002)		
		HSC	MSC.36(63)-	including			
		Code)	(1994)	IEC			
		13,	HSC	60945			
		IMO	Code)	Corrigendum			
		Res.	13,	1			
		MSC.97(73)-	IMO	(2008),			
		(2000)	Res.	EN			
		HSC	MSC.97(73)-	61162			
		Code)	(2000)	series,			
		13.	HSC	EN			
		Code)	—	62288			
		13,	—	(2008).			
		IMO	or				
		Res.	—	ISO			
		MSC.116(73),	—	22090-1			
		IMO	(2002)				
		Res.	including				
		MSC.191(79).	Corrig. 1				
		—	(2005),				
		—	IEC				
		60945	(2002)				
		—	including				
		IEC	IEC				
		60945	60945				
		—	Corrigendum				
		1	1				
		—	(2008),				
		IEC	IEC				
		61162	61162				
		—	series,				
		IEC	IEC				
		62288	62288				
		—	Ed.1.0(2008).				
A.1./4.47	Simplified voyage data recorder (S-VDR)	—	Reg. V/20,	—	EN	B + D	
		—	IMO	—	60945	B + E	
		—	Res.	—	(2002)	B + F	
		—	A.694(17),	including			
		—	IMO	IEC			
		—	60945				
		—	Res.	Corrigendum			
		—	MSC.163(78),	1			
		—	IMO	(2008),			
		—	Res.	EN			
		—	MSC.191(79).	61162			
		—	—	series,			

Status: This is the original version (as it was originally adopted).

					— EN 61996-2 (2008), EN 62288 (2008). or — IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, IEC 61996-2 (2007), IEC 62288 Ed.1.0(2008).
A.1/4.48	Mechanical pilot hoist	Deliberately left blank (as IMO Res. MSC.308(88), in force on 1 July 2012, quotes: "Mechanical pilot hoists shall not be used")			
A.1/4.49	Pilot ladder	— Reg. V/23, — Reg. X/3.	— Reg. V/23, — IMO Res. A.889(21), — IMO MSC/Circ.773.	— IMO Res. A.889(21), — ISO 799 (2004).	B + D B + E A.889(21)F G
A.1/4.50	DGPS equipment	— Reg. V/18, — Reg. X/3, — IMO Res. MSC.36(63)- (1994) HSC Code) 13, IMO Res. MSC.97(73)- (2000)	— Reg. V/19, — IMO Res. A.694 (17), IMO Res. MSC.36(63)- (1994) HSC Code) 13, IMO Res. IMO Res.	— EN 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 (2008), EN 61108-1 (2003), EN 61108-4 (2004),	B + D B + E B + F G

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

		HSC Code) 13.	MSC (2000 HSC Code)— 13, IMO Res. or MSC. IMO Res. MSC. 1	97(73)- series, EN 61162 EN 62288 (2008). IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61108-1 (2003), IEC 61108-4 (2004), IEC 61162 series, IEC 62288 Ed.1.0(2008).	EN	
A.1/4.51	DGLONASS equipment	—	Reg. V/18, —	Reg. V/19, —	EN	B + D

Status: This is the original version (as it was originally adopted).

			—	IMO Res. MSC.114(73), IMO Res. MSC.191(79).	(2002) including IEC 60945 Corrigendum 1 (2008), IEC 61108-2 (1998), IEC 61108-4 (2004), IEC 61162 series, IEC 62288 Ed.1.0(2008).	
A.1/4.52 Refer to note (b) of this Annex A.1	Daylight signalling lamp	—	Reg. V/18, Reg. X/3, IMO Res. MSC.36(63)- (1994 HSC Code), IMO Res. MSC.97(73)- (2000 HSC Code).	Reg. V/19, IMO Res. A.694(17), IMO Res. MSC.36(63)- (1994 HSC Code), IMO Res. MSC.95(72), IMO Res. MSC.97(73)- (2000 HSC Code).	EN 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 (2008), ISO 25861 (2007). IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), ISO 25861 (2007).	B + D B + E B + F
A.1/4.53 Refer to note (c) of this Annex A.1	Radar target enhancer	—	Reg. V/18, Reg. X/3, IMO Res. MSC.36(63)- (1994	IMO Res. A.694(17), IMO Res. MSC.36(63)- (1994 HSC	ISO 8729-B + E (2009)B + F G 60945 (2002) including IEC	B + D B + E B + F G

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

		HSC Code) 13, IMO Res. MSC 97(73)- (2000 (2000 HSC Code) 13, — IMO Res. MSC 164(78), — IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008).	Code) 13, IMO Res. MSC 97(73)- (2000 HSC Code) 13, — IMO Res. MSC 164(78), — IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008).	60945 Corrigendum 1 (2008).
A.1/4.54 Refer to note (c) of this Annex A.1	Bearing device	— Reg. V/18.	Reg. V/19.	— ISO 25862B + E (2009)B + F EN G 60945 (2002) including IEC 60945 Corrigendum 1 (2008). or — ISO 25862 (2009), IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008),.
A.1/4.55 Refer to note (c) of this Annex A.1	AIS SART equipment	— Reg. III/4, — Reg. IV/14.	Reg. III/6, — Reg. IV/7, — IMO Res. MSC 246(83), — IMO Res. MSC 247(83),	— EN B + D 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 (2008),

Status: This is the original version (as it was originally adopted).

			—	IMO	—	EN	
			—	Res.	—	61097-14	
			—	MSC	256(84),	(2010),	
			—	ITU-	—	EN	
			—	R	—	61162	
			—	M.1371-4(2010)	series.		
			—	or			
			—	IEC			
			—	60945			
			—	(2002)			
			—	including			
			—	IEC			
			—	60945			
			—	Corrigendum			
			—	1			
			—	(2008),			
			—	IEC			
			—	61097-14			
			—	(2010),			
			—	IEC			
			—	61162			
			—	series.			
A.1/4.56 Refer to note (c) of this Annex A.1	Galileo receiver	—	Reg. V/18,	Reg. V/19,	—	EN	B + D
		—	Reg.	IMO	—	60945	B + E
		—	X/3,	Res.	—	(2002)	B + F
		—	IMO	A.694(17),	—	IEC	
		—	Res.	IMO	—	60945	
		—	MSC	36(63)-	Res.	Corrigendum	
		—	(1994	(1994	A.813(19),	1	
		—	HSC	—	IMO	(2008),	
		—	Code)	—	Res.	EN	
		—	13,	MSC	36(63)-	61108-3	
		—	IMO	(1994	(1994	(2010),	
		—	Res.	HSC	—	EN	
		—	MSC	97(73)-	Code)	61162	
		—	(2000	(2000	13,	series,	
		—	HSC	—	IMO	EN	
		—	Code)	—	Res.	62288	
		—	13.	MSC	97(73)-	(2008).	
		—	(2000	or	HSC	IEC	
		—	Code)		—	60945	
		—	13,		(2002)		
		—	IMO		including		
		—	Res.		IEC		
		—	MSC	191(79),	60945		
		—	IMO		Corrigendum		
		—	Res.		1		
		—	MSC	233(82).	(2008),		

5. Radiocommunication equipment

Notes applicable to Section 5: Radiocommunication equipment.

Column 5: In case of conflicting requirements between IMO MSC/Circ.862 and the product testing standards, the IMO MSC/Circ.862 requirements shall take precedence.

Column 5:

IEC 61162 series refer to the following reference standards for Maritime navigation and radiocommunication equipment and systems — Digital interfaces:

- (a) IEC 61162-1 ed4.0 (2010-11) — Part 1: Single talker and multiple listeners
- (b) IEC 61162-2 ed1.0 (1998-09) — Part 2: Single talker and multiple listeners, high-speed transmission
- (c) IEC 61162-3 ed1.1 Consol. with am1 (2010-11) — Part 3: Serial data instrument network
 - IEC 61162-3 ed1.0 (2008-05) — Part 3: Serial data instrument network
 - IEC 61162-3-am1 ed1.0 (2010-06) Amendment 1 — Part 3: Serial data instrument network
- (d) IEC 61162-400 ed1.0 (2001-11) — Part 400: Multiple talkers and multiple listeners — Ship systems interconnection — Introduction and general principles
 - IEC 61162-401 ed1.0 (2001-11) — Part 401: Multiple talkers and multiple listeners — Ship systems interconnection — Application profile
 - IEC 61162-402 ed1.0 (2005-09) — Part 402: Multiple talkers and multiple listeners — Ship systems interconnection — Documentation and test requirements
 - IEC 61162-410 ed1.0 (2001-11) — Part 410: Multiple talkers and multiple listeners — Ship systems interconnection — Transport profile requirements and basic transport profile
 - IEC 61162-420 ed1.0 (2001-11) — Part 420: Multiple talkers and multiple listeners — Ship systems interconnection — Companion standard requirements and basic companion standards
 - IEC 61162-450 ed1.0 (2011-06) — Part 450: Multiple talkers and multiple listeners — Ethernet interconnection

EN 61162 series refer to the following reference standards for Maritime navigation and radiocommunication equipment and systems — Digital interfaces:

- (a) EN 61162-1 (2011) — Part 1: Single talker and multiple listeners
- (b) EN 61162-2 (1998) — Part 2: Single talker and multiple listeners, high-speed transmission
- (c) EN 61162-3 (2008) — Part 3: Serial data instrument network
 - EN 61162-3-am1 (2010) Amendment 1 — Part 3: Serial data instrument network
- (d) EN 61162-400 (2002) — Part 400: Multiple talkers and multiple listeners — Ship systems interconnection — Introduction and general principles
 - EN 61162-401 (2002) — Part 401: Multiple talkers and multiple listeners — Ship systems interconnection — Application profile
 - EN 61162-402 (2005) — Part 402: Multiple talkers and multiple listeners — Ship systems interconnection — Documentation and test requirements

- EN 61162-410 (2002) — Part 410: Multiple talkers and multiple listeners — Ship systems interconnection — Transport profile requirements and basic transport profile
- EN 61162-420 (2002) — Part 420: Multiple talkers and multiple listeners — Ship systems interconnection — Companion standard requirements and basic companion standards
- EN 61162-450 (2011) — Part 450: Multiple talkers and multiple listeners — Ethernet interconnection

No	Item designation	Regulation SOLAS 74, as amended, where “type approval” is required	Regulations of SOLAS 74, as amended, and the relevant resolutions and circulars of the IMO, as applicable	Testing standards	Modules for conformity assessment
1	2	3	4	5	6
A.1/5.1	VHF radio capable of transmitting and receiving DSC and radiotelephony	— Reg. IV/14, — Reg. X/3, — IMO Res. MSC.36(63)-14, — IMO Res. MSC.97(73)-14.	— Reg. IV/7, — Reg. X/3, — IMO Res. A.385(X), IMO Res. A.524(13), IMO Res. A.694(17), IMO Res. A.803(19), IMO Res. MSC.36(63)-(1994) HSC Code) — 14, — IMO Res. MSC.97(73)-(2000) HSC Code) — 14. —	— Circ.862+ F EN 60945 (2002) including IEC 60945 Corrigendum 1 EN 61162 series, ETSI EN 300 338-1 V1.3.1 (2010-02), ETSI EN 300 338-2 V1.3.1 (2010-02), ETSI EN	IMO B + D MSC/B + E Circ.862+ F EN 60945 (2002) including IEC 60945 Corrigendum 1 EN 61162 series, ETSI EN 300 338-1 V1.3.1 (2010-02), ETSI EN 300 338-2 V1.3.1 (2010-02), ETSI EN

Status: This is the original version (as it was originally adopted).

				Code)	301	
				14,	843-2	
			—	IMO	V1.2.1	
				MSC/	(2004-06),	
				Circ.862,	ETSI	
			—	IMO	EN	
				Comsar	301	
				Circ.32,	925	
			—	ITU-	V1.3.1	
				R	(2010-09).	
				M.489&2		
				(10/95),	IMO	
			—	ITU-	MSC/	
				R	Circ.862,	
				M.493-43	IEC	
				(10/09),	60945	
			—	ITU-	(2002)	
				R	including	
				M.541-9	IEC	
				(05/04),	60945	
			—	ITU-	Corrigendum	
				R	1	
				M.689-2	(2008),	
				(09/94),	IEC	
					61097-3	
					(1994),	
					IEC	
					61097-7	
					(1996),	
					IEC	
					61162	
					series.	
A.1/5.2	VHF DSC watchkeeping receiver	—	Reg.	—	Reg.	—
		IV/14,	IV/7,		EN	B + D
		—	Reg.	Reg.	60945	B + E
		X/3,	X/3,			(2002)
		—	IMO	IMO		B + F
		Res.	Res.			including
		MSC36(63)-	A.694(17),			IEC
		(1994)	IMO			60945
		—	HSC	Res.		
			Code)	A.803(19),		(2008),
			14,	IMO		EN
		—	IMO	Res.		61162
			Res.	MSC36(63)-		series,
				(1994)		ETSI
				HSC		
				Code)		
				14,		338-1
				IMO		V1.3.1
				Res.		(2010-02),
				MSC97(73)-		ETSI
				EN		

marie...

Document Generated: 2023-08-19

Statement

Status: This is the original version (as it was originally adopted).

Status: This is the original version (as it was originally adopted).

			Code) 14.	(2000 HSC Code) 14, IMO or Res. — MSC 148(77), IMO Comsar Circ.32, ITU-R M.540-2 (06/90), ITU-R M.625-3 (10/95).	301 843-4 V1.2.1 (2004-06). IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61097-6 (2005-12).	
A.1/5.4	EGC receiver	—	Reg. IV/14, Reg. X/3, IMO — Res. MSC 36(63)- (1994) — HSC Code) 14, — IMO Res. MSC 97(73)- (2000) — HSC Code) 14.	Reg. IV/7, Reg. X/3, IMO Res. A.570(14), IMO Res. A.664(16), IMO Res. A.694(17), IMO Res. MSC 36(63)- (1994) — HSC Code) 14, — IMO Res. MSC 97(73)- (2000) — HSC Code) 14, — IMO Res. MSC 97(73)- (2000) — HSC Code) 14, — IMO Comsar Circ.32.	EN 60945B + E (2002) B + F including IEC 60945 Corrigendum 1 (2008), ETSI ETS 300 460 Ed.1 (1996-05), ETSI ETS 300 460/ A1 (1997-11), ETSI EN 300 829 V1.1.1 (1998-03), ETSI EN 301 843-1 V1.2.1 (2004-06).	B + D

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

					—	IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61097-4 (2007).
A.1/5.5	HF marine safety information (MSI) equipment (HF NBDP receiver)	—	Reg. IV/14, —	Reg. IV/7, Reg. X/3, IMO Res. MSC 36(63)- (1994— HSC Code) 14, IMO Res. MSC 97(73)- (2000 HSC Code) 14	—	EN 60945B + D B + E (2002)B + F including IEC 60945 Corrigendum 1 (2008), EN 61162 series, ETSI ETS 300 067 Ed.1 (1990-11), ETSI ETS 300 067/ A1 Ed.1 (1993-10). IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, ETSI ETS

Status: This is the original version (as it was originally adopted).

				M.492-6 (10/95), ITU-R M.540-2 (06/90), ITU-R M.625-3 (10/95), ITU-R M.688 (06/90).	300 067 Ed.1 (1990-11), ETSI ETS 300 067/ A1 Ed.1 (1993-10).	
A.1/5.6	406 MHz EPIRB (Cospas-Sarsat)	—	Reg. IV/14, Reg. X/3, IMO — Res. MSC 36(63)- (1994) HSC Code) 14, IMO Res. MSC 97(73)- (2000) HSC Code) 14.	Reg. IV/7, Reg. X/3, IMO Res. 36(63)- (1994) IMO Res. A.694(17), IMO Res. A.696(+7), IMO Res. MSC 36(63)- (1994 or HSC Code) 14, IMO Res. MSC 97(73)- (2000) HSC Code) 14, IMO MSC/ Circ.862, IMO Res. MSC 97(73)- (2000) HSC Code) 14, IMO MSC/ Circ.862, IMO Comsar Circ.32 ITU- R	IMO MSC/B + E Circ.862+ F EN 60945 (2002) including IEC 60945 Corrigendum 1 ETSI EN 300 066 V 1.3.1 (2001-01). IMO MSC/ Circ.862, IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61097-2 (2008). IMO MSC/ Circ. 862 is	B + D B + E F EN 60945 (2002) including IEC 60945 Corrigendum 1 ETSI EN 300 066 V 1.3.1 (2001-01). IMO MSC/ Circ.862, IEC 60945 Corrigendum 1 (2008), IEC 61097-2 (2008). IMO MSC/ Circ. 862 is

Status: This is the original version (as it was originally adopted).

			—	ITU-R M.541-9 (05/04).	—	ETSI EN 301 843-5 V1.1.1 (2004-06). or — IMO MSC/Circ.862, — IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), — IEC 61097-3 (1994), — IEC 61097-9 (1997), — IEC 61162 series.
A.1/5.11	MF DSC watchkeeping receiver	—	Reg. IV/14, — Reg. X/3, — IMO Res. MSC 36(63)- (1994) HSC Code) 14, — IMO Res. MSC 97(73)- (2000) HSC Code) 14.	Reg. IV/9, — Reg. IV/10, — Reg. IMO Res. A.694(17), IMO — Res. A.804(19), IMO — Res. MSC 36(63)- (1994) HSC Code) 14, — IMO Res. MSC 97(73)- (2000) HSC Code) 14.	—	EN 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 (2008), EN 61162 series, ETSI EN 300 338-1 V1.3.1 (2010-02), ETSI EN 300 338-2 V1.3.1 (2010-02),

marie...

Document Generated: 2023-08-19

Statement

Status: This is the original version (as it was originally adopted).

			Code) —	—	ETSI
			14,	EN	
		—	IMO	301	
			Comsar	033	
			Circ.32,	V1.2.1	
		—	ITU-	(2005-12),	
			R —	ETSI	
			M.493-13	EN	
			(10/09),	301	
		—	ITU-	843-5	
			R	V1.1.1	
			M.541-9	(2004-06).	
			(05/04)r		
		—	ITU- —	IEC	
			R	60945	
			M.1173	(2002)	
			(10/95).	including	
				IEC	
				60945	
				Corrigendum	
				1	
				(2008),	
				IEC	
				61097-3	
				(1994),	
				IEC	
				61097-8	
				(1998),	
				IEC	
				61162	
				series.	
A.1/5.12	Inmarsat-B SES	—	Reg. —	Reg. —	IMO B + D
			IV/14,	IV/10,	MSC/B + E
		—	Reg. —	Reg. —	Circ B + F
			X/3,	X/3,	862,
		—	IMO —	IMO —	EN
			Res.	Res.	60945
			MSC 36(63)-	A.570(14),	(2002)
			(1994) —	IMO	including
			HSC	Res.	IEC
			Code)	A.694(17),	60945
			14,	IMO	Corrigendum
		—	IMO	Res.	1
			Res.	A.808(19),	(2008).
			MSC 97(73)-	IMO or	
			(2000)	Res. —	IMO
			HSC	MSC 36(63)-	MSC/
			Code)	(1994	Circ
			14.	HSC	862,
			Code)	—	IEC
			14,	60945	
				(2002)	

Status: This is the original version (as it was originally adopted).

				IMO Res. MSC 97(73)-(2000) HSC Code) 14, IMO MSC/ Circ.862, IMO Comsar Circ.32.	including IEC 60945 Corrigendum 1 (2008).
A.1/5.13	Inmarsat-C SES	— Reg. IV/14, — Reg. X/3, — IMO Res. MSC 36(63)-(1994) — HSC Code) 14, — IMO Res. MSC 97(73)-(2000) — HSC Code) 14.	— Reg. IV/10, — Reg. X/3, — IMO Res. A.570(14), IMO Res. A.664 (16), (applicable only — if the Inmarsat C SES comprises EGC functions), IMO Res. A.694(17), IMO Res. A.807(19), IMO Res. MSC 36(63)-(1994) — HSC Code) 14, — IMO Res. MSC 97(73)-(2000) — HSC	— Reg. IV/10, — Reg. X/3, — IMO Res. A.570(14), IMO Res. A.664 (16), (applicable only — if the Inmarsat C SES comprises EGC functions), IMO Res. A.694(17), IMO Res. A.807(19), IMO Res. MSC 36(63)-(1994) — HSC Code) 14, — IMO Res. MSC 97(73)-(2000) — HSC	IMO B + D MSC/B + E Circ.862+ F EN 60945 (2002) including IEC 60945 Corrigendum 1 (2008), EN 61162 series, ETSI ETS 300 460 Ed.1 (1996-05), ETSI ETS 300 460/ A1 (1997-11), ETSI EN 300 829 V1.1.1 (1998-03), ETSI EN 301 843-1 V1.2.1 (2004-06).

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

				Code) or 14, —	IEC 60945	
			—	IMO	(2002)	
			—	MSC/	including	
			—	Circ.862,		
			—	IMO	IEC	
			—	Comsar	60945	
			—	Circ.32.	Corrigendum	
				1		
					(2008),	
				—	IEC	
				—	61097-4	
				—	(2007),	
				—	IEC	
				—	61162	
					series.	
A.1/5.14	MF/HF radio capable of transmitting and receiving DSC, NBDP and radiotelephony <i>Note: In line with IMO and ITU decisions, the requirements for two-tone alarm generator and transmission on A3H are no longer applicable in testing standards.</i>	—	Reg. IV/14, —	Reg. IV/10, Reg. X/3, IMO Res. MSC HSC Code) 14, IMO Res. MSC HSC HSC Code) 14. —	IMO MSC/B + E Circ.862+ F EN 60945 (2002) A.694(17), IMO Res. A.806(19), IMO 1 Res. MSC (1994 (2000 HSC Code) 14, IMO Res. MSC (2000 HSC Code) 14, IMO Res. MSC (2000 HSC Code) 14, IMO Res. MSC Circ.862, IMO Comsar Circ.32, ITU- R M.476-5 (10/95), ITU- R	B + D B + E including IEC 60945 Corrigendum 1 (2008), EN 61162 series, ETSI ETS 300 067 Ed.1 (1990-11), ETSI ETS 300 067/ A1 Ed.1 (1993-10), ETSI EN 300 338-1 V1.3.1 (2010-02), ETSI EN

Status: This is the original version (as it was originally adopted).

				M.491-1 (07/86), ITU-R M.492-6 (10/95), ITU-R M.493-13 (10/09), ITU-R M.541-9 (05/04), ITU-R M.625eB (10/95), ITU-R M.1173- (10/95).	300 338-2 V1.3.1 (2010-02), ETSI ETS 300 373-1 V1.3.1 (2011-01), ETSI EN 301 843-5 V1.1.1 (2004-06). IMO MSC/ Circ.862, IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61097-3 (1994), IEC 61097-9 (1997), IEC 61162 series.	
A.1/5.15	MF/HF DSC scanning watchkeeping receiver	—	Reg. IV/14, Reg. X/3, IMO Res. MSC 36(63)- (1994— HSC Code) 14, IMO Res. MSC	— — — — — A.694(17), IMO Res. A.806(49), IMO Res. MSC 36(63)- (1994	EN 60945B + E (2002)B + F including IEC 60945 Corrigendum 1 (2008), EN 61162 series, ETSI EN	B + D B + E B + F

marie...

Document Generated: 2023-08-19

Sta

Status: This is the original version (as it was originally adopted).

		(2000 HSC Code) 14. —	HSC Code) 14, IMO Res. MSC 97(73)- (2000 HSC Code) 14, IMO Comsar Circ.32, ITU- R M.493-13 (10/09), ITU- R M.541-9 (05/04). — or — IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61097-3 (1994), IEC 61097-8 (1998), IEC 61162 series.	300 338-1 V1.3.1 (2010-02), ETSI EN 300 338-2 V1.3.1 (2010-02), ETSI EN 301 033 V1.3.1 (2010-09), ETSI EN 301 843-5 V1.1.1 (2004-06).		
A.1/5.16	Aeronautical two-way VHF radio telephone apparatus	Moved to A.2/5.8				
A.1/5.17	Portable survival craft two- way VHF radiotelephone apparatus	— IV/14, Reg. X/3, IMO —	Reg. III/6, IMO Res. A.694(17), Res.	— — — — —	EN 60945B + E (2002B + F including IEC 60945	B + D B + E B + F

Status: This is the original version (as it was originally adopted).

		MSC 36(63)- (1994) HSC Code) — 14, IMO Res. MSC 97(73)- (2000) HSC Code) — 14.	IMO Res. A.809(19), IMO Res. MSC 36(63)- (1994) HSC Code) — 8, 14, IMO Res. MSC 97(73)- (2000) HSC Code) — 8, 14, IMO Res. MSC 149(77), ITU- R M.489-2 (10/95) —	Corrigendum 1 (2008), ETSI EN 300 225 V1.4.1 (2004-12), ETSI EN 301 843-2 V1.2.1 (2004-06). IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61097-12 (1996).	
A.1/5.18	Fixed survival craft two-way VHF radiotelephone apparatus	— Reg. IV/14, — Reg. X/3, — IMO Res. — MSC 36(63)- (1994) HSC Code) — 14, IMO Res. MSC 97(73)- (2000) HSC Code) — 14.	Reg. — III/6, IMO Res. A.694(17), IMO Res. A.809(19), IMO Res. MSC 36(63)- (1994) HSC Code) — 14, IMO Res. MSC 97(73)- (2000) HSC Code) — 14.	Reg. — IMO Res. — Res. MSC 36(63)- (1994) HSC Code) — 14, IMO Res. MSC 97(73)- (2000) HSC Code) — 14.	EN 60945 B + D B + E (2002) B + F including IEC 60945 Corrigendum 1 (2008), ETSI EN 301 466 V1.1.1 (2000-10). IEC 60945 MSC 97(73)- (2002) including IEC 60945 Corrigendum

			—	ITU-R M.489-2 (10/95).	1 (2008), IEC 61097-12 (1996).
A1/5.19	Inmarsat-F77	—	Reg. IV/14, — Reg. X/3, — IMO Res. MSC 36(63)- (1994 HSC Code) 14, — IMO Res. MSC 97(73)- (2000— HSC Code) 14. — IMO Res. MSC 97(73)- (2000— HSC Code) 14, — IMO Res. MSC/ Circ.862, Comsar Circ.32.	Reg. IV/10, IMO Res. A.570 IMO (14), IMO Res. A.808 (19), IMO Res. IMO Res. A.694 (17), IMO Res. or MSC 36(63)- (1994 HSC Code) 14, — IMO Res. MSC 97(73)- (2000— HSC Code) 14, — IMO Res. MSC/ Circ.862, Comsar Circ.32.	IMO B + D MSC/B + E Circ.862+ F EN 60945 (2002) including IEC Corrigendum 1 (2008), IEC 60945 61097-13 (2003). IMO MSC/ Circ.862, IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61097-13 (2003). IMO

6. Equipment required under Colreg 72

No	Item designation	Regulation Colreg 72 where “type approval” is required	Regulations of Colreg and the relevant resolutions and circulars of the	Testing standards	Modules for conformity assessment
----	------------------	--	---	-------------------	-----------------------------------

Status: This is the original version (as it was originally adopted).

1	2	3	IMO, as applicable		6
			4	5	
A.1/6.1	Navigation lights	— Colreg Annex I/14.	Colreg Annex I/14, IMO Res. A.694(17), IMO Res. MSC.253(83).	EN 14744B + E (2005)B + F including AC (2006), EN 60945 (2002) including IEC 60945 Corrigendum 1 (2008). or — EN 14744 (2005) including AC (2006), IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008).	B + D

7. Bulk carrier safety equipment

No items in Annex A.1.

8. Equipment under SOLAS Chapter II-1. Construction — structure, subdivision and stability, machinery and electrical installations

No	Item designation	Regulation SOLAS 74, as amended, where “type approval” is required	Regulations of SOLAS 74, as amended, and the relevant resolutions and circulars of the	Testing standards	Modules for conformity assessment

1	2	3	IMO, as applicable	5	6
A.1/8.1 Refer to note (b) of this Annex A.1	Water level detectors	— Reg. II-1/22-1, Reg. II-1/25, Reg. XII/12.	Reg. — II-1/25, Reg. XII/12, IMO	IEC 60092-504E (2001) B + F including Res.A.1021(26) IMO Res. MSC.188(79). — IEC 60529 (2001) including: Corrigendum 1 (2003), Corrigendum 2 (2007), Corrigendum 3 (2009), IMO Res. MSC.188(79), IMO MSC.1/ Circ. 1291.	B + D B + F including Res.A.1021(26) Corrigendum 1 (2003), Corrigendum 2 (2007), Corrigendum 3 (2009), IMO Res. MSC.188(79), IMO MSC.1/ Circ. 1291.

ANNEX A.2

EQUIPMENT FOR WHICH NO DETAILED TESTING STANDARDS EXIST IN INTERNATIONAL INSTRUMENTS

1. Life-saving appliances

Column 4: IMO MSC/Circular 980 shall apply except when superseded by the specific instruments referred to in Column 4.

No	Item designation	Regulation SOLAS 74, as amended, where “type approval” is required	Regulations of SOLAS 74, as amended, and the relevant resolutions and circulars of the	Testing standards	Modules for conformity assessment

Status: This is the original version (as it was originally adopted).

device, item A.1/3.53 shall apply)	—	HSC Code), IMO Res. MSC.48(66)-(LSA Code), IMO Res. MSC.97(73)-(2000 HSC Code), IMO MSC/Circ.808.	—	
------------------------------------	---	---	---	--

2. Marine pollution prevention

No	Item designation	Regulation Marpol 73/78, as amended, where “type approval” is required	Regulations of Marpol 73/78, as amended, and the relevant resolutions and circulars of the IMO, applicable	Testing standards	Modules for conformity assessment
1	2	3	4	5	6
A.2/2.1	On board NO _x monitoring and recording devices	Moved to A.1/2.8			
A.2/2.2	On board exhaust gas cleaning systems	Moved to A.1/2.10			
A.2/2.3	Equipment using other equivalent methods to reduce on board NO _x emissions	— Annex VI, Reg. 4.	Annex VI, Reg. 4.		

Status: This is the original version (as it was originally adopted).

A.2/2.4	Equipment using other technological methods to limit SO _x emissions	—	IMO Res. MEPC.176(58) (Revised Marpol Annex VI, Reg. 4), IMO Res. MEPC.184(59).	—	IMO Res. MEPC.176(58) (Revised Marpol Annex VI, Reg. 4).	
A.2/2.5 (new item)	On board NO _x analysers using a measurement method other than the direct measurement and monitoring method of the NO _x Technical Code 2008	—	IMO Res. MEPC.176(58) (Revised Marpol Annex VI, Reg. 4)	—	IMO Res. MEPC.176(58) (Revised Marpol Annex VI, Reg. 4)	

3. Fire protection equipment

No	Item designation	Regulation SOLAS 74, as amended, where “type approval” is required	Regulations of SOLAS 74, as amended, and the relevant resolutions and circulars of the IMO, as applicable	Testing standards	Modules for conformity assessment
1	2	3	4	5	6
A.2/3.1	Non-portable and transportable extinguishers	Moved to A.1/3.52			
A.2/3.2	Nozzles for fixed pressure	Moved to A.1/3.49			

	water-spraying fire-extinguishing systems for special category spaces, ro-ro cargo spaces, ro-ro spaces and vehicle spaces			
A.2/3.3	Cold-weather starting of generator sets (starting devices)	Moved to A.2/8.1		
A.2/3.4	Dual-purpose type nozzles (spray/jet type)	Moved to A.1/3.55		
A.2/3.5	Fixed fire detection and fire alarm systems components for control stations, service spaces, accommodation spaces, machinery spaces and unattended machinery spaces	Moved to A.1/3.51		
A.2/3.6	Smoke detectors	Moved to A.1/3.51		
A.2/3.7	Heat detectors	Moved to A.1/3.51		
A.2/3.8	Electric safety lamp	— Reg. II-2/10, — Reg. X/3, — IMO MSC.98(73)-(FSS Code) — Reg. MSC.36(63)-(1994 HSC Code) 7, 3.	— Reg. II-2/10, — IMO Res. MSC.98(73)-(FSS Code) — Reg. MSC.36(63)-(1994 HSC Code) 7, 3.	IEC 60079 series.

Status: This is the original version (as it was originally adopted).

			—	IMO Res. MSC.97(73)-(2000 HSC Code) 7, IMO Res. MSC.98(73)-(FSS Code), 3.		
A.2/3.9	Protective clothing resistant to chemical attack	—	Reg. II-2/19. II-2/19.	Reg. II-2/19, IMO Res. MSC.36(63)-(1994 HSC Code) 7, IMO Res. MSC.97(73)-(2000 HSC Code) 7.	EN 943-1 (2002) including AC (2005), EN 943-2 (2002), EN ISO 6529 (2001), EN ISO 6530 (2005), EN 14605 (2005) including A1(2009), IMO MSC Circ.1120.	
A.2/3.10	Low-location lighting systems	Moved to A.1/3.40				
A.2/3.11	Nozzles for fixed pressure water spraying fire extinguishing systems for machinery spaces	Moved to A.1/3.10				
A.2/3.12	Equivalent fixed gas fire	Moved to A.1/3.45				

	extinguishing systems for machinery spaces and cargo pump rooms	
A.2/3.13	Compressed airline breathing apparatus (high-speed craft)	Item deleted
A.2/3.14	Fire hoses (reel type)	Moved to A.1/3.56
A.2/3.15	Sample extraction smoke detection systems components	Moved to A.1/3.63
A.2/3.16	Flame detectors	Moved to A.1/3.51
A.2/3.17	Manual call points	Moved to A.1/3.51
A.2/3.18	Alarm devices	Moved to A.1/3.53
A.2/3.19	Fixed water-based local application fire-fighting systems components for use in category "A" machinery spaces	Moved to A.1/3.48
A.2/3.20	Upholstered furniture	Moved to A.1/3.20
A.2/3.21	Paint lockers and flammable liquid lockers fire extinguishing systems components	— Reg. II-2/10.— Reg. II-2/10, IMO MSC.1/ Circ.1239.

Status: This is the original version (as it was originally adopted).

A.2/3.22	Galley exhaust duct fixed fire extinguishing systems components	—	Reg. II-2/9.	—	Reg. II-2/9.		
A.2/3.23	Helicopter deck fire extinguishing systems components	—	Reg. II-2/18.	—	Reg. II-2/18.	EN 13565-1 (2003) including A1 (2007).	
A.2/3.24	Portable foam applicator units	—	Reg. II-2/10,	—	Reg. II-2/10,		
		—	Reg. II-2/20,	—	Reg. II-2/20,		
		—	Reg. X/3.	—	IMO Res. MSC.36(63)-(1994 HSC Code) 7, IMO Res. MSC.97(73)-(2000 HSC Code) 7, IMO Res. MSC.98(73)-(FSS Code) 4, IMO MSC.1/Circ.1239, IMO MSC.1/Circ.1313.		
A.2/3.25	“C” class divisions	Moved to A.1/3.64					
A.2/3.26	Gaseous fuel systems used for domestic purposes (components)	—	Reg. II-2/4.	—	Reg. II-2/4, IMO MSC.1/Circ.1276.		

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

A.2/3.27	Fixed gas fire extinguishing systems (CO ₂) components	—	Reg. II-2/10, Reg. X/3.	—	Reg. II-2/10, Reg. II-2/20, IMO Res. MSC.36(63)- (1994 HSC Code) 7, IMO Res. MSC.97(73)- (2000 HSC Code) 7, IMO Res. MSC.98(73)- (FSS Code) 5, IMO MSC.1/ Circ.1313, IMO MSC.1/ Circ.1318.	Electrical automatic control and delay devices: EN 12094-1 (2003). Non-electrical automatic control and delay devices: EN 12094-2 (2003). Manual triggering and stop devices: EN 12094-3 (2003). Container valve assemblies and their actuators: EN 12094-4 (2004). High and low pressure selector valves and their actuators: EN 12094-5 (2006). Non-electrical disable devices:
----------	--	---	----------------------------	---	---	---

Status: This is the original version (as it was originally adopted).

			— EN 12094-6 (2006). Nozzles for CO ₂ systems: — EN 12094-7 (2000) including A1 (2005). Connectors: — EN 12094-8 (2006). Pressure gauges and pressure switches: — EN 12094-10 (2003). Mechanical weighing devices: — EN 12094-11 (2003). Check valves and non- return valves: — EN 12094-13 (2001) including AC (2002). Odourising devices for CO ₂ low pressure systems:
--	--	--	--

				—	EN 12094-16 (2003).
A.2/3.28	Medium expansion foam fire extinguishing systems components — Fixed deck foam for tankers	Moved to A.1/3.57			
A.2/3.29	Fixed low expansion foam fire extinguishing systems components for machinery spaces and tanker deck protection	Moved to A.1/3.58			
A.2/3.30	Expansion foam for fixed fire extinguishing systems for chemical tankers	Moved to A.1/3.59			
A.2/3.31	Water spraying hand-operated system	—	Reg. II-2/10.	—	Reg. II-2/10.
A.2/3.32	Dry chemical powder extinguishing systems	Moved to A.1/3.62			

4. Navigation equipment

Notes applicable to Section 4: Navigation equipment

Columns 3 and 4: References to SOLAS Chapter V are to SOLAS 1974 as amended by MSC 73 and entering into force on 1 July 2002.

Column 5:

IEC 61162 series refer to the following reference standards for Maritime navigation and radiocommunication equipment and systems — Digital interfaces:

Status: This is the original version (as it was originally adopted).

- (a) IEC 61162-1 ed4.0 (2010-11) — Part 1: Single talker and multiple listeners
- (b) IEC 61162-2 ed1.0 (1998-09) — Part 2: Single talker and multiple listeners, high-speed transmission
- (c) IEC 61162-3 ed1.1 Consol. with am1 (2010-11) — Part 3: Serial data instrument network
 - IEC 61162-3 ed1.0 (2008-05) — Part 3: Serial data instrument network
 - IEC 61162-3-am1 ed1.0 (2010-06) Amendment 1 — Part 3: Serial data instrument network
- (d) IEC 61162-400 ed1.0 (2001-11) — Part 400: Multiple talkers and multiple listeners — Ship systems interconnection — Introduction and general principles
 - IEC 61162-401 ed1.0 (2001-11) — Part 401: Multiple talkers and multiple listeners — Ship systems interconnection — Application profile
 - IEC 61162-402 ed1.0 (2005-09) — Part 402: Multiple talkers and multiple listeners — Ship systems interconnection — Documentation and test requirements
 - IEC 61162-410 ed1.0 (2001-11) — Part 410: Multiple talkers and multiple listeners — Ship systems interconnection — Transport profile requirements and basic transport profile
 - IEC 61162-420 ed1.0 (2001-11) — Part 420: Multiple talkers and multiple listeners — Ship systems interconnection — Companion standard requirements and basic companion standards
 - IEC 61162-450 ed1.0 (2011-06) — Part 450: Multiple talkers and multiple listeners — Ethernet interconnection

EN 61162 series refer to the following reference standards for Maritime navigation and radiocommunication equipment and systems — Digital interfaces:

- (a) EN 61162-1 (2011) — Part 1: Single talker and multiple listeners
- (b) EN 61162-2 (1998) — Part 2: Single talker and multiple listeners, high-speed transmission
- (c) EN 61162-3 (2008) — Part 3: Serial data instrument network
 - EN 61162-3-am1 (2010) Amendment 1 — Part 3: Serial data instrument network
- (d) EN 61162-400 (2002) — Part 400: Multiple talkers and multiple listeners — Ship systems interconnection — Introduction and general principles
 - EN 61162-401 (2002) — Part 401: Multiple talkers and multiple listeners — Ship systems interconnection — Application profile
 - EN 61162-402 (2005) — Part 402: Multiple talkers and multiple listeners — Ship systems interconnection — Documentation and test requirements
 - EN 61162-410 (2002) — Part 410: Multiple talkers and multiple listeners — Ship systems interconnection — Transport profile requirements and basic transport profile

- EN 61162-420 (2002) — Part 420: Multiple talkers and multiple listeners — Ship systems interconnection — Companion standard requirements and basic companion standards
- EN 61162-450 (2011) — Part 450: Multiple talkers and multiple listeners — Ethernet interconnection

No	Item designation	Regulation SOLAS 74, as amended, where “type approval” is required	Regulations of SOLAS 74, as amended, and the relevant resolutions and circulars of the IMO, as applicable	Testing standards	Modules for conformity assessment
1	2	3	4	5	6
A.2/4.1	Gyro compass for high-speed craft	Moved to A.1/4.31			
A.2/4.2	Heading control system for high-speed craft (formerly auto-pilot)	Moved to A.1/4.40			
A.2/4.3	Transmitting heading device THD (GNSS method)	Moved to A.1/4.41			
A.2/4.4	Daylight signalling lamp	Moved to A.1/4.52			
A.2/4.5	Searchlight for high-speed craft	Moved to A.1/4.42			
A.2/4.6	Night vision equipment for high-speed craft	Moved to A.1/4.43			
A.2/4.7	Track control system	Moved to A.1/4.33			

A.2/4.8	Electronic chart display and information system (ECDIS).	Moved to A.1/4.30					
A.2/4.9	Electronic chart display and information system (ECDIS) backup	Moved to A.1/4.30					
A.2/4.10	Raster chart display system (RCDS)	Moved to A.1/4.30					
A.2/4.11	Combined GPS/GLONASS equipment	—	Reg. V/18,	—	Reg. V/19,	—	EN 60945
		—	Reg. —	—	IMO	(2002)	
		—	X/3,	Res.		including	
		—	IMO	A.694(17),		IEC	
		Res.	—	IMO		60945	
		—	MSC 36(63)-	Res.		Corrigendum	
		(1994)	MSC 36(63)-	1			
		HSC	(1994)			(2008),	
		Code),	HSC	—		EN	
		—	IMO	Code),		61108-1	
		Res.	—	IMO		(2003),	
		—	MSC 97(73)-	Res.		EN	
		(2000)	MSC 97(73)-	—		61108-2	
		HSC	(2000)			(1998),	
		Code).	HSC	—		EN	
			Code),			61162	
			IMO			series,	
			Res.	—		EN	
			MSC 115(73),			62288	
			IMO			(2008).	
			Res. or				
			MSC 191(79).			IEC	
						60945	
						(2002)	
						including	
						IEC	
						60945	
						Corrigendum	
						1	
						(2008),	
						IEC	
						61108-1	
						(2003),	

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

					—	IEC 61108-2 (1998), IEC 61162 series, IEC 62288 Ed.1.0(2008).	
A.2/4.12	DGPS, DGLONASS equipment	Moved to A.1/4.44, A.1/4.50 and A.1/4.51					
A.2/4.13	Gyro compass for high-speed craft	Moved to A.1/4.31					
A.2/4.14	Voyage data recorder (VDR)	Moved to A.1/4.29					
A.2/4.15	Integrated navigation system	—	Reg. V/18,	—	Reg. V/19,	—	EN 60945
		—	Reg. X/3,	—	IMO	(2002)	including
		—	IMO	Res.	A.694(17),	IEC	
		—	Res.	—	IMO	60945	
		—	MSC	36(63)-	Res.	Corrigendum	
			(1994	(1994	MSC	1	
			HSC	Code)	(1994	(2008),	
			13,	HSC	Code)	EN	
		—	IMO	13,	—	61162	
			Res.	IMO	—	series,	
			MSC	97(73)-	Res.	61924	
			(2000	(2000	MSC	86(70),	(2006),
			HSC	Code)	IMO	—	EN
			13.	Res.	Res.	62288	
			MSC	97(73)-	MSC	97(73)-	(2008).
			(2000	(2000	(2000	or	
			or	or	HSC	—	
					Code)	IEC	
					13,	60945	
					IMO	(2002)	
					Res.	including	
					MSC	IEC	
					191(79).	60945	
						Corrigendum	
						1	
						(2008),	
						IEC	
						61162	
						series,	

Status: This is the original version (as it was originally adopted).

						IEC 61924 (2006), IEC 62288 Ed.1.0(2008).
A.2/4.16	Bridge equipment system	Deliberately left blank				
A.2/4.17	Radar target enhancer	Moved to A.1/4.53				
A.2/4.18	Sound reception system	— Reg. V/18, — Reg. X/3, — IMO Res. MSC 36(63)- (1994) HSC Code), IMO Res. MSC 97(73)- (2000) HSC Code). — Reg. V/19, — IMO Res. MSC 36(63)- (1994) HSC Code), IMO Res. MSC 97(73)- (2000) HSC Code), IMO Res. MSC 191(79). — Reg. — IMO Res. A.382(X), — IMO Res. MSC 36(63)- (1994) HSC Code), — Reg. — IMO Res. MSC 36(63)-	— IMO Res. MSC 36(63)- (1994) HSC Code), IMO Res. MSC 86(70), — IMO Res. MSC 97(73)- (2000) HSC Code), IMO Res. MSC 191(79). — IMO Res. A.694(17), — IMO Res. MSC 36(63)-	— including IEC Corrigendum 1 EN 60945 (2002) including IEC Corrigendum 1 EN 60945 (2008), EN 61162 series, EN 60945 (2002) including IEC Corrigendum 1 EN 60945 (2008), EN 61162 series, EN 62288 Ed.1.0(2008).	EN 60945 (2002) including IEC Corrigendum 1 EN 60945 (2008), EN 61162 series, EN 62288 Ed.1.0(2008).	
A.2/4.19	Magnetic compass for high-speed craft	— Reg. X/3, — IMO Res. MSC 36(63)- (1994) HSC Code), — Reg. Res. A.382(X), — IMO Res. MSC 36(63)- (1994) HSC Code), — Reg. Res. A.694(17), — IMO Res. MSC 36(63)-	IMO Res. A.382(X), — IMO Res. MSC 36(63)- (1994) HSC Code), — Reg. Res. A.694(17), — IMO Res. MSC 36(63)-	ISO 1069 (1973), ISO 25862(2009), EN 60945 (2002) including IEC Corrigendum 1 EN 60945 (2008), EN 61162 series, EN 62288 Ed.1.0(2008).	ISO 1069 (1973), ISO 25862(2009), EN 60945 (2002) including IEC Corrigendum 1 EN 60945 (2008), EN 61162 series, EN 62288 Ed.1.0(2008).	

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

		—	IMO Res. MSC 97(73)- (2000) HSC Code).	(1994 HSC Code), IMO Res. MSC 97(73)- (2000) HSC Code).	IEC 60945 Corrigendum 1 (2008). ISO 1069 (1973), ISO 25862(2009), IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008).
A.2/4.20	Track control system for high-speed craft	—	Reg. X/3, IMO Res. MSC 36(63)- (1994) HSC Code), IMO Res. MSC 97(73)- (2000) HSC Code).	IMO — Res. A.694(17), IMO Res. MSC 36(63)- (1994) HSC Code), IMO Res. MSC 97(73)- (2000) HSC Code).	EN 60945 (2002) including IEC 60945 Corrigendum 1 (2008), EN 61162 series, EN 62288 (2008). IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61162 series, IEC 62288 Ed.1.0(2008).

Status: This is the original version (as it was originally adopted).

A.2/4.21	Chart facilities for shipborne radar	Moved to A.1/4.45					
A.2/4.22	Transmitting heading device THD (gyroscopic method)	Moved to A.1/4.46					
A.2/4.23	Transmitting heading device THD (magnetic method)	Moved to A.1/4.2					
A.2/4.24	Thrust indicator	—	Reg. V/18,	—	Reg. V/19,	—	EN 60945
		—	Reg. —	—	IMO	(2002)	
		—	X/3,	—	Res.	including	
		—	IMO	—	A.694(17),	IEC	
		—	Res. —	—	IMO	60945	
		—	MSC 36(63)-	—	Res.	Corrigendum	
		—	(1994	—	MSC 36(63)-	1	
		—	HSC	—	(1994	(2008),	
		—	Code),	—	HSC	EN	
		—	IMO	—	Code),	61162	
		—	Res. —	—	IMO	series,	
		—	MSC 97(73)-	—	Res. —	EN	
		—	(2000	—	MSC 97(73)-	62288	
		—	HSC	—	(2000	(2008).	
		—	Code).	—	HSC or		
		—		—	Code),	IEC	
		—		—	IMO	60945	
		—		—	Res.	(2002)	
		—		—	MSC 191(79).	including	
		—		—		IEC	
		—		—		60945	
		—		—		Corrigendum	
		—		—	—	1	
		—		—	—	(2008),	
		—		—	—	IEC	
		—		—	—	61162	
		—		—	—	series,	
		—		—	—	IEC	
		—		—	—	62288	
		—		—	—	Ed.1.0(2008).	
A.2/4.25	Lateral thrust, pitch and mode indicators	—	Reg. V/18,	—	Reg. V/19,	—	EN 60945
		—	Reg. —	—	IMO	(2002)	
		—	X/3,	—	Res.	including	
		—		—	A.694(17),	IEC	

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

		—	IMO	—	IMO	—	60945	
		Res.	Res.	Res.	Res.	—	Corrigendum	
		MSC.36(63)-	MSC.36(63)-	MSC.36(63)-	MSC.36(63)-	1		
		(1994)	(1994)	(1994)	(1994)	(2008),		
		HSC	HSC	HSC	HSC	EN		
		Code),	Code),	Code),	Code),	61162		
		IMO	IMO	IMO	IMO	series,		
		Res.	Res.	Res.	Res.	EN		
		MSC.97(73)-	MSC.97(73)-	MSC.97(73)-	MSC.97(73)-	62288		
		(2000)	(2000)	(2000)	(2000)	(2008).		
		HSC	HSC	HSC	HSC or			
		Code).	Code).	Code).	Code),—	IEC		
		—	IMO	IMO	IMO	60945		
			Res.	Res.	Res.	(2002)		
			MSC.191(79).	MSC.191(79).	MSC.191(79).	including		
						IEC		
						60945		
						Corrigendum		
						1		
						(2008),		
						IEC		
						61162		
						series,		
						IEC		
						62288		
						Ed.1.0(2008).		
A.2/4.26	Rate-of-turn indicator	Moved to A.1/4.9						
A.2/4.27	Rudder angle indicator	Moved to A.1/4.20						
A.2/4.28	Propeller revolution indicator	Moved to A.1/4.21						
A.2/4.29	Pitch indicator	Moved to A.1/4.22						
A.2/4.30	Bridge equipment system	—	Reg. V/18,	—	Reg. V/19,	—	EN	
		—	Reg.	—	IMO	(2002)	60945	
		—	X/3,	—	Res.	including		
		—	IMO	—	A.694	IEC		
			Res.	(17),	—	60945		
			MSC.36(63)-	IMO	—	Corrigendum		
			(1994)	Res.	1			
			HSC	MSC.36(63)-	(2008),			
			Code)	(1994—	EN			
			13,	HSC	61162			
			IMO	Code)	series,			
			Res.	15,	EN			
			MSC.97(73)-	IMO	61209			
			(2000)	Res.	(1999),			

Status: This is the original version (as it was originally adopted).

		HSC Code) 13.	MSC (2000 HSC Code) or 15, —	97(73)- (2008). IEC 60945 (2002)	EN 62288 (2008).	
			IMO Res. —	191(79), including IMO SN.1/ Circ.288.	IEC 60945 Corrigendum 1 (2008), IEC 61162 series, IEC 61209 (1999), IEC 62288 Ed.1.0(2008).	
A.2/4.31	Bearing device	Moved to A.1/4.54				
A.2/4.32	Bridge navigational watch alarm system (BNWAS)	Moved to A.1/4.57				
A.2/4.33	Track control system (working at ship's speed from 30 knots and above)	— Reg. V/18, — Reg. X/3.	Reg. V/19, IMO Res. A.694 (17), IMO Res. MSC (1994— HSC Code), IMO Res. MSC (2000 or HSC Code), IMO Res. MSC	— including IEC 60945 Corrigendum 1 36(63)- (2008), EN 61162 series, EN 62288 97(73)- (2008). IEC 60945 (2002) including IEC 60945	EN 60945 (2002) IEC 60945 Corrigendum 1 (2008), EN 61162 series, EN 62288 97(73)- (2008). IEC 60945 (2002) including IEC 60945	

					Corrigendum 1 (2008), IEC 61162 series, IEC 62288 Ed.1.0(2008).
A.2/4.34	Equipment with long range identification and tracking (LRIT) capability	—	Reg. V/19	— Reg. V/19, — IMO Res. A.694(17), — IMO Res. A.813(19), — IMO Res. — MSC 202(81), — IMO Res. or MSC 241(81), — IMO Res. (2002) MSC 263(84), — IMO MSC 1/ Circ 1307.	EN 60945 (2002) including IEC 60945 Corrigendum 1 (2008), EN 61162 series. IEC 60945 including IEC 60945 (2002) Corrigendum 1 (2008), IEC 61162 series.
A.2/4.35	Galileo receiver	Moved to A.1/4.56			
A.2/4.36	AIS SART equipment	Moved to A.1/4.55			

5. Radiocommunication equipment

Notes applicable to Section 5: Radiocommunication equipment.

Column 5:

IEC 61162 series refer to the following reference standards for Maritime navigation and radiocommunication equipment and systems — Digital interfaces:

- (a) IEC 61162-1 ed4.0 (2010-11) — Part 1: Single talker and multiple listeners
 - (b) IEC 61162-2 ed1.0 (1998-09) — Part 2: Single talker and multiple listeners, high-speed transmission

- (c) IEC 61162-3 ed1.1 Consol. with am1 (2010-11) — Part 3: Serial data instrument network
 - IEC 61162-3 ed1.0 (2008-05) — Part 3: Serial data instrument network
 - IEC 61162-3-am1 ed1.0 (2010-06) Amendment 1 — Part 3: Serial data instrument network
- (d) IEC 61162-400 ed1.0 (2001-11) — Part 400: Multiple talkers and multiple listeners — Ship systems interconnection — Introduction and general principles
 - IEC 61162-401 ed1.0 (2001-11) — Part 401: Multiple talkers and multiple listeners — Ship systems interconnection — Application profile
 - IEC 61162-402 ed1.0 (2005-09) — Part 402: Multiple talkers and multiple listeners — Ship systems interconnection — Documentation and test requirements
 - IEC 61162-410 ed1.0 (2001-11) — Part 410: Multiple talkers and multiple listeners — Ship systems interconnection — Transport profile requirements and basic transport profile
 - IEC 61162-420 ed1.0 (2001-11) — Part 420: Multiple talkers and multiple listeners — Ship systems interconnection — Companion standard requirements and basic companion standards
 - IEC 61162-450 ed1.0 (2011-06) — Part 450: Multiple talkers and multiple listeners — Ethernet interconnection

EN 61162 series refer to the following reference standards for Maritime navigation and radiocommunication equipment and systems — Digital interfaces:

- (a) EN 61162-1 (2011) — Part 1: Single talker and multiple listeners
- (b) EN 61162-2 (1998) — Part 2: Single talker and multiple listeners, high-speed transmission
- (c) EN 61162-3 (2008) — Part 3: Serial data instrument network
 - EN 61162-3-am1 (2010) Amendment 1 — Part 3: Serial data instrument network
- (d) EN 61162-400 (2002) — Part 400: Multiple talkers and multiple listeners — Ship systems interconnection — Introduction and general principles
 - EN 61162-401 (2002) — Part 401: Multiple talkers and multiple listeners — Ship systems interconnection — Application profile
 - EN 61162-402 (2005) — Part 402: Multiple talkers and multiple listeners — Ship systems interconnection — Documentation and test requirements
 - EN 61162-410 (2002) — Part 410: Multiple talkers and multiple listeners — Ship systems interconnection — Transport profile requirements and basic transport profile
 - EN 61162-420 (2002) — Part 420: Multiple talkers and multiple listeners — Ship systems interconnection — Companion standard requirements and basic companion standards
 - EN 61162-450 (2011) — Part 450: Multiple talkers and multiple listeners — Ethernet interconnection

Status: This is the original version (as it was originally adopted).

		HSC Code), IMO Res. MSC (2000 HSC Code). —	(1994 HSC Code) or IMO — Res. MSC (2000 HSC Code), — IMO Comsar Circ.16, IMO Comsar Circ.32.	1 (2008). IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008).
A.2/5.3	Inmarsat-F SES	Moved to A.1/5.19.		
A.2/5.4	Distress panel	<p>— Reg. IV/14, — Reg. IV/6, — EN 60945</p> <p>— Reg. X/3, — IMO Res. including A.694(17), IEC 60945</p> <p>— IMO — Res. MSC.36(63)- (1994) — Corrigendum 1</p> <p>— Res. — IMO MSC.36(63)- (1994) (2008). HSC (1994)</p> <p>— Code), — HSC or — IEC 60945</p> <p>— IMO — Code), — Res. MSC.97(73)- (2002) 1</p> <p>— Res. — IMO MSC.97(73)- (2000) including IEC 60945</p> <p>— MSC.97(73)- (2000) — HSC (2000) 60945</p> <p>— HSC — Code), — Corrigendum 1</p> <p>— IMO — MSC/ Circ. 862, — (2008). Comsar</p> <p>— — Circ.32.</p>		
A.2/5.5	Distress alarm or alert panel	<p>— Reg. IV/14, — Reg. IV/6, — EN 60945</p> <p>— Reg. X/3, — IMO (2002) Res. A.694(17), including</p> <p>— IMO — IMO IEC 60945</p> <p>— Res. — Res. MSC.36(63)- (1994) — Corrigendum 1</p> <p>— MSC.36(63)- (1994) — HSC (2008). HSC Code), — Code) or</p>		

ANNEX

Document Generated: 2023-08-19

Status: This is the original version (as it was originally adopted).

		—	IMO Res. MSC 97(73)- (2000) HSC Code).	—	IMO Res. MSC 97(73)- (2000) HSC Code), — IMO MSC/ Circ.862, — IMO Comsar Circ.32.	IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008).
A.2/5.6	L-band EPIRB (Inmarsat)			Deliberately left blank		
A.2/5.7	Ship security alert system			— Reg. XI-2/6, — IMO Res. A.694(17), — IMO Res. MSC 147(77), — IMO MSC/ Circ.1072.	EN 60945 (2002) including IEC 60945 Corrigendum 1 (2008), EN 61162 series. or — IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), IEC 61162 series.	
A.2/5.8 Ex A.1/5.16	Aeronautical two-way VHF radio telephone apparatus	—	Reg. IV/14, — Reg. X/3, — IMO Res. MSC 36(63)- (1994) HSC Code) 14,	Reg. IV/7, IMO Res. A.694(17), IMO Res. MSC 36(63)- (1994) HSC HSC	EN 60945 (2002) including IEC 60945 Corrigendum 1 (2008), ETSI EN	

Status: This is the original version (as it was originally adopted).

—	IMO Res. 97(73)- (2000) HSC Code) 14.	Code) 14, IMO Res. 97(73)- (2000) — HSC Code) (2000) 14, —	Code) 14, IMO Res. MSC.80(70), IMO Comsar Circ.32, ICAO Convention, Annex 10, Radio —	301 688 V1.1.1 (2000-07). IEC 60945 (2002) including IEC 60945 Corrigendum 1 ETSI EN 301 688 V1.1.1 (2000-07).	Regulations.

6. Equipment required under Colreg 72

No	Item designation	Regulation Colreg 72 where “type approval” is required	Regulations of Colreg and the relevant resolutions and circulars of the IMO, as applicable	Testing standards	Modules for conformity assessment
1	2	3	4	5	6
A.2/6.1	Navigation lights	Moved to A.1/6.1.			
A.2/6.2	Sound signal appliances	— Colreg 72 Annex III/3.	Colreg 72 Annex III/3, IMO Res. A.694(17).	EN 60945 (2002) including IEC 60945 Corrigendum 1 (2008), Whistles — Colreg 72 Annex	

				— III/1 (performance), Bells or gongs — Colreg 72 Annex III/2 (performance). or — IEC 60945 (2002) including IEC 60945 Corrigendum 1 (2008), Whistles — Colreg 72 Annex III/1 (performance), Bells or gongs — Colreg 72 Annex III/2 (performance).	
--	--	--	--	---	--

7. Bulk carrier safety equipment

No	Item designation	Regulation SOLAS 74, as amended, where “type approval” is required	Regulations of SOLAS 74, as amended, and the relevant resolutions and circulars of the IMO, as applicable	Testing standards	Modules for conformity assessment
1	2	3	4	5	6

Status: This is the original version (as it was originally adopted).

A.2/7.1	Loading instrument	—	Reg. XII/11, 1997	—	Reg. XII/11, 1997	IMO MSC Circ 1/1229	
A.2/7.2	Water level detectors on bulk carriers	Item deleted					

8. SOLAS Chapter II-1 equipment

No	Item designation	Regulation SOLAS 74, as amended, where “type approval” is required	Regulations of SOLAS 74, as amended, and the relevant resolutions and circulars of the IMO, as applicable	Testing standards	Modules for conformity assessment
1	2	3	4	5	6
A.2/8.1	Cold-weather starting of generator sets (starting devices)	— Reg. II-1/44, — Reg. X/3.	Reg. II-1/44, IMO Res. MSC.36(63)-(1994 HSC Code) — 12, IMO Res. MSC.97(73)-(2000 HSC Code) 12.		

(1) [OJ L 46, 17.2.1997, p. 25.](#)

(2) [OJ L 305, 20.11.2010, p. 1.](#)

(3) [OJ L 239, 15.9.2011, p. 1.](#)