

SCHEDULE 3

HAZARD WARNING PANELS AND LABELS

Information to be shown on labels

10. The following information shall be shown on each label—
 - (a) if the substance is listed in Column 1 of Part I of the approved list—
 - (i) in space (1), the substance identification number for that substance and (if desired) the name of the substance given in the said Column 1 or its trade name, and
 - (ii) in space (2), the sign shown in Column 3 of Part I of Schedule 1 which adjoins such description set out in Column 2 of that Part as corresponds with the classification of the substance (the sign to comply with the specifications contained in Part III of Schedule 1); except that, until 1st January 1993, in the case of a dangerous substance whose classification is “other dangerous substance”, the sign shown in Part II of Schedule 1 may be used (the sign to comply with the specifications contained in Part IV of Schedule 1);
 - (b) if the substance is not listed in Column 1 of Part I of the approved list—
 - (i) in space (1), an internationally-recognised chemical name for it, its accepted common name or its trade name; and the words “hot liquid” where the substance is being carried at a temperature in excess of 100°C, and the words “above FP” where the substance is being carried above its flash point, and
 - (ii) in space (2), the sign shown in Column 3 of Part I of Schedule 1 which adjoins the classification of the substance (the sign to comply with the specifications contained in Part III of Schedule 1); except that, until 1st January 1993, in the case of a dangerous substance whose classification is “other dangerous substance”, the sign shown in Part II of Schedule 1 may be used (the sign to comply with the specifications contained in Part IV of Schedule 1); and
 - (c) where all the substances being carried bear the same classification, space (2) (if included in the label) may be left blank.