SCHEDULE 1

Rendering requirements

Part II

Methods of rendering

Method 6

Added fat continuous atmospheric

Separation and storage of final products

4. On discharge from the vessel, any surplus tallow not required to maintain the vessel's operating level shall be removed, and the material separated into its tallow and protein components. Protein and tallow shall be stored separately.