STATUTORY RULES OF NORTHERN IRELAND

2000 No. 375

Ionising Radiations Regulations (Northern Ireland) 2000

Part I

Interpretation and General

Duties under the Regulations

- **4.**—(1) Any duty imposed by these Regulations on an employer in respect of the exposure to ionising radiation of persons other than his employees shall be imposed only in so far as the exposure of those persons to ionising radiation arises from work with ionising radiation undertaken by that employer.
- (2) Duties under these Regulations imposed upon the employer shall also be imposed upon the manager of a mine (within the meaning of section 156 of the Mines Act (Northern Ireland) 1969(1) in so far as those duties relate to the mine of which he is the manager and to matters under his control.
- (3) Duties under these Regulations imposed upon the employer shall also be imposed upon the owner, occupier or agent of a quarry (within the meaning of Article 2 of the Quarries (Northern Ireland) Order 1983(2) in so far as those duties relate to the quarry or part of the quarry of which he is the owner, occupier or agent and to matters under his control.
- (4) Subject to regulation 6(1)(b), duties under these Regulations imposed upon the employer shall also be imposed on the holder of a nuclear site licence under the Nuclear Installations Act 1965 in so far as those duties relate to the licensed site.

⁽²⁾ S.I. 1983/150 (N.I. 4)