## STATUTORY RULES OF NORTHERN IRELAND

## 2003 No. 33

## Control of Asbestos at Work Regulations (Northern Ireland) 2003

## Plans of work

- 7.—(1) An employer shall not undertake any work with asbestos unless he has prepared a suitable written plan of work (hereinafter referred to in this regulation as "the plan of work") detailing how that work is to be carried out.
  - (2) The employer shall keep a copy of the plan of work-
    - (a) at those premises at which; and
    - (b) for such time as,

the work to which the plan relates is being carried out.

- (3) The plan of work shall include in particular details of-
  - (a) the nature and probable duration of the work;
  - (b) the location of the place where the work is to be carried out;
  - (c) the methods to be applied where the work involves the handling of asbestos or materials containing asbestos;
  - (d) the characteristics of the equipment to be used for-
    - (i) protection and decontamination of those carrying out the work,
    - (ii) protection of other persons on or near the worksite; and
  - (e) the measures which the employer intends to take in order to comply with the requirements of regulation 10.
- (4) The employer shall ensure, so far as is reasonably practicable, that the work to which the plan of work relates is carried out in accordance with that plan.