

## SCHEDULE 6

### **(Annex VI to the high-speed Directive) SUBSYSTEMS**

#### **EC verification**

**5.2** The notified body responsible for checking production must have permanent access to building sites, production workshops, storage areas and, where appropriate, prefabrication or testing facilities and, more generally, to all premises which it considers necessary for its task. The contracting entity or its authorised representative within the Community must send it or have sent to it all the documents needed for that purpose and in particular the implementation plans and technical records concerning the subsystem.