
STATUTORY RULES OF NORTHERN IRELAND

1993 No. 37

**Workplace (Health, Safety and Welfare)
Regulations (Northern Ireland) 1993**

Cleanliness and waste materials

9. —

(1) Every workplace and the furniture, furnishings and fittings therein shall be kept sufficiently clean.

(2) The surfaces of the floors, walls and ceilings of all workplaces inside buildings shall be capable of being kept sufficiently clean.

(3) So far as reasonably practicable, waste materials shall not be allowed to accumulate in a workplace except in suitable receptacles.