SCHEDULE 2

SOLVENT EMISSIONS

PART 2

SEPA functions

- **8.** SEPA may permit emissions to exceed a fugitive emission limit required under subparagraph (a) of Article 59(1) of the Industrial Emissions Directive, provided that—
 - (a) it is not technically and economically feasible to comply with that sub-paragraph,
 - (b) SEPA ensures that the operator of the installation uses the best available techniques in respect of those emissions, and
 - (c) SEPA is satisfied that there are no significant risks to human health and the environment.