

SCHEDULE 8

MARKING OF PROJECTIONS

PART 4

GENERAL VISIBILITY OF MARKERS

9. Any end marker or side marker which is required by any provision of this Schedule to be fitted to a projection of a load must be kept clean and unobscured.