

SCHEDULE 1

Types of accidents and incidents other than any occurring within the Channel Tunnel System which must be notified to the Rail Accident Investigation Branch immediately and by the quickest means available

5. A collision of rolling stock with an arrestor mechanism or buffer stop, other than in a siding, that causes damage to the rolling stock.