SCHEDULE 1

PART 1

ESSENTIAL REQUIREMENTS

Accuracy

13. The manufacturer shall specify the class index of the relevant instrument. The class indices are $A,\,B$ and C.