

SCHEDULE 4

Sampling and analysis

PART 3

Monitoring for indicative dose and analytical performance characteristics

Screening strategies for gross alpha activity and gross beta activity

- 10.** Subject to paragraph 11 the recommended screening levels are—
 - (a) 0,1Bq/l for gross alpha activity; and
 - (b) 1,0Bq/l for gross beta activity.